



Mercedes B:				
Vinnumber:	W1K2470861J331474	Versionname:		
First Registrationdate:	4/10/2021	Fiscalpower:		
Expertise Mileage:	80957	Power Kw:		
Bodytype:		Body colour	Blue	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	1711	
Fueltype:	Hybrid Petrol			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Seats electric F L		
Cruise Control		Seats electric F R		
Steering wheel multifunctional		Sun Roof electric		
Seats F heated		Panoramic roof		
Radio multimedia		Luggage cover		
Type of headlighting	Headlighting LED	Front parking sensors		
Type of GPS	GPS big screen color	Rear parking sensors		
Type of Lining	Lining semi-artificial leather	Type of Tow bar	No Tow bar	
Type of climate control	Autom climate control			
Limited Technical Inspection				
Tyres				
Winter tyres:	205/55/17/95 V			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 17 95 V
Tyre size FR				205/55 R 17 95 V
Tyre size RL				205/55 R 17 95 V
Tyre size RR				205/55 R 17 95 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				2480
Tyre make RR				2480
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Number of charging cables (normal)	1			
Number of charging cables (rapid charge)	1			
Total cost ex VAT				3977,86
Bonnet, Chemical polution, Repair and paint (complete)				406,19



Bumper F, Scratch(es), Spot repair

148,33



Wing RL, Scratch(es), Repair and paint (complete)

431,58



Mirror side repeater L, Crack, Replace

39,08



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)

296,58



Bumper moulding R, Crack, Replace

70,17



Tailgate / Boot, Dent(s), Paintless dent repair

95,47




Wing FR, Bad repair, Check

0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

204,21




Door FR, Dent(s) and scratch(es), Repair and paint (complete)

535,06



Door RR, Dent(s) and scratch(es), Replace and paint

1751,19



Wing RR, Scratch(es), Acceptable

0,00

