



Renault Clio:

Vinnumber:	VF1RJA00668577747	Versionname:	
First Registrationdate:	3/02/2022	Fiscalpower:	
Expertise Mileage:	121946	Power Kw:	67
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:		Parking lot:	1706
Fueltype:	Petrol		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		

Limited Technical Inspection

Tyres

195/55/16/87 H				
Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL:				5.0
Tyre profile depth FR:				5.0
Tyre profile depth RL:				5.0
Tyre profile depth RR:				5.0
Tyre size FL:				195/55 R 16 87 H
Tyre size FR:				195/55 R 16 87 H
Tyre size RL:				195/55 R 16 87 H
Tyre size RR:				195/55 R 16 87 H
Tyre type FL:				All seasons
Tyre type FR:				All Seasons
Tyre type RL:				All seasons
Tyre type RR:				All Seasons
Tyre make FL:				2480
Tyre make FR:				2480
Tyre make RL:				2480
Tyre make RR:				2480

Assistance equipment

Emergency spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	457,20
Interior, Damaged, Acceptable:	0,00



Engine insulation, Damaged, Replace 50,00



Bumper F, Scratch(es), Acceptable 0,00



Grille, Dent(s), Acceptable 0,00



Wheel cover RL, Scratch(es), Acceptable 0,00



Wing RL, Scratch(es), Acceptable 0,00



Internal boot lining L, Broken, Smart repair 116,69



Boot lid covering R, Broken, Forfeit 2,50



Bumper R, Scratch(es), Repair and paint (complete) 237,26



Boot moulding, Scratch(es), Acceptable 0,00



Wheel cover RR, Scratch(es), Replace

25,25



Wheel cover FR, Scratch(es), Replace

25,50

