



Land Rover Discovery Sport (KKL): 2CHX176

Vinnumber:	SALCA2BT9PH922042	Versionname:	Discovery Sport S P300e 1.5i 309pk/cv 5p AWD Aut.
First Registrationdate:	4/08/2022	Fiscalpower:	
Expertise Mileage:	115257	Power Kw:	147
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Hybrid Petrol		
Maintenance	NOT OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

235/50/20/104 W				
Summer tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				235/50 R 20 104 W
Tyre size FR				235/50 R 20 104 W
Tyre size RL				235/50 R 20 104 W
Tyre size RR				235/50 R 20 104 W
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Service, Maintenance, Check



Door RL, Dent(s), Acceptable



Wing RL, Scratch(es), Acceptable



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing trim RR, Scratch(es), Replace



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Outer door handle RR, Scratch(es), Repair and paint (complete)



Door trim RR, Scratch(es), Replace



Door FR, Dent(s) and scratch(es), Replace and paint



Alloy rim RR, Scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Acceptable



Kenteken	2CHX176
Merk Model	Land Rover Discovery Sport S P300e 1.5i 309pk/cv 5p AWD Aut.
Brandstofsoort	Benzine
Datum deel1	8/4/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
6/23/25	75,845	68000 km	Uitvoeren
6/23/25	75,845	batterij	Vervangen
6/23/25	75,845	instelling koplampen	Afstellen
6/23/25	75,845	luchtfilter	Vervangen
6/23/25	75,845	luchtfilter interieur	Vervangen
6/23/25	75,845	oliezeef	Vervangen
6/23/25	75,845	ruitenswisserrubber achter	Vervangen
6/23/25	75,845	ruitenswisserrubber vooraan	Vervangen
1/30/24	31,895	34000 km	Uitvoeren
1/30/24	31,895	batterij	Vervangen
1/30/24	31,895	luchtfilter interieur	Vervangen
1/30/24	31,895	oliezeef	Vervangen
1/30/24	31,895	ruitenswisserrubber achter	Vervangen
1/30/24	31,895	ruitenswisserrubber vooraan	Vervangen