


MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia					
				Policyholder			Opposite party				Opposite party company				
				Operation 2026	Claim number			Code / Agency				Date accident 04/06/2026			
				Expert code		Adjuster code		Policy number			Injured person can recover the VAT				
Date assignment 04/06/2026		Date first survey		Place SERRA RICCO'		C/O VAR	Repairs		Photo	Lien in favor of		Expiry date			
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)										Formerly plate					
Lessee / Co-owner										Date of overhaul					
Vehicle (Brand - Model - Version) VOLKSWAGEN T-ROC 2.0 TDI 150cv SCR						Plate GF558CL		Vin Chassis WVGZZA1ZMV031862		First Registration 20/04/2021					
Usage status NON CONOSCIUTO		Km 146154	Tyres % 50	Color BIANCO		Type of enamel METALLIZED			Consistency of damage		Type of Expert's report NOT DEFINITIVE				
Equipment															
Approval code		For commercial vehicles	Carrying Qls 0	Tare, Q 0	Wheelbase		Seats No. 0					Axles 0			
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses									
Damaged items / restoration operations						SR		LA		VE		ME	D.M. S.C.	Costs of spare parts * (VAT excluded)	
						Dif		Time		Dif		Time		Time	
1	2GA867605D82V	Internal panel of rear hatch				S		S		S					
1	2GA805903K9B9	Front bumper lower part				S		S		S					
1	2GA807434AJ9B9	Rear bumper lower part				S		S		S					
1	2GA854731D9B9	Front wheel arch trim				L	S		S		S				
1	2GA867769DEH8	Parcel shelf				S		S		S					
1	2GA854939AFRYP	Trim of front door				L	S		S		S				
1	05L130755	Pompa iniezione				S		S		S					
1	05L109119A	Cinghia distribuzione				S		S		S					
1	03N109244A	Tenditore				S		S		S					
1	05L109243	Tenditore				S		S		S					
1	04L260849G	Cinghia servizi				S		S		S					
1	04L903315N	Tenditore servizi				S		S		S					
1	05L130277E	Iniettori				S		S		S					
1	Codice Ricambio	Kit bulloni iniettori				S		S		S					
1	Codice Ricambio	Kit tubazioni				S		S		S					
1	05L130089	Rail				S		S		S					
1	04L130764E	Valvola regolaz. press.				S		S		S					
1	05L906054A	Sensore pressione				S		S		S					
1	5Q0919088AM	Pompa carb. con sens.				S		S		S					
1	5WA201055M	Serbatoio carb.				S		S		S					
1	5Q0127177	Filtro gasolio				S		S		S					
1	Codice Ricambio	S/R parti meccaniche, pulizia imp. e codifiche				S		S		S					
1	2GA807421GGRU	Rear bumper upper part				M				M					
1	2GA807217QGRU	Front bumper upper part				M		M		M					
1	2GA821021	Front mudguard				L	L		L		L				
1	2G7857537GRU	External rear-view mirror cap				L	L			L					
1	2GA831052AH	Front door				R	L		L		L				
1	2GA809844	rear mudguard				R	L		L		L				
1	2GA831051AH	Front door				L	L		L		L				
1	Codice Ricambio	Rettifica n.4 cerchi in lega													
1	Codice Ricambio	Igienizzazione/smacchiatura int. tessuto													
1	Codice Ricambio	Ossatura vano porta post. PRM				L									
1	Codice Ricambio	Ossatura vano porta post. PRM				R									
1	Codice Ricambio	Ossatura vano porta ant. PRM													

New for old value (N)		Remarks											
		Next ...											
Sheet No 1 / 2													

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2026		Claim number				Code / Agency				Date accident 04/06/2026							
				Expert code		Adjuster code				Policy number				Injured person can recover the VAT							
Date assignment 04/06/2026		Date first survey		Place SERRA RICCO'		C/O VAR		Repairs		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)														Formerly plate							
Lessee / Co-owner														Date of overhaul							
Vehicle (Brand - Model - Version) VOLKSWAGEN T-ROC 2.0 TDI 150cv SCR								Plate GF558CL		Vin Chassis WVGZZZA1ZMV031862				First Registration 20/04/2021							
Usage status NON CONOSCIUTO		Km 146154		Tyres % 50		Color BIANCO		Type of enamel METALLIZED				Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0										Wheelbase		Seats No. 0		Axles 0	
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts			
								Dif		Time		Dif		Time		Dif		Time		Time	
1		Codice Ricambio		Cofano ant. PRM																	
1		Codice Ricambio		Bracciolo centrale ant. PRM																	
1		Codice Ricambio		--- NOTE ---																	
1		Codice Ricambio		Quantificati i danni visibili, potenzialmente correlati																	
1		Codice Ricambio		con quanto rilevabile e come da prev, fornitoci dal																	
1		Codice Ricambio		(a seguito del Suo rilevam. del carb. contaminato).																	

New for old value (N)	Remarks PNEUM. M S GOODYEAR 215/55R17. VHL SPORCO. NOTE NEL CORPO PERIZIA.
-----------------------	---