

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia									
				Policyholder				Opposite party				Opposite party company							
				Operation 2026		Claim number		Code / Agency				Date accident 01/07/2026							
				Expert code		Adjuster code		Policy number				Injured person can recover the VAT							
Date assignment 01/07/2026		Date first survey 07/07/2026		Place ROMA		C/O VAR		Repairs TO START		Photo Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)											Formerly plate								
Lessee / Co-owner											Date of overhaul								
Vehicle (Brand - Model - Version) FIAT PANDA 1.0 FireFly 70cv S&S Hybrid								Plate GJ939YZ		Vin Chassis ZFABF5BJ5N3H00767		First Registration 21/04/2022							
Usage status NON CONOSCIUTO		Km 70334		Tyres % 40		Color Grigio		Type of enamel METALLIZED/DOUBLE		Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																			
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0						Wheelbase		Seats No. 0		Axles 0			
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses													
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts	
								Dif Time		Dif Time		Dif Time		Time		+		(VAT excluded)	
1	51881126	Trim of rear bumper						S		S		S							
1	52174842	Front light						R	S		S		S						
1	735628563	Front bumper central trim							S		S		S						
1	52056622	Front wheel cap						L	S		S		S						
1	735628630	Front wheel cap						R	S		S		S						
1	735553848	Rear wheel cap						L	S		S		S						
1	735553848	Rear wheel cap						R	S		S		S						
1	735667437	Internal panel of rear door						L	S		S		S						
1	735667436	Internal panel of rear door						R	S		S		S						
1	735535876	Dashboard glove compartment flap							S		S		S						
1	Codice Ricambio	Cornice sportello portaoggetti							S		S		S						
1	Codice Ricambio	Tappetino lato guidatore							S		S		S						
1	51858991	Rear door						R	M		L		M						
1	52098463	Front door						R	M		L		M						
1	96525563	Front bumper							M		M		M						
1	51931803	Front mudguard						L	M		M		M						
1	96525562	Rear bumper							L		L		L						
1	71771215	rear mudguard						R	L				L						
1	51841736	Front bonnet							L		L		L						
1	52098468	Front door						L	L		L		L						
1	51858992	Rear door						L	L		L		L						
1	52048222	Roof							L		L		L						
1	6000627445	Compartment structure of front door						L	L		L		L						
1	Codice Ricambio	Snacchiatura tappezzeria																	
1	Codice Ricambio	Seconda chiave																	

New for old value (N)	Remarks
	Pneum. Continental 175/65 R16. Vhl sporco.

ALPHABET

Telaio ZFABF5BJ5N3H00767

GJ939YZ

FIAT PANDA 1.0 FireFly 70cv S&S Hybrid berlina 2v 70CV 5P manuale

Current Odo (Time of Ma	Maintenance Request	Service Type Descriptio	Maintenance Job Description
5.765	13/10/22	Maintenance	Gestione Garanzia
5.868	20/10/22	Maintenance	Gestione Garanzia
43.965	09/12/24	Maintenance	Generico
43.965	09/12/24	Maintenance	Olio Motore
43.965	09/12/24	Tagliando a 45 000 km	Tagliando a 45 000 km
67.947	27/04/26	Maintenance	Olio Motore
67.947	27/04/26	Tagliando a 60 000 km	Tagliando a 60 000 km
68.745	27/04/26	Maintenance	Revisione Periodica MTC
68.745	27/04/26	Maintenance	Revisione Periodica MTC mo