


FIAT DUCATO:

Vinnumber:	ZFA25000002G89139	Versionname:	2.3 Multijet 150 pk XL-H2 35 Maxi
First Registrationdate:	16/04/2018	Fiscalpower:	
Expertise Mileage:	189355	Power Kw:	109
Bodytype:		Body colour	White
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel
Transmission:		Parking lot	Icv18
Fueltype:	Diesel		
Maintenance	OK		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Light Commercial Vehicle		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	1	Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection
Tyres

215/75/16/114 R				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				8.0
Tyre profile depth RR				8.0
Tyre size FL				215/75 R 16 114 R
Tyre size FR				215/75 R 16 114 R
Tyre size RL				215/75 R 16 114 R
Tyre size RR				215/75 R 16 114 R
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3107,42
Ignition key, Missing, Replace	262,56



Ignition key, Broken, Replace	262,56
-------------------------------	--------



Door panel RR, Broken, Replace	150,85
--------------------------------	--------



Bumper F, Dent(s), Acceptable	0,00
-------------------------------	------



Bumper grille, Scratch(es), Acceptable	0,00
--	------



Bumper moulding F, Scratch(es), Acceptable	0,00
--	------



Wing RL, Dent(s) and scratch(es), Acceptable	0,00
--	------



Door FL, Dent(s) and scratch(es), Acceptable	0,00
--	------



Steel rim FL, Scratch(es), Acceptable	0,00
---------------------------------------	------



Mirror side repeater L, Broken, Replace	31,96
---	-------



Outside rear-view mirror housing L, Scratch(es), Acceptable	0,00
---	------



Outside rear-view mirror base L, Broken, Replace	289,22
--	--------



Boot door lining L, Broken, Replace	165,60
-------------------------------------	--------



Boot door lining R, Broken, Replace	163,50
-------------------------------------	--------



Internal boot lining L, Broken, Replace	127,00
---	--------



Internal boot lining R, Broken, Replace	550,90
---	--------



Internal boot lining R, Broken, Replace	351,30
---	--------



Wheel aperture RR, Dent(s) and scratch(es), Acceptable	0,00
--	------



Wheel aperture RL, Dent(s) and scratch(es), Acceptable	0,00
--	------



Bumper R, Scratch(es), Acceptable

0,00



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)

685,47



Wing trim FR, Broken, Replace

66,50



Outside rear-view mirror housing R, Scratch(es), Acceptable

0,00



Wing RR, Dent(s) and scratch(es), Acceptable

0,00



Sliding door R, Dent(s) and scratch(es), Acceptable

0,00



Outer sill R, Scratch(es), Acceptable

0,00

