

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2026		Claim number		Code / Agency				Date accident 30/07/2026									
				Expert code		Adjuster code		Policy number				Injured person can recover the VAT									
Date assignment 30/07/2026		Date first survey 31/07/2026		Place TORINO		C/O VAR		Repairs TO START		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)												Formerly plate									
Lessee / Co-owner												Date of overhaul									
Vehicle (Brand - Model - Version) MAZDA CX-60 2.5L e-SKYACTIV PHEV Excl. Line AWD								Plate GM158PT		Vin Chassis JMZKH0HB701121168				First Registration 30/01/2023							
Usage status NON CONOSCIUTO		Km 69007		Tyres % 50		Color NERO		Type of enamel METALLIZED/DOUBLE				Consistency of damage YES		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0										Wheelbase		Seats No. 0		Axles 0	
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts			
								Dif Time		Dif Time		Dif Time		Time		+		(VAT excluded)			
1 KAAB68550H02		Internal panel of rear door				L		S		S		S									
1 KAAA50031ABB		Front bumper						S		S		S									
1 KR9R51W30BE4		Front wheel arch trim				L		S		S		S									
1 KAAA50231		Rear bumper side trim				R		S		S		S									
1 KAAA502218P		Rear bumper						M		M		M									
1 KBB352211A		Front mudguard				L		L		L		L									
1 KBY15902XG		Front door				L		L		L		L									
1 KBY371410		rear mudguard				L		L		L		L									
1 KBY370410		rear mudguard				R		L		L		L									
1 Codice Ricambio		Pneumatico ant.				R															
1 Codice Ricambio		Seconda chiave																			
1 Codice Ricambio		N4 Dischi ruota																			
1 Codice Ricambio		Igienizzazione interni																			

New for old value (N)	Remarks Pneum. Hankook 235/50 R20. Vhl sporco. Presenti due cavi di ricarica (mod2-3); verificare dot. di serie.
-----------------------	--