



LAND ROVER DISCOVERY SPORT: GM-380-RT

Vinnumber:	SALCA2BT7PH330526	Versionname:	LAND ROVER DISCOVERY SPORT 1.5 P300e PHEV
First Registrationdate:	14/03/2023	Fiscalpower:	AUTO 4WD SE VP [5P] bva 8-309CH-11cv (SUV)
Expertise Mileage:	28828	Power Kw:	227
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Wheel-drive	Interior colour:	Black
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Seats electric F L	
GPS big screen color		Seats electric F R	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Headlights Xenon/LED/Laser	
Steering wheel leather		Front parking sensors	
Type of climate control	Autom climate control	Rear parking sensors	
		Rear view camera	
		Seat cover lining	Lining Semi-leather

Tyres


	235/50/20/104 Y			
Summer tyres:	Fr.L.	Pirelli: 25%	Fr.R.	Pirelli: 25%
	Re.L.	Pirelli: 30%	Re.R.	Pirelli: 30%
Tyre profile depth FL				6.4
Tyre profile depth FR				6.5
Tyre profile depth RL				6.3
Tyre profile depth RR				6.2
Tyre size FL				235/50 R 20 104 Y
Tyre size FR				235/50 R 20 104 Y
Tyre size RL				235/50 R 20 104 Y
Tyre size RR				235/50 R 20 104 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Interior, Dirty, Cleaning



Alloy rim RL, Scratch(es), Repair/replace (lump sum)



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing trim RL, Scratch(es), Replace



Door trim RL, Scratch(es), Replace



Door FL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Paint




Wing RR, Scratch(es), Polish



Charging cable (normal), Missing, Replace




Bumper moulding R, Scratch(es), Paint



Tailgate / Boot, Scratch(es), Paint



Bumper corner RL, Scratch(es), Paint



Historique Maintenance

Immatriculation: **GM-380-RT** Date de 1ère immatriculation: **14/03/2023**

Modèle: **Land Rover DISCOVERY SPORT 1.5 P300e PHEV AUTO 4WD SE VP [5P] bva 8-309CH-11cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
15/04/2025	18.534	NDJ PARIS	REVISION ET CLIM
	0		LIQUIDE DE FREIN
	0		PILE DE CLE RPLT
25/03/2024	10.075	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE