

KNOX

Volkswagen ID.4 '21 BEV


Vehicle information


Make:	Volkswagen	License:	
Gearbox:	Automatic	Body color:	
Model:	ID.4 '21 BEV	VIN:	WVGZZZE2ZMP022188
Fuel type:	Electric	Power:	150 kW
Version:	ID.4 77kWh Life	First registration	05/05/2021
Mileage:	153050 km	N° of doors:	

Damage summary

Interior	2
Left	5
Right	3

Commercial pictures





Options according to the inspector

Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser	Yes
Hook	Yes	Radio multimedia	Yes	Telephone equipment	Yes

Damages

Alloy rim FL
Scratch(es)
Repair and paint (complete)
Left



Alloy rim FR
Scratch(es)
Repair and paint (complete)
Right



Alloy rim RL
Scratch(es)
Repair and paint (complete)
Left



Alloy rim RR
Scratch(es)
Repair and paint (complete)
Right





Door FL
Scratch(es)
Repair and paint (complete)
Left



Door RL
Scratch(es)
Repair and paint (complete)
Left



Interior
Smell
Ozone treatment (Animal smell)
Interior



Interior
Dirty
Chemical cleaning
Interior



Wing RL
Scratch(es)
Repair and paint (complete)
Left



Wing RR
Dent(s) and scratch(es)
Repair and paint (complete)
Right



Tyres		
	Front Left	
	Summer	
	255/45/20/101/T	
	Continental	
	5.3 mm	
	Front Right	
	Summer	
	255/45/20/101/T	
	Continental	
	5.2 mm	
	Rear Left	
	Summer	
	255/45/20/101/T	
	Continental	
	4.2 mm	
	Rear Right	
	Summer	
	255/45/20/101/T	
	Continental	
	3.7 mm	

Checks		
CO2 Emission	0 Digital maintenance	Yes
GPS storage	Yes Luggage cover	Yes
Number head rests	5 Number of charging cables (rapid charge)	1
Number of keys total	2 Reset to factory settings	Yes, vehicle is reset to factory settings
Service book	N/A User's manual	Yes

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.