

MACDAM

Skoda Enyaq '21 BEV



Vehicle information

Make:	Skoda	License:	
Gearbox:	Automatic	Body color:	
Model:	Enyaq '21 BEV	VIN:	TMBJC7NY6MF023045
Fuel type:	Electric	Power:	150 kW
Version:	Enyaq iV80	First registration	03/06/2021
Mileage:	186656 km	N° of doors:	

Damage summary

Front	1
Interior	2
Left	1
Rear	3
Right	1

Commercial pictures





Batterijcertificaat

Datum van diagnose: 08/06/2026

Readpleeg het Moba-certificaat door deze QR-code te scannen

Meer weten over: www.get-moba.com

90,26%

Status van de gezondheid (SOH)*

Skoda Enyaq 80

VIN : TMBJC7NY6MF023045
Kilometerstand : 186.656 km

*SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie

CARA
Assessment Battery Health Check



Options according to the inspector

Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser	Yes
Hook	Yes	Panoramic roof	Yes	Radio multimedia	Yes
Sun Roof electric	Yes	Telephone equipment	Yes		

Damages

Bumper R

Scratch(es)

Repair and paint (complete)

Rear



Bumper trim R

Scratch(es)

Replace

Rear



Charging cable (normal)

Missing

Replace

Rear



Door RL
Dent(s)
Repair and paint (complete)
Left




Ignition key
Worn
Replace
Interior



Shutter / cover
Missing
Replace
Interior



Windscreen
Stone chip(s)
Windscreen repair
Front



Wing RR
Chemical polution
Polish
Right



Tyres			
Front Left			
Summer			
235/55/19/105/V			
Michelin			
5.9 mm			
Front Right			
Summer			
235/55/19/105/V			
Michelin			
5.8 mm			
Rear Left			
Summer			
235/55/19/105/V			
Michelin			
3.6 mm			
Rear Right			
Summer			
235/55/19/105/V			
Michelin			
3.7 mm			

Checks			
Certificate of Conformity	No	CO2 Emission	0
Digital maintenance	Yes	GPS storage	Yes
GPS storage	HD	Luggage cover	Yes
Number head rests	5	Number of charging cables (rapid charge)	1
Number of keys total	2	Service book	N/A
User's manual	Yes		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.