

DEKRA Automotive Solutions

Vehicle details

VIN	VR3F4DGZT PY646925	Registration date	01/01/1900	Exterior Color	Unknown
Brand	PEUGEOT			Odometer	48 475 km
Model	508 1.6 Hybrid 225 e-EAT8 GT				

Inspection Details

Arrival Date	12/12/2025	Inspection date	11/12/2025
Assign Date	12/12/2025		



Generic equipment

--

Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
Load cover	✓

Technical Document

Service manual holder	✓
User manual	✓
Adapter USB	✓
Spare key	✓
Certificate of conformity	✓
Title / License document	✓

Tyres

Michelin 235/45/18 Y Summer 5.0 mm




Michelin 235/45/18 Y Summer 5.0 mm

Michelin 235/45/18 Y Summer 5.0 mm






Michelin 235/45/18 Y Summer 5.0 mm



Damages

1		Part	Engine soundproofing	Repair Time	0.20	Part Cost	184.48€
		Position	-	Repair Cost	12.00€	Gross Cost	196.48€
		Damages	Perforated	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	196.48€

DEKRA Automotive Solutions

2		Part	Bumper	Repair Time	-	Part Cost	-
		Position	Front right	Repair Cost	-	Gross Cost	75.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	75.00€	Net Cost	75.00€
3		Part	Spoiler	Repair Time	-	Part Cost	-
		Position	Front	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
4		Part	Special rim 18"	Repair Time	-	Part Cost	-
		Position	Back right	Repair Cost	-	Gross Cost	150.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Lumpsum repair	Flat Rate	150.00€	Net Cost	150.00€
5		Part	Door	Repair Time	0.20	Part Cost	-
		Position	Back right	Repair Cost	12.00€	Gross Cost	12.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Polishing	Flat Rate	12.00€	Net Cost	12.00€
6		Part	Special rim 18"	Repair Time	-	Part Cost	-
		Position	Front right	Repair Cost	-	Gross Cost	150.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Lumpsum repair	Flat Rate	150.00€	Net Cost	150.00€