



CITROËN BERLINGO: FM-733-KK

Vinnumber:	VR7EFBHWBKN535850	Versionname:	CITROËN BERLINGO Taille M 1000kg BlueHDi 75
First Registrationdate:	17/12/2019		BVM Club VU [4P] bvm 5-75CH-5cv
Expertise Mileage:	88593		(fourgonnettesimple cabine)
Bodytype:	Transporter	Fiscalpower:	
Gearbox:	MAN 5 VIT	Power Kw:	55
Transmission:	Front	Body colour:	White
Fueltype:	Diesel	Paint type:	Opaque
Engine functioning:	Yes	Interior colour:	Black
Battery functioning:	Yes	Type of rims (mounted):	Steel
Vehicle running:	Yes	Dashboard color:	Black
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	1	Radio	
Number keys remote	1	Rear parking sensors	
Windows electric F		Sliding door right-side	
Cruise Control		Seat cover lining	Lining Other
Type of climate control	Manual climate control		

Tyres

	215/65/16/102 V			
Summer tyres:	Fr.L.	Hankook: 25%	Fr.R.	Hankook: 20%
	Re.L.	Hankook: 20%	Re.R.	Hankook: 20%
Tyre profile depth FL				6.4
Tyre profile depth FR				6.8
Tyre profile depth RL				6.9
Tyre profile depth RR				6.8
Tyre size FL				215/65 R 16 102 V
Tyre size FR				215/65 R 16 102 V
Tyre size RL				215/65 R 16 102 V
Tyre size RR				215/65 R 16 102 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Spare wheel	Yes	Jack	Yes
Remote ignition key, Missing, Repair/replace (lump sum)			



Floor mat F, Tear, Replace



Door panel FL, Scratch(es), Replace



Door FL, Dent(s), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Replace



Side panel L, Dent(s), Repair and paint (complete)



Door trim FL, Deformed / Strained, Replace



Bumper F, Deformed / Strained, Replace



Bumper F, Scratch(es), Paint



Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Paint



Door trim FR, Deformed / Strained, Replace



Door trim RR, Scratch(es), Replace



Outside rear-view mirror housing R, Scratch(es), Replace



Boot door lining L, Scratch(es), Replace



Boot door lining R, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)




Boot door panel RL, Dent(s), Repair and paint (complete)



Bumper corner RR, Deformed / Strained, Repair and paint (complete)



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)



Rear light R, Scratch(es), Replace



Historique Maintenance

Immatriculation: **FM-733-KK** Date de 1ère immatriculation: **17/12/2019**

Modèle: **Citroen BERLINGO Taille M 1000kg BlueHDi 75 BVM Club VU [4P] bvm 5-75CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
09/06/2026	88.589	CDR LATTES	DIVERS
			REVISION ET CLIM
			LIQUIDE DE FREIN
			DIAG
			RESERVOIR ADBLUE RPLT
			ADBLUE
14/04/2026	87.248	CDR LATTES	LAMPES AR RPLT
03/06/2025	76.144	CDR LATTES	DIVERS CLIM
			PLAQUETTES AV RPLT
			BALAIS ESSUIE GLACE AV
			REVISION ET AIR ET CARBURANT
28/10/2024	64.432	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
02/05/2024	57.927	GM GROUP	LIQUIDE DE FREIN
			BALAIS ESSUIE GLACE AV AR
			PLAQUETTES AR RPLT
			REVISION ET CLIM
29/03/2023	39.750	GM GROUP	LAMPE AR RPLT
			DISQUES PLAQUETTES AV RPLT
			REVISION
26/04/2022	30.993	CDR LATTES	LIQUIDE DE FREIN
			BALAIS ESSUIE GLACE AV
			REVISION ET CLIM
25/05/2021	17.932	GM GROUP	BALAIS ESSUIE GLACE AV
			REVISION