



VOLKSWAGEN CADDY MAXI: [REDACTED]

Vinnumber:	WV2ZZZ2KZLX046862	Versionname:	2.0 CRTDi 75kW SCR BMT Maxi Trendline
First Registrationdate:	9/03/2020	Fiscalpower:	
Expertise Mileage:	208065	Power Kw:	75
Bodytype:		Body colour:	Grey
Gearbox:	MAN 5 VIT	Type of rims (mounted):	Steel
Transmission:		Parking lot:	2103
Fueltype:	Diesel		
Maintenance:	NOT OK		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Rear parking sensors:	
Cruise Control:		Type of Tow bar:	Tow bar fixed
Steering wheel multifunctional:			
Radio multimedia:			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		
Type of GPS storage:	SD present		

Limited Technical Inspection

Tyres

205/55/16/94 V				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 16 94 V
Tyre size FR				205/55 R 16 94 V
Tyre size RL				205/55 R 16 94 V
Tyre size RR				205/55 R 16 94 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	4704,88
Service, Maintenance, Check	0,00



Interior, Dirty, Shampooing 175,00



Seat cover FL, Tear, Replace 417,72



Armrest, Worn, Replace 136,47



Interior, Smell, Forfeit 150,00



Glove box, Scratch(es), Smart repair 116,69




Engine insulation, Damaged, Replace 0,00



Bonnet, Dent(s) and scratch(es), Replace and paint 1227,08





Bumper F, Dent(s) and scratch(es), Acceptable 0,00



Windscreen, Tear, Replace 0,00



Wheel cover RL, Missing, Replace 68,42



Wheel cover FL, Missing, Replace 68,42



Wing RL, Dent(s) and scratch(es), Repair and paint (complete) 442,70



Door RL, Dent(s) and scratch(es), Repair and paint (complete) 512,87



Internal boot lining L, Scratch(es), Acceptable 0,00



Internal boot lining R, Scratch(es), Acceptable 0,00



Shutter / cover R, Missing, Replace 19,51



Shutter / cover R, Missing, Replace 19,51



Boot lid covering R, Scratch(es), Acceptable 0,00



Rear light R, Crack, Replace 142,57




Bumper R, Scratch(es), Acceptable 0,00




Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete) 625,96



Wheel cover FR, Missing, Replace 68,42



Wheel cover RR, Missing, Replace 68,42



Wing FR, Dent(s), Acceptable 0,00



Sliding door R, Scratch(es), Repair and paint (complete) 0,00



Wing RR, Dent(s) and scratch(es), Repair and paint (complete) 0,00



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete) 445,12



Roof, Scratch(es), Acceptable 0,00

