



PEUGEOT 508 SW:

Vinnumber:	VR3FCYHZTMY009954	Versionname:	1.5 BlueHDi 130 S&S EAT8 Allure Pack
First Registrationdate:	12/03/2021	Fiscalpower:	
Expertise Mileage:	190064	Power Kw:	96
Bodytype:		Body colour	Blue
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3307
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar removable
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS base		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Tyres

215/55/17/98 W				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/55 R 17 98 W
Tyre size FR				215/55 R 17 98 W
Tyre size RL				215/55 R 17 98 Y
Tyre size RR				215/55 R 17 98 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				2480
Tyre make RR				2480


Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3775,66
Seat cover FL, Tear, Replace	786,80



GPS, Crack, Replace 715,54



Engine insulation, Damaged, Replace 117,86



Bumper F, Dent(s) and scratch(es), Repair and paint (complete) 356,09




Bonnet, Chemical polution, Polish 0,00



Door FL, Dent(s) and scratch(es), Repair and paint (complete) 505,30



Door RL, Dent(s), Acceptable 0,00



Bumper R, Bad re 356,09



Door RR, Dent(s), Acceptable	0,00
------------------------------	------



Alloy rim FR polished, Scratch(es), Repair and paint (complete)	204,21
---	--------



Roof, Dent(s) and scratch(es), Repair and paint (complete)	733,77
--	--------

