



Peugeot 308

| | | | |
|------------------------------------|--------------------------|-------------------------|------------------|
| Vinnumber: | VR3F4DGXTNY559863 | Versionname: | |
| First Registrationdate: | 8/07/2022 | Fiscalpower: | |
| Expertise Mileage: | 113863 | Power Kw: | |
| Bodytype: | | Body colour: | Grey |
| Gearbox: | Automatic | Type of rims (mounted): | Aluminium |
| Transmission: | | Parking lot: | 2329 |
| Fueltype: | Hybrid Petrol | | |
| Type of rims (mounted): | Aluminium | | |
| Certificate of Conformity: | Yes | | |
| Category: | Passenger Car | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|---------------------------------------|-----------------------|----------------------|
| Number of keys total | 2 | Luggage cover | |
| Cruise Control | | Front parking sensors | |
| Steering wheel multifunctional | | Rear parking sensors | |
| Radio multimedia | | Type of Tow bar | Tow bar fixed |
| Type of headlighting | Headlighting LED | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining semi-artificial leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

Tyres

| 225/45/17/92 H | | | | |
|-----------------------|-------|-------------------------|-------|-------------------------|
| Summer tyres: | Fr.L. | Vredestein: 5 mm | Fr.R. | Vredestein: 5 mm |
| | Re.L. | Vredestein: 5 mm | Re.R. | Vredestein: 5 mm |
| Tyre profile depth FL | | | | 5.0 |
| Tyre profile depth FR | | | | 5.0 |
| Tyre profile depth RL | | | | 5.0 |
| Tyre profile depth RR | | | | 5.0 |
| Tyre size FL | | | | 225/45 R 17 92 H |
| Tyre size FR | | | | 225/45 R 17 92 H |
| Tyre size RL | | | | 225/45 R 17 92 H |
| Tyre size RR | | | | 225/45 R 17 92 H |
| Tyre type FL | | | | Summer |
| Tyre type FR | | | | Summer |
| Tyre type RL | | | | Summer |
| Tyre type RR | | | | Summer |
| Tyre make FL | | | | 2480 |
| Tyre make FR | | | | 2480 |
| Tyre make RL | | | | 2480 |
| Tyre make RR | | | | 2480 |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 1 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|---|----------------|
| Total cost ex VAT | 2688,89 |
| Centre console, Scratch(es), Acceptable | 0,00 |



Seat cover FL, Damaged, Acceptable 0,00



Seat cover FL, Stain, Cleaning 29,16



Wing RL, Scratch(es), Repair and paint (complete) 431,58



Door RL, Scratch(es), Acceptable 0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 204,21



Charging cable (fast), Missing, Replace 256,50



Boot lid covering R, Scratch(es), Replace 285,17



Bumper R, Scratch(es), Repair and paint (complete) 296,58



Rear light L, Scratch(es), Replace 345,69



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21



Alloy rim RR polished, Scratch(es), Repair and paint (complete) 204,21



Wing RR, Dent(s) and scratch(es), Repair and paint (complete) 431,58



Roof, Chemical polution, Polish 0,00



Bodywork, Not original part, Remove lettering 0,00

