

MACDAM

Audi Q4 e-tron '21 BEV



Vehicle information



Make:	Audi	License:	
Gearbox:	Automatic	Body color:	
Model:	Q4 e-tron '21 BEV	VIN:	WAUZZZFZ9NP038717
Fuel type:	Electric	Power:	150 kW
Version:	Q4 e-tron 40 Advanc.Ed.	First registration	17/05/2022
Mileage:	183872 km	N° of doors:	

Damage summary

Left	4
Rear	2
Right	3

Commercial pictures





Options according to the inspector				
Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser
Radio multimedia	Yes	Telephone equipment	Yes	

Damages

Alloy rim FL

Scratch(es)

Repair and paint (complete)

Left



Alloy rim FR

Scratch(es)

Repair and paint (complete)

Right



Alloy rim RL

Scratch(es)

Repair and paint (complete)

Left



Alloy rim RR

Scratch(es)

Repair and paint (complete)

Right



Bumper R
Scratch(es)
Repair and paint (complete)
Rear



Charging cable (normal)
Missing
Replace
Rear



Door RL
Scratch(es)
Repair and paint (complete)
Left



Door RR
Scratch(es)
Repair and paint (complete)
Right



Wing trim RL
Scratch(es)
Replace and paint
Left



Tyres			
Front Left			
Summer			
238/45/21/101/T			
Pirelli			
5.0 mm			
Front Right			
Summer			
238/45/21/101/T			
Pirelli			
5.2 mm			
Rear Left			
Summer			
238/45/21/101/T			
Continental			
4.6 mm			
Rear Right			
Summer			
238/45/21/101/T			
Continental			
4.3 mm			

Checks			
CO2 Emission	0	Digital maintenance	Yes
GPS storage	Yes	Luggage cover	Yes
Number head rests	3	Number of charging cables (rapid charge)	1
Number of keys total	2	Service book	N/A
User's manual	Yes		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.