

MACDAM

Volkswagen ID.4 '21 BEV




Vehicle information


Make:	Volkswagen	License:	
Gearbox:	Automatic	Body color:	
Model:	ID.4 '21 BEV	VIN:	WVGZZZE2ZMP044275
Fuel type:	Electric	Power:	150 kW
Version:	ID.4 77kWh Life	First registration	18/06/2021
Mileage:	205318 km	N° of doors:	

Damage summary

Front	2
Left	2
Rear	3
Right	2

Commercial pictures





Options according to the inspector				
Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser
Radio multimedia	Yes	Telephone equipment	Yes	

Damages				
---------	--	--	--	--

Alloy rim FL
Scratch(es)
Repair and paint (complete)
Left



Alloy rim RR
Scratch(es)
Repair and paint (complete)
Right



Bumper F
Scratch(es)
Repair and paint (complete)
Front



Bumper R
Scratch(es)
Replace
Rear



Bumper spoiler F
Dent(s)
Replace
Front




Charging cable (normal)
Missing
Replace
Rear




Door RR
Scratch(es)
Repair and paint (partial)
Right



Tailgate / Boot
Dent(s) and scratch(es)
Repair and paint (complete)
Rear



Wing RL
Bad repair
Repair and paint (complete)
Left



Tyres

Front Left

Summer

255/50/19/103/T

Hankook

6.4 mm

Front Right

Summer

255/50/19/103/T

Hankook

6.2 mm

Rear Left

Summer

255/50/19/103/T

Hankook

6.0 mm

Rear Right

Summer

255/50/19/103/T

Hankook

5.7 mm

Checks			
CO2 Emission	0	Digital maintenance	Yes
GPS storage	Yes	Luggage cover	Yes
Number head rests	5	Number of charging cables (rapid charge)	1
Number of keys total	2	Reset to factory settings	Yes, vehicle is reset to factory settings
Service book	N/A	User's manual	Yes

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.