



**PEUGEOT 3008: FV-961-GQ**

Vinnnumber:	<b>VF3MCYHZRLS240077</b>	Versionname:	<b>PEUGEOT 3008 BlueHDi 130 S&amp;S EAT8 ACTIVE BUSINESS VP [5P] bva 8-130CH-7cv (SUV)</b>
First Registrationdate:	<b>23/11/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>107953</b>	Power Kw:	<b>96</b>
Bodytype:	<b>SUV</b>	Body colour:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Interior colour:	<b>Grey</b>
Fueltype:	<b>Diesel</b>	Type of rims (mounted):	<b>Aluminium</b>
Engine functioning:	<b>Yes</b>	Dashboard color:	<b>Black</b>
Battery functioning:	<b>Yes</b>		
Vehicle running:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		

**Options**


Number of keys total	<b>1</b>	Radio	
Number keys remote	<b>1</b>	Central consol F	
GPS big screen color		Luggage cover	
GPS storage		Headlights Xenon/LED/Laser	
GPS storage	<b>HD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Seat cover lining	<b>Lining Other</b>
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	<b>Autom climate control</b>		

**Tyres**

<b>215/65/17/103 V</b>				
Summer tyres:	Fr.L.	<b>Bridgestone: 60%</b>	Fr.R.	<b>Bridgestone: 60%</b>
	Re.L.	<b>Bridgestone: 45%</b>	Re.R.	<b>Bridgestone: 45%</b>
Tyre profile depth FL				<b>4.4</b>
Tyre profile depth FR				<b>4.4</b>
Tyre profile depth RL				<b>5.3</b>
Tyre profile depth RR				<b>5.1</b>
Tyre size FL				<b>215/65 R 17 103 V</b>
Tyre size FR				<b>215/65 R 17 103 V</b>
Tyre size RL				<b>215/65 R 17 103 V</b>
Tyre size RR				<b>215/65 R 17 103 V</b>
Tyre type FL				<b>All seasons</b>
Tyre type FR				<b>All Seasons</b>
Tyre type RL				<b>All seasons</b>
Tyre type RR				<b>All Seasons</b>
Tyre make FL				<b>255</b>
Tyre make FR				<b>255</b>
Tyre make RL				<b>255</b>
Tyre make RR				<b>255</b>

**Assistance equipment**

Roof liner, Burned, Replace



Interior, Dirty, Cleaning



Floor mat F, Tear, Replace



Remote ignition key, Missing, Repair/replace (lump sum)



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Alloy rim FR, Scratch(es), Acceptable



Side repeater L, Broken, Replace



Door RL, Scratch(es), Paint



Windscreen, Stone chip(s), Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Side repeater R, Scratch(es), Replace



Bumper corner RL, Deformed / Strained, Repair and paint (complete)



Bumper corner RR, Scratch(es), Acceptable



## Historique Maintenance

Immatriculation: **FV-961-GQ**

Date de 1ère immatriculation: **23/11/2020**

Modèle: **Peugeot 3008 BlueHDi 130 S&S EAT8 ACTIVE BUSINESS VP [5P] bva 8-130CH-7cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
09/02/2026	102.173	GARAGE PAUL BERT	REVISION ET CLIM
	0		ADBLUE
09/05/2025	82.974	GARAGE PAUL BERT	DIVERS CLIM
	0		PLAQUETTES AV RPLT
	0		PLAQUETTES AR RPLT
	0		REVISION
	0		ADBLUE
	0		LIQUIDE DE FREIN
14/02/2024	58.871	GARAGE DU STADE	REVISION
	0		REVISION
	0		FILTRE A AIR RPLT
	0		FILTRE CLIM RPLT
	0		BALAIS ESSUIE GLACE AV
	0		RECYCLAGE
03/06/2022	28.793	DANGLADE	REVISION