



Expertise

Protocol number: 46532400
Order No. / Reference: 26687646
Inspection date: 13 Jul 2026

Manufacturer: Opel	Model: Astra 1.5 D Start/Stop Sports Tourer Automatik Edition
VIN: W0VBD8EVXN8042304	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Astra 1.5 D Start/Stop Sports Tourer Automatik Edition	
Vehicle Identification number	W0VBD8EVXN8042304
Mileage (Read)	161,034 km
First registration	12 Aug 2022
Number of holders	1
Next periodical technical inspection	08/2027
(Report not on hand)	
Power / Engine displacement	90 kw / 1,496 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 9
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Silver metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	85 %
Last service on / at	10/2025 at 141,514 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ672625
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / ALL 00261		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,980 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Continental	8mm / 8mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91V	Summer tyres on Steel rim with wheel cover	Continental	4mm / 4mm
2)	205/55 R16 91V	Summer tyres on Steel rim with wheel cover	Continental	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment



Standard equipment

- 1.5 DIESEL ENGINE
- 2-WAY HEADREST
- 205/55 R 16 .. H
- 5-door Sports Tourer
- 9-speed automatic 9T45
- Ambient lighting
- OUTER HANDLE ASSY.
- 80 Ah battery
- AIR CONDITIONER CONTROL
- APERTURE, SUN, MIRROR WITH LIGHTING
- BOÎTE VITESSES-AUTO 9 VIT, 9T45, CPA, GEN 1
- 15-inch brake system
- CHASSIS EQUIPMENT, FRONT SHOCK ABSORBER ASSEMBLY
- COVERING FLOOR MAT CHARCOAL
- DAYT. RUNNING SEP. CAVITY LED
- Digital radio system
- Electric window lift, express up/down
- Ergonomic seat driver's side
- EXTRA FUEL ECONOMY
- RIM - 16 x 6.5, J, HIGH-VENT STEEL, DESIGN 1
- FOR 40/60 SPLIT SEAT
- FOR USE WITH 15" BRAKE SYSTEM
- FOR HEATED FRONT SEATS
- FOR WINDOW PUSH BUTTON
- FOR MONOCHROME DOT MATRIX DRIVER INFORMATION CENTER
- FOR SPORTS SEATS
- Exhaust gas EURO 6.3
- HOUSING MIRROR
- Generator 170A
- luggage compartment partition net
- Headlamp Control Auto Delay
- HEATING DUCT, REAR PASSENGER 2ND POSITION
- Humidity Sensor
- IN CONJUNCTION WITH SERVICE INTERVAL DISPLAY
- INDICATOR ENGINE OIL LIFE
- INTERIOR LAMP, REAR ROOF, INDOOR LAMP AND DOUBLE READING LAMP
- KIT TIRE INFLATOR
- LAMP INTR AMBIENT
- last 8 VIN digits to select Audatex option code for build date
- LED taillights
- Leather steering wheel, including cruise control
- Adjustable steering column with height and tilt adjustment
- LIGHT, TRUNK
- LEFT-HAND DRIVE
- Adjustable airflow
- LUMBAR DRIVER SEAT POWER 4WAY
- front center armrest
- MODEL UPGRADE 06
- 1496ccm (1.5 Ltr) 90kW
- 2-zone automatic climate control
- 205/55R16 SL 91V BW HW1
- 6.5 J x 16 steel wheel styled
- from M8000001/MG000001
- Stop+Start system
- AXLE RATIO - 2.89
- BATTERY LN4 AGM 12V 80AH
- Monochrome screen
- FRONT FLOOR CONSOLE WITH SLIDING ARMREST
- BRAKE MECHANIC PARKING
- CHASS EQUIP RR AXLE COMP CRANK
- CHASSIS FRONT WHEEL DRIVE-FWD
- Console
- Cruise Control, Automatic, Electric Speed
- digital audio system
- ELECTRICALLY OPERATED WINDOWS,REAR
- ENGINEERING YEAR 2021
- ESP, Electronic Stability Program
- VEHICLE LABELING - ECE ORGANISATION
- rear electric window regulator
- FOR DRIVER,PASSENGER,SIDE AND CURTAIN AIR BAG
- FOR 433 MHz FREQUENCY
- FOR BEDING, COVER, DISC, BLACK
- FOR MANUAL EXTENSION SEAT CUSHION
- SAFETY NET FOR ASSEMBLY PREPARATION
- FOR HEADLIGHT AUTOMATIC WITH TUNNEL DETECTION
- GEARING CODE
- GENERATOR 170 AMP
- LUGGAGE NET, FLOOR CARGO AREA
- Speed control
- LED HEADLAMPS
- HORN, SINGLE NOTE
- IDENTIFICATION-MCM
- IN CONJUNCTION WITH FOLDABLE MIRRORS, MANUAL
- BLACK INTERIOR
- Interior mirror automatically dimming
- KEY PRIMARY FOLDABLE ADD RIGID
- Short antenna, roof, radio
- LAMP, ASSY., INDOORS CUSTOMER SPECIAL
- SPEAKERS, 6
- leather steering wheel
- Steering wheel assembly, three spokes, leather
- Rear reading lights
- MANUAL HEADLIGHT RANGE ADJUSTMENT
- LOCK CONTROL STEER COLUMN MECH
- LUGGAGE CARRIER ROOF PAINT V1
- MARKETING AREA EUROPE GROUP
- MODEL CONVERSION RENAULT TRUCK, EXTRA LONG WHEELBASE, STD ROOF, 3,900 KG (GMD)



- OPEL / VAUXHALL SPECIFICATION - COCKPIT
- OPEL / VAUXHALL SPECIFICATION - FRONT VERTICAL SUSPENSION
- OPEL / VAUXHALL SPECIFICATION - ROOF TRIM
- CHÂSSIS-RABAISSÉ, MODIFIÉ OPTIONS
- PAYS-ALLEMAGNE
- PORT ELEK DEVICE USB ONLY
- PROVISION OPTIONS EUROPE
- Quickheat heating system
- Radio R 4.0 IntelliLink
- Wheel cover 16 inch
- REFRIGERANT LOW GWP
- TIRES, 215/55 R 16-93H
- Automatic tire pressure monitoring system
- RESTR SEAT BELT PRETENS RR
- Restraint Provisions Latch
- SALES PACKAGE WINTER PACK VAR1
- SALESPACK ERGON.SPORT SEAT DRV
- Side windows/rear window dark tinted
- SHUTTERS FRT GRILL ACT UPR&LWR
- Visibility Package
- Illuminated sun visors
- PASSENGER AIRBAG LOCK SWITCH
- Start/Stop System
- Control code
- SYSTÈME ELECTRONIQUE: EVENT DATA LOG (protégé)
- TACHOMETER ASSEMBLY, KM/H
- BAG, FRONT SEAT BACK, RIGHT
- TRANS-AUTO MERCHANDISED EQU.
- TRIM LEVEL STEERING
- VA ASM FRONT FASCIA
- VAA/COMPONENT REL FRONT SEAT ROW
- VEHICLE TYPE PASSENGER CAR
- VIN MODEL YEAR 2022
- FRONT SEAT, REAR, HEIGHT ADJUSTABLE, MANUAL
- WARNING LIGHT - SEAT BELT, PASSENGER
- WINDOW TYPE PRIVACY
- WINDSHIELD TYPE SOLAR ABSORBIN
- WIRING PROV CUSTOM WIRING BODY
- decorative molding, side panel

Extra equipment

- 2-layer metallic - Silver metallic
- Heated steering wheel
- Front/rear parking sensors

- OPEL / VAUXHALL SPECIFICATION - FRONT HORIZONTAL SUSPENSION
- OPEL / VAUXHALL SPECIFICATION - REAR SUSPENSION
- OPEL / VAUXHALL SPECIFICATION - TIRES AND WHEELS
- Parking Assistance Package Parking Assistance Package Parking Assistance Package
- POWER STEERING, NON-VARIABLE RATIO, ELECTRIC STANDARD RACK TRAVEL
- Quickheat rapid heating system
- Radio controls on the steering wheel
- RDO INFOTAINMENT SYS MID LEVEL
- Rain sensor
- Tire pressure monitoring system
- TIRE PRESSURE MONITORING SYSTEM
- RESTR.SYS.RR SEAT BELT 3P CENT
- INTERIOR REARVIEW MIRROR
- SALES REGION PKG MARKET, GROUP 01 (PSA)
- HEATED STEERING WHEEL SWITCH
- SENSOR, PARK PILOT
- SEAT BELT WARNING, REAR
- Sight and Light pack
- SAVE CHOOSE NONE
- REAR SPOILER
- STEERING WHEEL, RADIO AND PHONE CONTROLS
- SYSTÈME D'APPLICATION DE FREIN-ELECTRO-HYDRAULIQUE, E-BOOST
- BAG, FRONT SEAT BACK, LEFT
- TIRE SPARE NONE
- TRIM CLOTH LEV 2.1 JET BLACK
- ELECTRIC DOOR LOCK
- VA ASM STEERING COLUMN
- VEHICLE FUEL DIESEL B10
- USE WITH CENTER REAR HEADREST
- FRONT SEAT, DRIVER'S SIDE, 6-WAY MANUAL TRANSMISSION
- WARNING LIGHT - SEAT BELT, DRIVER
- WINDSCREEN, TACT, HUMIDITY-DEPARATE
- WIRING PROV CUSTOM WIRING (IP)
- WIRING PROV CUSTOM WIRING HDLP

- IntelliLux LED Matrix Light
- Navigation system
- Front seat heating



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Body	Underbody panelling (VM) - Broken / torn - Replace
2	Bonnet	Bonnet - dent(s) - Smart repair
3	Door - rear left side	Door - dent(s) - Smart repair
4	Tail light	Tail lamp - right side (Innen) - Scratched - Replace
5	Rear bumper	Bumper with Parktronic - Scratched - Paint
6	Vehicle glazing	Windscreen - Stone chips - Replace

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 23 Oct 2024	2.583,00 €

Repainting

No.	Repainting
1	Mudguard - left side, Professionally carried out

Paint coat thickness measurement

Mudguard - left side	221 µm
----------------------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Navigation



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Damage 1: Body: Underbody panelling (VM) - Broken / torn - Replace




Damage 1: Body: Underbody panelling (VM) - Broken / torn - Replace




Damage 2: Bonnet: Bonnet - dent(s) - Smart repair



Damage 2: Bonnet: Bonnet - dent(s) - Smart repair



Damage 3: Door - rear left side: Door - dent(s) - Smart repair



Damage 3: Door - rear left side: Door - dent(s) - Smart repair



Damage 4: Tail light: Tail lamp - right side (Innen) - Scratched - Replace



Damage 4: Tail light: Tail lamp - right side (Innen) - Scratched - Replace



Damage 5: Rear bumper: Bumper with Parktronic - Scratched - Paint



Damage 5: Rear bumper: Bumper with Parktronic - Scratched - Paint



Damage 5: Rear bumper: Bumper with Parktronic - Scratched - Paint



Damage 5: Rear bumper: Bumper with Parktronic - Scratched - Paint



Damage 5: Rear bumper: Bumper with Parktronic - Scratched - Paint



Damage 6: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 6: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 6: Vehicle glazing: Windscreen - Stone chips - Replace



Mudguard - left side: 221 µm