VOLKSWAGEN ARTEON

Vehicle information

Brand:	**VOLKSWAGEN**	License plate:	**2BDC191**
Gearbox:		Body color:	
Model:	**ARTEON**	LEVEL:	**WVWZZZ3HZNE001530**
Fuel type:		Power:	**115 kW**
Version:	**1.4 EHYBRID DSG ELEGANCE**	First registration	**07/10/2021**
Mileage:	**145516 km**	Number of doors:	


Summary of damages

Back	2
Before	1
Interior	4
Roof & other	1

Commercial photos






























Options according to the inspector

GPS	**Yes**

Damages


Bodywork

Damaged -

Acceptable.


Roof & other

























MACADAM


BDC-191



MACADAM

MACADAM

MACADAM

MACADAM

MACADAM



MACADAM


MACADAM


MACADAM



Ignition key
not working (well)
Acceptable
Interior



Ventilation grille. AR M
Broken
E - Replace
Interior





Damaged **Interior**
- Acceptable
Interior












Tire repair kit missing. Check rear.



Windshield Chip
(s)
Windshield Repair
Front




Rear bumper,
claw(s)
, paint
the rear












AVG Smart Repair
Hole **Floor Mats** Interior




Tires

Front Left
Winter
Aluminum
245/45/18/100/V
Uniroyal
3.0 mm

Front Right
Winter
Aluminum
245/45/18/100/V
Uniroyal
3.0 mm

Left Back
Winter
Aluminum
245/45/18/100/V
Dunlop
4.0 mm

Rear Right
Winter
Aluminum
245/45/18/100/V
Dunlop
4.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**No**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**P/A**	Vehicle inspection	**NOT OK**
Interview	**OK**	Interview	**over 2300 km**
Repair kit	**P/A**	Number of charging cables (220V)	**1**
Number of charging cables (fast charging)	**1**	Total number of keys	**3**
Charge level	**90**	Factory reset	**Yes, the vehicle has been reset to factory settings.**
Type of maintenance log	**Digital interview**		

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.