ARVAL
BNP PARIBAS GROUP

2CKX205

INSPECTION REPORT

End of contract

GENERAL INFO

File	322209
License plate	2CKX205
Vehicle identification number	JHMRT6880NX205337
Dossier	2022125016
Make	Honda CR-V 2.0 135kW Execut.4W
Mileage	91650
First registration	30/08/2022
client availability date	16/09/2026
inspectionDate	24/09/2026










CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	




B
2 CKX 205
HONDA
BELCAR


DAMAGES

Damages	Type	Acceptable
187	Wing Rear Right / Trim / Replace	N
196	Door Rear Right // Polish	N
197	Door Rear Right / Trim / Replace	N
13	Bumper Front // Painting	Y
31	Front Bonnet // Smart Repair Small	Y
71	Side View Mirror Left // Plastic Repair	Y
86	Door Front Left // Polish	Y
100	Door Rear Left // Smart Repair Small	N
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
156	Rear Bonnet // Polish	Y
181	Wing Rear Right // Smart Repair Medium	Y
216	Door Front Right // Polish	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	Y
532	Trunk Compartment / Side Cover Left / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures




Wing Rear Right // Smart Repair Medium-scratch





Wheel Two Tone Rear Right // Repair-scratch




Trunk Compartment / Side Cover Left / Replace-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Rear Bonnet // Polish-scratch




Bumper Rear / Lower Cover Not Painted / Replace-scratch




Door Front Right // Polish-scratch




Wheel Two Tone Front Right // Repair-scratch





Bumper Front // Painting-scratch




Wheel Two Tone Rear Left // Repair-scratch




Door Front Left // Polish-scratch

Front Bonnet // Smart Repair Small-dent





Bumper Rear // Painting-scratch + dent




Door Rear Left // Smart Repair Small-scratch + dent




Side View Mirror Left // Plastic Repair-cracked




Door Rear Right // Polish-scratch






Door Rear Right / Trim / Replace-scratch




Wing Rear Right / Trim / Replace-scratch