TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48368195
Order No. / Reference: 27132412
Inspection date: 27 Oct 2026

Manufacturer: Audi	Model: Q4 e-tron 40 Sportback
VIN: WAUZZZFZ4PP073605	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi Q4 e-tron 40 Sportback	
Vehicle Identification number	WAUZZZFZ4PP073605
Mileage (Read)	79,750 km
First registration	10 Aug 2023
Number of holders	1
Next periodical technical inspection	08/2028
(Report on hand)	
Fuel type	Electric
Power	70 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	SUV
Colour / colour code	Mythosschwarz Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	10 Monat(e)
Last service on / at	08/2025 at 53,215 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV278779
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BZT 00054		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,625 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R20 100T	Summer tyres on Light alloy	Bridgestone	5mm / 5mm
2)	255/45 R20 101T	Summer tyres on Light alloy	Bridgestone	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 106H	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	235/55 R19 106H	Winter tyres on Light alloy	Goodyear	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- Acoustic vehicle warning system
- Anti-lock braking system (ABS)
- Audi connect Remote & Control for MMI plus and pro
- Audi pre sense front
- Electrically adjustable/heated exterior mirrors
- third brake light
- Decorative inlay, black tactile lacquer
- Rear parking sensors
- Chassis: Comfort chassis
- Luggage compartment lid, electrically opening and closing without sensor-controlled luggage compartment release
- rear window wiper
- Interior mirror dimming
- Automatic air conditioning
- Comfort center armrest in front
- Combo 2 charging socket (EU)
- LED taillights
- Steering wheel: Double-spoke leather steering wheel with multifunction
- On-board charger up to 11 kW (AC)
- Upholstery: Fabric Index
- Radio: MMI Radio
- Seats: Standard front seats
- Seats: Front seats manually adjustable
- Stationary air conditioning
- First aid kit with warning triangle
- Electronic immobilizer
- Central locking
- Airbag: Front side airbags, with head airbag and front interaction airbag
- Audi connect emergency call and service
- Audi drive select
- Evasive steering assist and turning assist
- Vehicle tool kit
- Fabric headliner
- Tachometer
- Electronic Stability Control (ESC)
- front and rear floor mats
- Speed limiter with preparation for adaptive cruise control
- Transmission: 1-speed direct drive
- Interior lighting
- i-Size child seat anchors on the front passenger side, i-Size and Top Tether anchors on the outer rear seats
- Headrests (5)
- Mode 3 charging cable for public charging
- LED headlights
- Light and rain sensor
- Model name and performance/technology lettering
- Package: Gloss Package
- Wheel: Tire pressure monitoring system
- Power steering
- Seats: Rear seat backrest foldable
- Lane Departure Warning
- 12-volt socket
- Camera-based traffic sign recognition
- Green thermal insulation glazing

Extra equipment

- Deletion of performance/technology lettering
- Paint finish: Metallic
- Paintwork: Full paintwork
- LED headlights: Matrix LED headlights (The Matrix LED headlights with digital light signatures, dynamic light styling and dynamic turn signals. Front and rear LED headlights with the following functionalities: - digital daytime running light signature (4 light signatures selectable when stationary) - low beam - high beam - position light - dynamic turn signal - cornering light - all-weather light - maneuvering light - motorway light - automatic dynamic headlight range control. LED taillights)
- Navigation: MMI Navigation plus (11.6-inch MMI Navigation plus with MMI touch including Audi connect Navigation & Infotainment - camera-based traffic sign recognition - 10.25-inch Audi virtual cockpit with two display options "Classic" and "Sport" - voice control)
- Package: Climate Control Package (The 3-zone automatic climate control electronically regulates the air temperature, volume, and distribution. An additional function is the sun-position-dependent control. The temperature settings for the driver and front passenger sides can be adjusted separately. Separate temperature control and air vents are available in the rear. The 3-zone automatic climate control features automatic recirculation in combination with a dust- and odor-removing cabin air filter. The comfort stationary climate control cools or heats the interior.)
- Package: Black Optics Package (Sportback) (black accents in the area of the Audi Singleframe grille - black accents in the area of the front and rear bumpers - black trim strips on the side windows)
- Package: S line exterior (S line bumpers with bottom line all around in contrasting paint finish Manhattan Grey Metallic - Wheels, 5-Y-spoke, 8.0 J / 9.0 J x 20, tires 235/50 / 255/45 R 20 - S line exterior differentiations with S line emblem on the fenders - Sport suspension)
- Radio accessories: Audi sound system (8 speakers including center speaker and subwoofer, 6-channel amplifier with a total output of 180 watts)
- Headlight cleaning system (Provides more light on the road, especially in adverse weather conditions. Cleaning with water and high pressure creates better luminosity and good visibility due to reduced scattering.)
- Glazing: Sun protection glazing, tinted (rear window, door and rear side windows tinted)
- Chassis: Sport chassis (The sport chassis, with a 15 mm lower ride height compared to the standard chassis and more dynamic spring and damper tuning, uses a McPherson strut axle with lower wishbones, shock absorbers, coil springs, subframe and stabilizer bar at the front. At the rear, a 4-link axle with separate spring and damper arrangement, shock absorbers, coil springs, subframe and stabilizer bar is used.)
- Steering wheel: Double-spoke leather sports steering wheel, flattened at the top and bottom, with multifunction controls and paddle shifters (The double-spoke leather sports steering wheel, flattened at the top and bottom, impresses with its sporty look and feels good in the hand. The height and reach of the steering wheel are manually adjustable.)
- Package: Advanced Assistance Package (Adaptive Cruise Control with predictive control (the set speed of the adaptive cruise control is additionally adjusted to detected speed limits and the road ahead) - Parking Aid Plus, supports the driver when parking and maneuvering forwards and backwards with acoustic signals and visual display - Adaptive Driving Assistant supports acceleration, braking, maintaining speed and distance, and lane keeping)
- Package: Comfort package (electrically adjustable, heated and folding exterior mirrors, automatically dimming on both sides, with integrated LED turn signals and curb view function for the passenger-side exterior mirror, aspherical mirror glass on the left, convex on the right, including heated windshield washer nozzles - automatically dimming, frameless interior mirror - 4-way lumbar support for the front seats - projection lights in the exterior mirrors)
- Wheel: Audi new car tire warranty (36-month term from vehicle handover to the first customer)
- Wheels: Light alloy wheels (4 pieces) in 5-Y-spoke design (front size: 8.0 J x 20 with 235/50 R 20 tires, rear size: 9.0 J x 20 with 255/45 R 20 mobility tires)
- Reversing camera (image display of the area behind the vehicle on the MMI display).
- Front seat heating (heats seat and backrest center section (standard seats in fabric), otherwise seat and backrest center section as well as seat side bolsters - individually adjustable in 3 stages for driver and front passenger via direct selection button on the climate control unit)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - Smart repair
2	Boot lid / rear door	Rear spoiler - Scratch(es) - Smart repair
3	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
4	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value

Wear and tear

No.	Component group	Description
1	Door - front right side	Door edge - Scratch(es) - No deduction
2	Side panel - rear right side	Side panel - Scratch(es) - No deduction
3	Door - rear left side	Door - Scratch(es) - No deduction
4	Front bumper	Front bumper - Stone chips - No deduction
5	Sill - left side	Sill - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig und eingeschränkt möglich.
- Mehrkosten möglich .



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Documents



Figure 17: Additional tyres



Figure 18: Navigation



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.




Figure 34: Misc.




Figure 35: Misc.




Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Boot lid / rear door: Rear spoiler - Scratch(es) - Smart repair




Damage 2: Boot lid / rear door: Rear spoiler - Scratch(es) - Smart repair



Damage 2: Boot lid / rear door: Rear spoiler - Scratch(es) - Smart repair



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value