TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48421286
Order No. / Reference: 27206527
Inspection date: 27 Oct 2026

Manufacturer: Ford	Model: Transit 310 L2H2 Lkw VA Trend
VIN: WF0XXXTTGXKK53799	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit 310 L2H2 Lkw VA Trend	
Vehicle Identification number	WF0XXXTTGXKK53799
Mileage (Read)	88,305 km
First registration	25 Jul 2019
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	77 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Polar-Silber Metallic
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	Available / incomplete	**Next maintenance in**	
Last service on / at	10/2021 at 27,153 km		
Key is / should be	1 / 4	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FH921183
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BNF 03640		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,140 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 109R	Winter tyres on Steel	Continental	5mm / 5mm
2)	215/65 R16 109R	Winter tyres on Steel	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R15 104T	Summer tyres on Steel rim with wheel cover	Semperit	6mm / 6mm
2)	215/65 R15 104T	Summer tyres on Steel rim with wheel cover	Bridgestone	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	215/65 R15 104T	Summer tyres on Steel	Bridgestone	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- roof, middle
- Double-leaf rear door with 180° opening angle (without window)
- Front electric windows
- Ford Easy Fuel
- Cruise control including leather steering wheel
- Grab handle on the B-pillar of the passenger side
- Front air conditioning
- Cargo area floor: Vinyl floor covering "Easy Clean" including wheel arch lining
- Fog light
- Particulate filter: diesel particulate filter
- Wheels: Tire repair kit
- Headlights with static cornering lights
- Sliding door entry light automatically illuminates when the door is opened
- Side protection strips
- Power steering
- Rear bumper with integrated step
- Partition to the cargo area without window
- Immobiliser
- Central locking with remote control
- Second key with remote control
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- On-board computer
- Headliner in driver's cab
- Tachometer
- Electronic Stability Program (ESP) with Traction Control (TSC)
- Generator, 200 A
- Transmission: 6-speed transmission
- Interior lighting with delay circuit
- Cargo area lighting
- leather steering wheel
- Steering column, adjustable in height and reach
- Front and rear parking pilot system
- Wheels: Wheel trims
- Wheels: Steel wheels 6.5 J x 15 with 215/65 R 15 tires
- Headlights with delayed shut-off
- Sliding door: Sliding door, right
- Rear mud flaps
- Low side paneling
- Seat belts
- Daytime running light
- Lashing eyes
- Heat-insulating glazing, lightly tinted
- Auxiliary heater, electric

Extra equipment

- 2 batteries
- Paint finish: Metallic
- Wheels/Tires: Spare wheel, steel wheel
- Seats: Seat Package 15 (Driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - Double passenger seat with storage compartment under individually foldable seat cushions - Height-adjustable headrests - Integrated (fold-out) tray in the double passenger seat - Heated driver's seat - Heated passenger seat - Interior armrest for driver - Manual lumbar support (driver's seat) - Seat upholstery: fabric)
- Parking heater package 1 (parking heater (fuel-operated auxiliary heater), programmable, incl. remote control)
- 3rd and 4th master keys
- Radio: Audio system 15: Ford navigation system including Ford SYNC 3 with AppLink and touchscreen (16.5 cm screen diagonal - radio, MP3-compatible, dual tuner, DAB/DAB+, speed-dependent volume control, audio remote control on the steering wheel, 4 front speakers, USB port, AUX input - voice control - Bluetooth and USB interface - hands-free system - SMS readout/send function - Bluetooth audio streaming - emergency call assist - SD card slot - acoustic and visual route guidance - TMCpro - detailed visualization (3D display) - Michelin travel guide for Europe)
- Steel rear step

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Bonnet	Bonnet (wird erneuert) - Corrosion - Repair and paint
2	Misc.	Inspection / maintenance - No evidence - No deduction
3	Braking system	Brake fluid - No evidence - No deduction
4	Documents	Service book - Incomplete - No deduction
5	Sliding door, right	Sliding door - Scratch(es) - Smart repair
6	Boot lid / rear door	Rear door - right side - Scratch(es) - Paint
7	Boot lid / rear door	Rear door - left side - Scratch(es) - Paint
8	Door - front right side	Door - Scratch(es) - Paint
9	Body	Body - Damage by hail - Repair

Wear and tear

No.	Component group	Description
1	Side panel - rear left side	Side panel - Abrasion - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Vehicle key (2-4)

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Servicerestlauf nicht anzeigbar

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster




Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Damage 1: Bonnet: Bonnet (wird erneuert) - Corrosion - Repair and paint



Damage 1: Bonnet: Bonnet (wird erneuert) - Corrosion - Repair and paint



Damage 5: Sliding door, right: Sliding door - Scratch(es) - Smart repair



Damage 5: Sliding door, right: Sliding door - Scratch(es) - Smart repair



Damage 5: Sliding door, right: Sliding door - Scratch(es) - Smart repair



Damage 6: Boot lid / rear door: Rear door - right side - Scratch(es) - Paint




Damage 6: Boot lid / rear door: Rear door - right side - Scratch(es) - Paint



Damage 6: Boot lid / rear door: Rear door - right side - Scratch(es) - Paint



Damage 6: Boot lid / rear door: Rear door - right side - Scratch(es) - Paint



Damage 6: Boot lid / rear door: Rear door - right side - Scratch(es) - Paint



Damage 7: Boot lid / rear door: Rear door - left side - Scratch(es) - Paint



Damage 7: Boot lid / rear door: Rear door - left side - Scratch(es) - Paint



Damage 7: Boot lid / rear door: Rear door - left side - Scratch(es) - Paint



Damage 7: Boot lid / rear door: Rear door - left side - Scratch(es) - Paint



Damage 7: Boot lid / rear door: Rear door - left side - Scratch(es) - Paint



Damage 8: Door - front right side: Door - Scratch(es) - Paint



Damage 8: Door - front right side: Door - Scratch(es) - Paint



Damage 8: Door - front right side: Door - Scratch(es) - Paint



Damage 8: Door - front right side: Door - Scratch(es) - Paint




Damage 8: Door - front right side: Door - Scratch(es) - Paint



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair




Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair




Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair




Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Missing part 1: Equipment: Vehicle key (2-4) - Missing - Replace