TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48510994
Order No. / Reference: 26989984-1
Inspection date: 21 Oct 2026

Manufacturer: Ford	Model: Transit 350 L2H2 Lkw VA Trend Kasten
VIN: WF0EXXTTREPE30304	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit 350 L2H2 Lkw VA Trend Kasten	
Vehicle Identification number	WF0EXXTTREPE30304
Mileage (Read)	37,983 km
First registration	26 Oct 2023
Number of holders	1
Next periodical technical inspection	11/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	125 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frozen White
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Anthracite-Grey
Re-import	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	30,000 km
Last service on / at	02/2026 at 30,706 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GX203768
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / BNI 09698		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 113R	Winter tyres on Light alloy	Bridgestone	6mm / 6mm
2)	235/65 R16 113R	Winter tyres on Light alloy	Bridgestone	8mm / 8mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- Exterior mirrors, electrically adjustable and heated
- Battery: Battery life, programming of battery life to 10 minutes
- On-board computer (with fuel consumption and mileage information (e.g. remaining range) as well as outside temperature display and Ford ECO mode)
- Tachometer
- Third brake light
- Front electric windows (with quickdown/up function for driver's side)
- Ford Easy Fuel (comfortable fuel filler cap and misfuelling protection)
- Generator, high-performance version
- Lockable glove compartment with lid
- Front air conditioning (including dust and pollen filter)
- Fuel tank 70 l
- Cargo area lighting
- Steering column, adjustable in height and reach
- Fog light
- Emergency brake assist including emergency brake light
- Package: Technology Package 9 (Heated windscreen - Rain-sensing wipers - Front and rear parking sensors - Active emergency braking assist (camera-based) - Lane Keeping Assist with Driver Alert and High Beam Assist; additionally with Lane Departure Warning - Automatic Headlights with Day/Night Sensor - Cruise Control - Fog Lights - Ford Audio System)
- Wheels: Wheel trims
- Wheels: Steel wheels 6.5 J x 16 with 235/65 R 16 tires
- Sliding door: Sliding door, right
- Rear mud flaps
- Power steering
- Seat belts (front seat belt tensioners and force limiters)
- Seats: Seat package 13 (driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - double passenger seat with storage compartment under individually foldable seat cushions - height-adjustable headrests - integrated tray in the double passenger seat (foldable) - interior armrest for driver - manual lumbar support (driver's seat) - seat cover: fabric)
- Heat-insulating glazing, lightly tinted
- Second key with remote control
- Driver's side airbag
- Anti-lock braking system with electronic brake-force distribution (EBD) including (Electronic Safety and Stability Program (ESP) with Traction Control System (TCS) - Hill Start Assist - Crosswind Assist - Safety Brake Assist - Rollover Protection - Emergency Brake Support including emergency brake light)
- roof, middle
- Double-leaf rear door with 180° opening angle (without window)
- Electronic Stability Program (ESP) with Traction Control System (TCS) (Hill Start Assist - Crosswind Assist - Emergency Brake Assist - Rollover Protection)
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Transmission: 6-speed transmission
- Interior lighting with delay function (with reading lights at the front)
- Paint finish: Solid color paint
- Steering wheel: Faux leather steering wheel
- MyKey key system (individually programmable secondary key)
- Emergency call assistant
- Particulate filter: diesel particulate filter
- Radio: Ford audio system with radio and DAB+ (Radio (FM/AM) - Digital radio reception DAB/DAB+ (Digital Audio Broadcasting) - MyFord Dock - FordPass Connect - Speakers, antenna - Audio remote control on steering wheel - Bluetooth interface - USB port - Hands-free system)
- Wheels: Tire repair kit
- Sliding door entry light automatically illuminates when the door is opened
- Side protection strips
- Seat belts (front seat belt tensioners and force limiters - warning system for unfastened driver's seat belt)
- Start-stop system
- Rear bumper with integrated step
- Daytime running light
- Partition wall (plastic) at the height of the B-pillar
- recirculation mode
- Lashing eyes
- Immobiliser
- Central locking with remote control
- Front overhead storage compartment

Extra equipment

- Fixed towbar (13-pin including trailer sway control (TSC))
- Battery: Extended battery life, battery life can be programmed to 30 minutes
- Navigation system (dynamic and cloud-based navigation with road map for Western Europe - including automatic climate control - Ford audio system with 12" multifunction display and Ford SYNC 4 - Bluetooth, hands-free system with voice control - music playback with voice control - integration of storage media (USB, MP3 player) - FordPass Connect including Wi-Fi hotspot, control of selected functions with the FordPass app - Emergency call assistant - Ford Power-Up - AppLink, Android Auto, Apple CarPlay - touchscreen)
- Package: Service Line (Sobogrip mounting base - Sowaflex wall cladding - shelving systems (left and right) - shelves with various boxes - drawers - case fixing incl. impact plate - floor rail - gas cylinder holder - perforated aluminum sheet - multi-console - foldable workbench, incl. parallel vise 120 and turntable - floor vent - roof vent - partition wall (plastic))
- Seats: Seat Package 15 (Driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - Double passenger seat with storage compartment under individually foldable seat cushions - Height-adjustable headrests - Integrated (fold-out) tray in the double passenger seat - Heated driver's seat - Heated passenger seat - Interior armrest for driver - Manual lumbar support (driver's seat) - Seat upholstery: fabric)
- Electrically folding exterior mirrors (with integrated turn signals)
- LED exterior light mounted high, downlight, rear
- Navigation system in conjunction with Technology Package 13 (dynamic and cloud-based navigation with traffic information, lane guidance and road map for Western Europe - including automatic climate control - Ford audio system with 12" multifunction display and Ford SYNC 4 - Bluetooth, hands-free system with voice control - music playback with voice control - integration of storage media (USB, MP3 player) - FordPass Connect including Wi-Fi hotspot, control of selected functions via the FordPass app - Emergency call assist - Ford Power-Up, Android Auto, Apple CarPlay - touchscreen)
- Package: Technology Package 13 (Heated windscreen, wipers with rain sensor - Front and rear parking sensors, plus side sensors, active radar-based emergency braking assist) - Lane Keeping Assist with Driver Alert and High Beam Assist; plus Lane Keeping Assist and Lane Change Assist - Headlight Assist with day/night sensor - Blind Spot Assist, adaptive cruise control, reversing camera - LED downlights, fog lights - Electrically adjustable, folding, and heated exterior mirrors - Automatic climate control - Ford audio system with 12" multifunction display and Ford SYNC 4
- Xenon: Bi-xenon headlights with static cornering lights, LED daytime running lights (including automatic headlight range control)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Door - front right side	Door - Dent / paintcoat damage - Smart repair
2	Sliding door, right	Sliding door - dent(s) - Smooth repair work
3	Seat - front	Seat cover - left side - Burn hole (cigarettes) - Loss in value
4	Indicator - front	Mirror - right side - Broken / torn - Replace
5	Boot lid / rear door	Rear door - left side - Dent / paintcoat damage - Loss in value
6	Bonnet	Insulation lining (Verschimmelt) - Soiled - Replace
7	Front bumper	Front bumper - dent(s) - Replace

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Rear bumper	Rear bumper - Scratch(es) - No deduction
3	Wheel / tyres	Wheel rims - complete set (WR LM statt SR Stahl) - Differs from the original configuration - No deduction
4	Interior	Cargo space partition (Sortimo Regalsystem) - Differs from the original configuration - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Für den montierten Radsatz wurde kein Nachweis erbracht.

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.





Figure 28: Misc.



Damage 1: Door - front right side: Door - Dent / paintcoat damage - Smart repair




Damage 1: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 2: Sliding door, right: Sliding door - dent(s) - Smooth repair work




Damage 2: Sliding door, right: Sliding door - dent(s) - Smooth repair work



Damage 3: Seat - front: Seat cover - left side - Burn hole (cigarettes) - Loss in value



Damage 3: Seat - front: Seat cover - left side - Burn hole (cigarettes) - Loss in value




Damage 4: Indicator - front: Mirror - right side - Broken / torn - Replace



Damage 4: Indicator - front: Mirror - right side - Broken / torn - Replace



Damage 5: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Loss in value



Damage 5: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Loss in value



Damage 5: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Loss in value



Damage 6: Bonnet: Insulation lining (Verschimmelt) - Soiled - Replace



Damage 7: Front bumper: Front bumper - dent(s) - Replace



Damage 7: Front bumper: Front bumper - dent(s) - Replace

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Wear and tear 1: Vehicle glazing: Windscreen - Stone chips - No deduction