TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48449409
Order No. / Reference: 27216691
Inspection date: 2 Nov 2026

Manufacturer: Volkswagen	Model: T-Roc 2.0 TDI SCR DSG R-Line
VIN: WVGZZZA1ZNV134344	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen T-Roc 2.0 TDI SCR DSG R-Line	
Vehicle Identification number	WVGZZZA1ZNV134344
Mileage (Read)	186,723 km
First registration	25 Aug 2022
Number of holders	2
Next periodical technical inspection	08/2027
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Indiumgrau Metallic/Dach in Deep Black Pearl
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	8,100 km
Last service on / at	05/2026 at 171,370 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM668422
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CFP 00367		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,960 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R19 99Y	Summer tyres on Light alloy	Bridgestone	4mm / 4mm
2)	225/40 R19 99Y	Summer tyres on Light alloy	Bridgestone	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 04/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger, with front passenger airbag deactivation
- white ambient lighting
- Electrically adjustable, folding, and heated exterior mirrors with memory function
- Vehicle tool kit
- Black headliner
- Decorative inlays “Lava Stone Black”
- Digital cockpit, multi-colored, various selectable information profiles
- Electronic parking brake including auto-hold function
- Automatic headlight control, with LED daytime running lights
- Electric windows front and rear
- Windscreen made of laminated safety glass, heat-insulating
- Transmission: 7-speed DSG
- Rear window heated
- Interior mirror automatically dimming
- Air conditioning with active combination filter
- Front headrests
- Steering wheel: Multifunction sports steering wheel in leather, with touch controls and paddle shifters
- front center armrest
- Non-smoking version
- Emergency call service
- Package: Winter Package
- Brushed stainless steel pedals
- Progressive steering
- Rain sensor
- Wheels: Light alloy (4) "Valencia" 7 J x 17, Galvano Grey
- LED taillights, dark red
- Drawer under the right front seat
- Seats: Front passenger seat backrest folds down completely
- Seats: Rear seat backrest asymmetrically split and foldable with center armrest
- Lane keeping assistant “Lane Assist”
- Telephone interface
- Ambient lighting with logo projection
- Prepared for "We Connect" and "We Connect Plus"
- Electronic immobilizer
- Green thermal insulation glazing, sides and rear
- Airbag: Head airbag system for front and rear passengers including front side airbags
- Adaptive Cruise Control (ACC) "stop & go" including speed limiter
- Hill start assist
- third brake light
- Silver anodized roof rails
- Diesel particulate filter
- Tachometer
- Front door sill trims with "R-Line" logo
- Electronic Stability Program with counter-steering support
- Driving profile selection
- Chassis: Sport chassis
- High beam control "Light Assist"
- Pedestrian detection
- Luggage compartment floor height-adjustable and removable
- Rear window wiper with intermittent function
- ISOFIX mounting points
- Rear headrests (3)
- LED Plus headlights
- Light in the front footwell
- Illuminated makeup mirrors in the sun visors
- Fatigue detection
- Emergency braking assistant "Front Assist"
- Package: Seat Comfort Package
- Park Assist system including parking aid
- Upholstery: Fabric inner side panels in "ArtVelours"
- Radio “Ready 2 Discover” incl. “Streaming & Internet”
- Tire pressure monitoring system
- Wheels: Tire Mobility Set
- Gearshift knob in leather
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
- Seats: Lumbar support in the front
- Seats: Sport comfort seats in the front
- Seats: Front seats with height adjustment
- Start-stop system with brake energy recuperation
- Textile floor mats front and rear
- First aid kit, warning triangle and high-visibility vest
- Prepared for later activation: Navigation function "Discover Media" incl. "Streaming & Internet"
- Central locking without safe locking, with remote control and 2 remote keys

Extra equipment

- Air conditioning system "Air Care Climatronic" (with active combination filter and 2-zone temperature control)
- Package: "Easy Open & Close" with safe locking ("Easy Open & Close" - tailgate with sensor-controlled opening and closing, with remote unlocking - anti-theft alarm system with interior monitoring, backup horn and tow-away protection - keyless locking and starting system "Keyless Access" with safe locking)
- Package: "IQ.Drive" assistance package including "IQ.LIGHT" (DSG) (Dynamic Light Assist high beam control - Travel Assist, Lane Assist and Emergency Assist - IQ.LIGHT - LED matrix headlights with LED daytime running lights - LED taillights with dynamic turn signals - Illuminated strip between the headlights - Proactive occupant protection system in conjunction with Front Assist and Side Assist - Side Assist lane change assist)
- Paint finish: Metallic, different roof color
- Panoramic tilt/slide sunroof with panoramic roof at the rear
- Rear View reversing camera
- Seats: Top sports seats in the front (passenger seat backrest not foldable)
- Steering wheel: Multifunction sports steering wheel in leather, heated, with touch controls and paddle shifters
- Towing device (removable and lockable towing device - height-adjustable and removable luggage compartment floor)
- Wheels: Alloy (4) "Misano" 8 J x 19 in black (wheel locks with enhanced theft protection - tires 225/40 R 19)
- "Comfort" telephone interface with inductive charging function (operation and display via multifunction display and touchscreen of the radio or radio navigation system as well as via multifunction steering wheel - hands-free system - Bluetooth audio - external antenna connection with LTE support)
- Chassis: Adaptive chassis control DCC (incl. driving profile selection - progressive steering)
- Display: Digital Cockpit Pro, multicolor, various selectable info profiles
- Navigation system "Discover Pro" incl. "Streaming & Internet" (6 speakers - App-Connect Wireless for Apple CarPlay - 23.4 cm touchscreen - FM radio reception - Dual tuner with phase diversity for optimal radio reception - Navigation system "Discover Pro" incl. "Streaming & Internet" - Radio Data System (RDS) - Radio station logos - Radio - Digital radio reception DAB+ - MP3 playback - USB-C interface - Output power 4 x 20 watts - Map with 2D display - Voice control - Traffic sign recognition)
- Package: Design package "Black Style" (R-Line) (Black - Exterior mirrors painted in contrasting color - Chrome applications on light switch, mirror adjustment switch, window regulator switch; air vents with black frames - Black roof rails - "Lava Stone Black" decorative inlays for instrument panel, center console and front door panels - Carbon-look foil wrapping on the C-pillars - Wheel locks with enhanced anti-theft protection - Darkened rear side windows and rear window - Black trim strips)
- Voice control

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Mudguard - left side	Mudguard - left side - dent(s) - Smooth repair work
2	Wheel / tyres	Alloy rim - rear left side - Scratched - Loss in value
3	Wheel / tyres	Alloy rim - rear right side - Scratched - Loss in value
4	Wheel / tyres	Alloy rim - front left side - Scratched - Loss in value
5	Wheel / tyres	Tyre - front right side - Damaged - Replace
6	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint
7	Door - rear right side	Door - Scratch(es) - Paint
8	Wheel / tyres	Alloy rim - front right side - Scratched - Replace
9	Rear bumper	Rear bumper - Dent / paintcoat damage - Repair and paint
10	Door - front left side	Door - Scratch(es) - Paint
11	Bonnet	Bonnet (Mehrere) - Stone chips - Paint
12	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Repair and paint

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: VIN



Figure 13: Mounted tyres




Figure 14: Documents




Figure 15: Documents




Figure 16: Navigation




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.




Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.




Figure 41: Misc.



Damage 1: Mudguard - left side: Mudguard - left side - dent(s) - Smooth repair work



Damage 1: Mudguard - left side: Mudguard - left side - dent(s) - Smooth repair work



Damage 2: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value




Damage 5: Wheel / tyres: Tyre - front right side - Damaged - Replace



Damage 5: Wheel / tyres: Tyre - front right side - Damaged - Replace



Damage 5: Wheel / tyres: Tyre - front right side - Damaged - Replace



Damage 6: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 6: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 6: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 6: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 6: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 7: Door - rear right side: Door - Scratch(es) - Paint



Damage 7: Door - rear right side: Door - Scratch(es) - Paint



Damage 7: Door - rear right side: Door - Scratch(es) - Paint



Damage 7: Door - rear right side: Door - Scratch(es) - Paint



Damage 7: Door - rear right side: Door - Scratch(es) - Paint



Damage 7: Door - rear right side: Door - Scratch(es) - Paint



Damage 8: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - front right side - Scratched - Replace




Damage 9: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 9: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 9: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 9: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 9: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 9: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 9: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 9: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 9: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 9: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 9: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 10: Door - front left side: Door - Scratch(es) - Paint



Damage 10: Door - front left side: Door - Scratch(es) - Paint



Damage 10: Door - front left side: Door - Scratch(es) - Paint




Damage 10: Door - front left side: Door - Scratch(es) - Paint




Damage 10: Door - front left side: Door - Scratch(es) - Paint



Damage 10: Door - front left side: Door - Scratch(es) - Paint



Damage 11: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 11: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 11: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 11: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 11: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 11: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 11: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint




Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint