Macadam Austria GmbH
Europaplatz 2/1/2
1150 Wien

Inspection location
Lagermax - AT - Straßwalchen
Lagermax Str. 1
5204 Straßwalchen

Inspection date: 5 Oct 2026
Protocol number: **47919350**

WBY31AW070FN49438

Vehicle details

Operator		**Inspection condition**	sufficient
License number		**Mileage (Read)**	11,101 km
Manufacturer	BMW	**Next maintenance in**	6 Monat(e)
Type / Model	i4 xDrive M50	**Main inspection (Report not on hand)**	08/2027
Vehicle Identification number	WBY31AW070FN49438	**Power**	350 kW
First registration	24 Aug 2022	**Upholstery/Colour**	Alcantara / Leather / Black
Last maintenance	04/2025, 9,057 km	**Paintwork**	Blue
Fuel type	Electric	**Gearbox**	Direct drive

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door - Scratch(es) - Smart repair
2	Wheel / tyres	Alloy rim - rear right side - Scratched - Repair
3	Wheel / tyres	Alloy rim - front right side - Scratched - Repair

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction

Missing parts

Missing part
Wheel / tyres - Wheel lock

Detected repainting

No.	Location
1	Bumper rear, Bumper front

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	255/35 R20	Pirelli	Summer tyres	5mm - 5mm	Not o.k.	
2	285/30 R20	Pirelli	Summer tyres	5mm - 5mm	Not o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Standard equipment

Code	Description
-	12V power outlet
-	2-year warranty
-	3-zone automatic climate control
-	AC charging
-	Airbag for driver and front passenger
-	Ambient lighting
-	Anti-lock braking system (ABS)
-	Attention assistant
-	Automatic start-stop function
-	Automatic tailgate operation
-	Battery thermal management for optimized DC fast charging
-	BMW Controller
-	BMW ID
-	BMW Live Cockpit Plus
-	BMW M 50 Years Emblems
-	BMW xDrive
-	Bumper system
-	Center lock switch
-	Central locking system including 2 remote controls
-	Centre console - rear
-	Crash sensor
-	Cruise control with braking function
-	cup holder
-	DAB tuner
-	DC charging
-	Door sills
-	Driving experience switch
-	Dynamic Stability Control (DSC) with extended features
-	Electric drive unit
-	electric window regulators
-	Electrically adjustable and heated exterior mirrors
-	Electromechanical parking brake with automatic hold function
-	Electronic immobilizer (EWS)
-	Fund seats
-	glove box
-	Hands-free device with USB interface
-	Head airbags for the 1st and 2nd rows of seats
-	Headlight range control
-	Heat/sun protection glazing
-	HiFi speaker system

Code	Description
-	High-voltage battery
-	Home lights
-	Interior and exterior mirror package
-	Interior lighting
-	ISOFIX child seat attachment
-	Lashing eyes in the luggage compartment
-	LED headlights
-	LED license plate lights
-	LED taillights
-	Loading flap
-	luggage compartment light
-	M headliner anthracite
-	M High Gloss Shadow Line
-	M interior trim strips Aluminium Rhombicle Anthracite, 18" M Aerodynamic wheels 858 M Bicolor with mixed tires
-	M rear spoiler
-	M Sport brakes
-	M steering wheel
-	Model lettering
-	Multifunction for steering wheel
-	Parking Assistant
-	Passenger airbag deactivation
-	Rain sensor
-	Rear view camera
-	recuperation system
-	Servotronic
-	Side airbag for driver and front passenger
-	Speed Limiter
-	Standard seat for driver and passenger
-	Start/Stop button
-	Stationary air conditioning
-	Steering column adjustment
-	Stereo speaker system with 6 speakers
-	Storage options
-	through-loading system
-	Tire pressure monitoring
-	Tire Pressure Monitoring System (RPA)
-	Tool set
-	Vehicle key
-	Velour floor mats
-	Warning triangle with first aid kit
-	Welcome light
-	Widescreen Display

Extra equipment

Code	Description
04U9	Acoustic pedestrian protection
05AQ	Active Guard Plus
08TF	Active pedestrian protection
02VF	Adaptive M suspension
A050	AGM battery 50 Ah
0302	Alarm system
04UR	Ambient interior lighting
0775	Anthracite headliner
0534	Automatic air conditioning
0491	Backrest width adjustment driver
04V1	BMW ICONICSOUNDS ELECTRIC
05AZ	BMW Laserlight
06U3	BMW Live Cockpit Professional
03FW	BMW LM wheel double spoke 868M STD HP
03MQ	BMW M HERITAGE LOGOS
01CB	CO2 scope
0322	Comfort access
06AK	Connected Drive Services
06C4	Connected Package Professional
0654	DAB tuner (DAB+ capable)
08TR	Decoding additional functions
05AU	Driving Assistant Professional
0459	Electric seat adjustment with memory
032X	Elimination of touchless operation of rear door panel.
0230	EU-specific additional scopes
0851	German language version
0688	Harman/Kardon surround sound system
0494	Heated seats for driver and passenger
05AC	High beam assist
0760	High-gloss Shadow Line
06VB	Infotainment controls
04LN	INT. PERFORMS. ALU. RHOMBICLE ANTHR.
0431	Interior mirror automatically dimming
0430	Interior/exterior mirrors with automatic dimming
06AF	Legal emergency number
0487	Lumbar support for driver
0715	M Aerodynamics Package
071C	M Exterior Package Carbon
03MF	M Leuchten Shadow Line
04GQ	M safety belts
07M9	M Shadow Line with extended scope
03M2	M Sport brakes, high-gloss red

Code	Description
033B	M SPORT PACKAGE PRO
033T	M technology package
0548	odometer
0879	Onboard literature in German
05DM	Parking assistance system
05DA	Passenger airbag deactivation
08R9	Refrigerant R1234yf
04AW	Sensatec instrument panel
01CX	SPORT BOOST
0493	Storage package
06NX	Storage tray wireless charging
06AE	Teleservices
0420	tinted glazing
02VB	Tire pressure gauge
02VC	Tyre repair kit
02VL	Variable sport steering
0428	Warning triangle and first aid kit
02PA	Wheel bolt lock

Comments

Dieses Gutachten wurden in Verantwortung von Ing. Martin Lennes, allgemein beeideter und gerichtlich zertifizierter Sachverständiger, erstellt.

Die o.a. Serienausstattung des Fahrzeuges basiert auf Angaben der Firma Eurotax und Macadam Austria übernimmt daher für deren Inhalt keine Haftung.

Die o.a. Sonderausstattung des Fahrzeuges stammt aus dem BMW System Myair und Macadam Austria übernimmt daher für deren Inhalt keine Haftung.

Macadam Austria GmbH
Europaplatz 2/1/2
1150 Wien

Inspection location
Lagermax - AT - Straßwalchen
Lagermax Str. 1
5204 Straßwalchen

Inspection date: 5 Oct 2026
Protocol number: **47919350**

Vehicle details

Manufacturer	BMW	**Inspection condition**	sufficient
Type / Model	i4 xDrive M50	**Mileage (Read)**	11,101 km
Vehicle Identification number	WBY31AW070FN49438	**First registration**	24 Aug 2022

Details of the order:
In accordance with the contract, the evaluation of vehicle's condition was performed without the vehicle being disassembled.

This product is based on the Austrian standard ÖNORM V5080. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on their own expertise.

Vehicle identification:
The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.

Inspection conditions:
The inspection conditions were sufficient for the assessment of the vehicle.

General condition:
The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior




Figure 6: Interior



Figure 7: Interior



Figure 8: Interior




Figure 9: Interior




Figure 10: Interior




Figure 11: Interior




Figure 12: Interior




Figure 13: Interior




Figure 14: Interior



Figure 15: Misc.




Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.


Pictures of damage




Damage Door - front left side: Door - front left side: Door - Scratch(es) - Smart repair



Damage Door - front left side: Door - front left side: Door - Scratch(es) - Smart repair



Damage Door - front left side: Door - front left side: Door - Scratch(es) - Smart repair



Damage Wheel / tyres: Wheel / tyres: Alloy rim - rear right side - Scratched - Repair




Damage Wheel / tyres: Wheel / tyres: Alloy rim - rear right side - Scratched - Repair



Damage Wheel / tyres: Wheel / tyres: Alloy rim - rear right side - Scratched - Repair



Damage Wheel / tyres: Wheel / tyres: Alloy rim - rear right side - Scratched - Repair



Damage Wheel / tyres: Wheel / tyres: Alloy rim - rear right side - Scratched - Repair



Damage Wheel / tyres: Wheel / tyres: Alloy rim - front right side - Scratched - Repair



Damage Wheel / tyres: Wheel / tyres: Alloy rim - front right side - Scratched - Repair