TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 48541185
Order No. / Reference: 27235410
Inspection date: 5 Nov 2026

Manufacturer: Ford	Model: Ranger DoKa LKW XLT 2.0L EcoBlue
VIN: 6FPPXXMJ2PNM47890	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Ranger DoKa LKW XLT 2.0L EcoBlue	
Vehicle Identification number	6FPPXXMJ2PNM47890
Mileage (Read)	73,294 km
First registration	15 Feb 2023
Number of holders	1
Next periodical technical inspection	03/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,996 ccm / 4
Power	125 kW
Gearbox / Number of gears	Manual / 6
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Silber-Metallic
Doors / Seats	4 / 5
Upholstery type	Cloth
Colour of upholstery	Black
Re-import	no
readiness to drive	Roadworthy

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	
Last service on / at	06/2025 at 41,390 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP476568
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	1566 / AAL 00149		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,270 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/70 R16 111T	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	255/70 R16 111T	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	265/65 R17 112T	Winter tyres on Light alloy	Continental	7mm / 7mm
2)	265/65 R17 112T	Winter tyres on Light alloy	Continental	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	255/70 R16 111T	Summer tyres on Steel	Continental	9 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS
- Airbag: Front and side airbag system for driver and front passenger
- All-wheel drive (switchable four-wheel drive)
- Exterior mirror housings in chrome finish
- On-board computer
- Tachometer
- ESP (Electronic Stability Program)
- Electric front windows
- Floor mats: Driver's side floor mat, textile
- Cruise control
- Transmission: 6-speed transmission
- tailgate lock
- rear window wiper
- Isofix mount
- Front headrests (2)
- Load support with protective frame at the rear of the cabin
- Centre console
- Package: Cargo space 5
- Package: Rear seat 11
- Package: Seat 47
- Upholstery: Cloth
- Tire pressure monitoring system
- Rear mud flaps
- Electro-mechanical power steering
- Power outlet: 12-volt connection, one connection in the rear.
- Door handles in chrome finish
- Lashing eyes
- Central/double locking with remote control
- Airbag: Passenger airbag deactivation function
- Airbag: Driver's knee airbag
- Airbag: Head airbags, above the side windows
- Exterior mirrors, electrically adjustable and heated
- Flooring: Carpet
- Differential open
- Third brake light
- Electric rear windows
- Heated windshield
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Grab handle, driver and passenger side
- Heated rear window
- Interior mirror automatically dimming
- Air conditioning
- Cargo area protection tray
- Leather gear knob
- Fog light
- Package: Wheel 5 (Light alloy wheels 7J x 16 with 255/70 R 16 - 6-spoke Y-design, black - Spare wheel steel wheel)
- Particulate filter: Diesel particulate filter (DPF)
- Radio: Audio system 61: CD audio system incl. Ford SYNC
- Windscreen wipers with rain sensor
- Plastic side sill protectors
- Start-stop system
- Front bumper in body color
- Daytime running light
- Rear underride guard, black
- Immobiliser

Extra equipment

- Digital tachograph - preparation (gearbox plug)
- Package: Cargo space 4 (hardtop)
- Package: XLT-3 (Heated driver and passenger seats - Rear parking pilot system - Rear bumper)
- Paint finish: Metallic
- Parking heater, programmable, with remote control
- Towbar (13-pin - 90° tailgate opening angle - lane keeping assist)
- Radio: Audio system 129: Audio system including Ford SYNC 3 with AppLink and touchscreen (additionally with Ford Navi 8" TFT multifunction color display (20.3 cm screen) with touchscreen radio (FM/AM), DAB, FordPass Connect, multifunction leather steering wheel, USB port, Bluetooth interface, 6 speakers, 12-volt socket in the rear, air conditioning with automatic temperature control, acoustic and visual route guidance, dynamic navigation with enhanced traffic information system (TCMpro), lane guidance, road map for Europe (integrated memory))

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Engine	Hose turbocharger (Ölspuren erkennbar) - Soiled - Diagnosed and repair if necessary
2	Engine	Engine cover - top / cover (Marderspuren) - Damaged - Replace
3	Side panel - rear left side	Side panel - Scratch(es) - Smart repair
4	Bonnet	Insulation lining - Broken / torn - Replace
5	Rear bumper	Cover - bumper - rear (Chrom) - dent(s) - Replace
6	Braking system	Brake discs and brake pads - front - Corrosion - Replace

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Es wird kein Service Restlauf angezeigt.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Additional tyres




Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.




Figure 34: Misc.



Damage 1: Engine: Hose turbocharger (Ölspuren erkennbar) - Soiled - Diagnosed and repair if necessary



Damage 1: Engine: Hose turbocharger (Ölspuren erkennbar) - Soiled - Diagnosed and repair if necessary



Damage 1: Engine: Hose turbocharger (Ölspuren erkennbar) - Soiled - Diagnosed and repair if necessary



Damage 1: Engine: Hose turbocharger (Ölspuren erkennbar) - Soiled - Diagnosed and repair if necessary



Damage 2: Engine: Engine cover - top / cover (Marderspuren) - Damaged - Replace



Damage 2: Engine: Engine cover - top / cover (Marderspuren) - Damaged - Replace



Damage 3: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 4: Bonnet: Insulation lining - Broken / torn - Replace



Damage 4: Bonnet: Insulation lining - Broken / torn - Replace



Damage 5: Rear bumper: Cover - bumper - rear (Chrom) - dent(s) - Replace



Damage 5: Rear bumper: Cover - bumper - rear (Chrom) - dent(s) - Replace



Damage 5: Rear bumper: Cover - bumper - rear (Chrom) - dent(s) - Replace



Damage 6: Braking system: Brake discs and brake pads - front - Corrosion - Replace



Damage 6: Braking system: Brake discs and brake pads - front - Corrosion - Replace



Damage 6: Braking system: Brake discs and brake pads - front - Corrosion - Replace



Damage 6: Braking system: Brake discs and brake pads - front - Corrosion - Replace



Damage 6: Braking system: Brake discs and brake pads - front - Corrosion - Replace



Damage 6: Braking system: Brake discs and brake pads - front - Corrosion - Replace