ARVAL
BNP PARIBAS GROUP

1XTF326

INSPECTION REPORT

End of contract

GENERAL INFO

File	322692
License plate	1XTF326
Vehicle identification number	WF0JXXGAHJLA80071
Dossier	2020036153
Make	Ford Fiesta 1.5TDCi 63 ST-Line
Mileage	138012
First registration	14/05/2020
client availability date	28/09/2026
inspectionDate	15/10/2026











CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
184	Wing Rear Right // Repair & Painting	N
194	Door Rear Right // Repair & Painting	N
209	Rocker Panel Right / Cover / Replace	N
891	Lettering Removal 15min	N
13	Bumper Front // Painting	N
35	Front Bonnet // Polish	Y
80	Door Front Left // Smart Repair Small	Y
133	Bumper Rear // Painting	Y
165	Roof // Polish	Y
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N


Damage Pictures

Front Bonnet // Polish-scratch





Roof // Polish-Chemical reaction





Wheel Alloy Front Right // Repair-scratch





Wheel Alloy Rear Right // Repair-scratch





Wheel Alloy Rear Left // Repair-scratch




Door Front Left // Smart Repair Small-scratch







Bumper Front // Painting-scratch








Bumper Rear // Painting-scratch





Rocker Panel Right / Cover / Replace-scratch



Door Rear Right // Repair & Painting-scratch + dent





Wing Rear Right // Repair & Painting-scratch + dent



Lettering Removal 15min-Remainder stickers