MACADAM








Seat Ateca (UKL): 2BPA644

Vinnumber:	**VSSZZZ5FZN6515690**	Versionname:	**Ateca Move! 1.0TSi 110pk/cv 5p**
First Registrationdate:	**1/02/2022**	Fiscalpower:	
Expertise Mileage:	**78827**	Power Kw:	**81**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**NOT OK**		
Maintenance	**uit te voeren**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**215/55/17/98 W**			
	Fr.L.	**Firestone: 4 mm**	Fr.R.	**Firestone: 4 mm**
	Re.L.	**Goodyear: 4 mm**	Re.R.	**Goodyear: 4 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**215/55 R 17 98 W**
Tyre size FR	**215/55 R 17 98 W**
Tyre size RL	**215/55 R 17 94 V**
Tyre size RR	**215/55 R 17 94 V**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**258**
Tyre make FR	**258**
Tyre make RL	**259**
Tyre make RR	**259**


Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**


Service, Maintenance, Check



Interior, Dirty, Cleaning



Bonnet, Repaired, Check



Bumper F, Scratch(es), Acceptable



Step L, Scratch(es), Acceptable



Step L, Scratch(es), Acceptable



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)





Outside rear-view mirror housing L, Scratch(es), Acceptable




Outside rear-view mirror base L, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable






Outer door handle FL, Scratch(es), Acceptable




Luggage compartment cover, Broken, Forfeit






Tailgate / Boot, Scratch(es), Acceptable




Step R, Scratch(es), Acceptable




Step R, Dent(s), Acceptable




Door RR, Scratch(es), Acceptable








Outside rear-view mirror housing R, Scratch(es), Acceptable




Alloy rim FR, Scratch(es), Repair and paint (complete)






Bodywork, Not original part, Remove lettering



Roof, Chemical polution, Repair and paint (complete)




Onderhoudshistorie van: VSSZZZ5FZN6515690

ALPHABET

Kenteken	2BPA644
Merk Model	Seat Ateca Move! 1.0TSi 110pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	2/1/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
9/30/25	63,738	diagnose	Uitvoeren
9/30/25	63,738	klein materiaal	
9/30/25	63,738	remblokken achter	Vervangen
9/30/25	63,738	remblokken vooraan	Vervangen
11/27/24	48,300	0139-Aanvulling op onderhoudsbeurt	Uitvoeren
11/27/24	48,300	klein materiaal	
11/27/24	48,300	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
11/27/24	48,300	remvloeistof	Vervangen
11/27/24	48,300	ruitenwisserrubber achter	Vervangen
11/27/24	48,300	ruitenwisserrubber vooraan	Vervangen
11/27/24	48,300	ruitenwisservloeistof	Vervangen
9/30/24	46,635	controle niveaus	Uitvoeren
9/30/24	46,635	olie bijvullen	Bijvullen/-laden
9/30/24	46,635	ruitenwisservloeistof	Bijvullen/-laden
2/1/24	33,139	klein materiaal	Uitvoeren
2/1/24	33,139	luchtfilter interieur	Vervangen
2/1/24	33,139	Onderhoudsbeurt (variabel interval)	Uitvoeren
8/16/23	25,535	batterij	Vervangen
8/16/23	25,535	klein materiaal	Uitvoeren
8/16/23	25,535	ruitenwisserrubber achter	Vervangen
8/16/23	25,535	ruitenwisserrubber vooraan	Vervangen
8/16/23	25,535	Tussentijdse onderhoudsbeurt (variabel	Uitvoeren
3/16/23	18,241	controle niveaus	Uitvoeren
3/16/23	18,241	klein materiaal	Uitvoeren
3/16/23	18,241	olie bijvullen	Bijvullen/-laden
3/16/23	18,241	ruitenwisservloeistof	Bijvullen/-laden