TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48603431
Order No. / Reference: 27223376
Inspection date: 10 Nov 2026

Manufacturer: Volkswagen	Model: Multivan T7 Kurz
VIN: WV2ZZZST7RH029021	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Multivan T7 Kurz	
Vehicle Identification number	WV2ZZZST7RH029021
Mileage (Read)	101,881 km
First registration	16 Sept 2024
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Multipurpose vehicle
Colour / colour code	Pure Grey
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Grey
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	17,700 km
Last service on / at	07/2026 at 89,590 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HD636859
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CQJ 00508		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,850 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 102H	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	215/65 R16 102H	Winter tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 102H	Summer tyres on Steel rim with wheel cover	Continental	5mm / 5mm
2)	215/65 R16 102H	Summer tyres on Steel rim with wheel cover	Continental	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Distraction and fatigue detection
- Airbag: Side and head airbags for driver and front passenger (head airbags for the outer rear seats - center airbag in the front)
- Exterior mirror housings in high-gloss black
- On-board tools and tire mobility set (in the storage compartments in the luggage compartment)
- Parking assistance in the front and rear areas
- Deletion: No seats in the 3rd row.
- Chassis: Suspension and damping, standard
- Window in the sliding door, left
- Windows: Front pane made of laminated safety glass, heat and sound insulating
- Transmission: DSG (dual-clutch transmission), 7-speed automatic
- Tailgate closing without interior unlocking function
- Instrument cluster (km/h) (displays for speed, total/trip distance, engine speed, fuel level and time)
- Headrests (5)
- LED headlights with LED daytime running lights
- Strip between the headlights painted in glossy black
- Headlight range control
- Multifunction display: Digital Cockpit
- Non-smoking version
- eCall emergency call system
- Without Mode 3 charging cable
- Radio: "Ready 2 Discover" with 25.4 cm (10 inch) color touchscreen including "Streaming & Internet"
- Radio: Digital radio reception
- Wheel covers
- Wheels/Tires: 4 steel wheels 6.5 J x 16
- Wheels/Tires: Tire pressure monitoring system
- Sliding door in the passenger/cargo compartment: sliding door on the left
- Plastic lock carrier cover
- Keys for locking system: 2 vehicle keys
- Seat belt monitoring system (warning tone and light for unfastened seat belts front and rear)
- Seats in the passenger compartment: 3 individual seats facing forward in the 2nd row.
- Sun visors with mirrors, ticket holder on the driver's side (airbag label on the sun visor and B-pillar on the passenger side)
- Telephone: Mobile phone interface
- First aid kit, warning triangle and high-visibility vest
- Prepared for online services
- Preparation Alcohol Interlock
- Electronic immobilizer
- Central locking with keyless start system "Keyless Start" without safe locking
- Airbag for driver and front passenger (with passenger airbag deactivation)
- Anti-lock braking system
- Evasive steering assist and turn assist
- Reinforced battery (68 Ah/ 380 A)
- third brake light
- Decorative inlays: Decorative inlays "Scale Light Grey"
- Electronic Stability Program (ESP)
- Chassis: 16" chassis with 16" disc brakes at the front and 16" disc brakes at the rear
- Window in the sliding door, right
- Electric windows, front
- Cruise control
- Glove compartment without light
- Boot lid
- Rear window with wiper/washer system, heated
- Intelligent Speed Assist including speed limiter
- Air conditioning with manual control
- Fuel-powered auxiliary heater
- LED taillights
- Steering wheel: Multifunction leather steering wheel with paddle shifters
- Multimedia systems: 2 USB-C ports on the front
- Emergency braking assistant "Front Assist" (with pedestrian and cyclist detection)
- Particulate filter: Soot particle filter for diesel engines
- Radio: App-Connect incl. App-Connect Wireless (for Apple CarPlay and Android Auto)
- Radio accessories: 8 speakers (passive)
- Wheels/Tires: 215/65 R 16 102 H XL, optimized for low rolling resistance
- Windscreen wiper interval control, 4-stage adjustable (for the front windscreen wipers)
- Sliding door in the passenger/cargo compartment: sliding door on the right
- Speed-sensitive power steering (Servotronic)
- dimmable interior safety mirror
- Seat covers: Bi-color fabric seat covers, "Bright Dots" design
- Seats: Left and right seats in the 1st row (with height adjustment - including 2-way headrest)
- Lane keeping assistant “Lane Assist”
- Daytime running lights with cornering lights
- Traction control
- Traffic sign recognition
- Prepared for VW Connect and VW Connect Plus (Prepared for online services)
- Green thermal insulation glazing

Extra equipment

- Windows (glass type in the cargo/passenger compartment) - rear windows tinted
- Drawers under the outer seats in the passenger compartment and 2 waste bins
- Heated seats for the driver's cab, left and right, separately adjustable
- Navigation system "Discover Pro" (25.4 cm (10 inch) color touchscreen - streaming & internet)
- Seats: Armrests for driver and front passenger seats, on both sides (with electric lumbar support and folding table)
- Partitions: Mesh partition

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Bonnet	Bonnet - Dent / paintcoat damage - Smart repair
2	Rear bumper	Rear bumper - Scratch(es) - Smart repair
3	Side panel - rear right side	Sill - Dent / paintcoat damage - Smart repair
4	Sliding door - left side	Sliding door - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Tirefit complete
Equipment - Vehicle tool kit

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Winter - Radsatz ist kein Bestandteil des Lieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument cluster



Figure 9: Instrument panel

Figure 10: Interior 360° view (Online Link)



Figure 11: Cargo area



Figure 12: VIN



Figure 13: Mounted tyres




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Additional tyres



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Damage 1: Bonnet: Bonnet - Dent / paintcoat damage - Smart repair



Damage 1: Bonnet: Bonnet - Dent / paintcoat damage - Smart repair



Damage 1: Bonnet: Bonnet - Dent / paintcoat damage - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 3: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 3: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 3: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair




Damage 4: Sliding door - left side: Sliding door - Dent / paintcoat damage - Repair and paint




Damage 4: Sliding door - left side: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 4: Sliding door - left side: Sliding door - Dent / paintcoat damage - Repair and paint



Missing part 1: Equipment: Tirefit complete - Missing - Replace



Missing part 2: Equipment: Vehicle tool kit - Missing - Replace