TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48182645
Order No. / Reference: 27006866
Inspection date: 15 Oct 2026

Manufacturer: Volkswagen	Model: Caddy 2.0 TDI BMT DSG Life Maxi
VIN: WV2ZZZSKZNX001387	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Caddy 2.0 TDI BMT DSG Life Maxi	
Vehicle Identification number	WV2ZZZSKZNX001387
Mileage (Read)	179,858 km
First registration	3 Jan 2022
Number of holders	1
Next periodical technical inspection (Report on hand)	04/2027
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	90 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Candy-Weiß
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	4,300 km
Last service on / at	11/2025 at 156,883 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GF285888
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	0603 / CLH 00185		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,300 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98V	Winter tyres on Light alloy	Dunlop	4mm / 4mm
2)	215/55 R17 98V	Winter tyres on Light alloy	Dunlop	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98H	Summer tyres on Light alloy	Hankook	3mm / 3mm
2)	215/55 R17 98H	Summer tyres on Light alloy	Hankook	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- Klimaautomatik

Standard equipment

- Waste container with removable lid
- Storage compartments: Storage tray on the headliner with 2 roof grab handles in the driver's cab
- Airbag: Side and head airbags for driver and front passenger
- Reinforced battery (70 Ah/ 420 A)
- Operating voltage 12 V
- Brake booster
- third brake light
- Three-phase generator 140 A
- Electronic parking brake including auto-hold function
- Automatic headlight control with daytime running lights
- Window: Side window in the passenger/cargo compartment, rear left, permanently installed
- Window: Side window in the passenger/cargo compartment, front left, permanently installed
- Windows: Laminated glass front pane in heat-insulating glazing
- Luggage compartment cover, foldable and removable
- Transmission: DSG (dual-clutch transmission), 7-speed automatic
- Rear window wiper/washer system with intermittent function
- Electric child safety lock for sliding doors
- Folding tables on the backrests of the seats in the first row.
- Paint finish: Solid (Candy White)
- Steering wheel: Multifunction steering wheel in leather (DSG)
- front center armrest
- Multi-collision brake
- Non-smoking version
- eCall emergency call system
- Upholstery: Fabric, "Trialog" design
- Radio accessories: Digital radio reception DAB+
- Wheels, tires: Covers for alloy wheels
- Wheels/Tires: "Barahona" alloy wheels 6.5 J x 17, in brilliant silver
- Wheels: Tire Mobility Set
- Gearshift lever DSG
- Sliding door, left side in the passenger/cargo area
- Keys for locking system: 2 remote control flip keys
- Side indicator lights
- Seat belts: Three-point automatic seat belts
- dimmable interior safety mirror
- Seats in the driver's cab: Backrest release for the right front seat
- Seats in the passenger compartment: 3-seater bench in the 2nd row (foldable, rollable and removable)
- Seats: Seat left and right, in the 1st row
- Sun visors with mirrors, airbag label on passenger sun visor
- Power outlets: 12-volt socket in the cargo area
- Telephone: Mobile phone interface
- Lashing points: 6 lashing points for securing cargo
- Electronic immobilizer
- Registration as a truck
- Additional dust protection seal on the outside
- Storage and stowage boxes
- Towing eye front and rear, screw-in
- Airbag for driver and front passenger
- Exterior mirrors, electrically adjustable, heated and folding
- Exterior mirror housings in black, door handles in body color and sliding door rail in silver
- Floor coverings, carpeting in the driver's cab and passenger compartment
- Roof rails, black
- Electrical interface for external use
- Electronic Stability Program with Brake Assist
- Windows: Heated rear window
- Window: Side window in the passenger/cargo compartment, rear right, permanently installed
- Window: Side window in the passenger/cargo compartment, front right, permanently installed
- Windows: Green heat-insulating glass
- electric window regulators
- Cruise control system including speed limiter
- Glove compartment with lid, illuminated
- Tailgate with window cutout
- Interior lighting: in the passenger compartment
- Instrument usage (km/h)
- Child seat anchorage (I-Size) and top tether
- Headrests (2), height adjustable
- Paint protection/transport protection film
- Steering column adjustable in height and tilt
- Headlight range control
- Multifunctional camera
- Fatigue detection
- Emergency braking assistant "Front Assist"
- Particulate filter: Soot particle filter for diesel engines
- "Composition Audio" radio with 20.96 cm (8.25 inch) color touchscreen
- Wheels/Tires: 215/55 R 17 98 H XL, optimized for low rolling resistance
- Wheels/Tires: Tire pressure monitoring system
- reversing light
- Windscreen wiper intermittent control with light sensor
- Sliding door, on the right in the passenger/cargo area
- Side paneling for comfort in the passenger compartment
- Speed-sensitive power steering (Servotronic)
- Seat belts: in the passenger compartment
- Driver's cab seats: Height adjustment for both front seats, manual
- Seats in the driver's cab: Lumbar support manually adjustable, left and right
- Seats: Folding tables on the backrests of the seats in the 1st row.
- Lane keeping assistant “Lane Assist”
- Start-stop system
- Bumpers in body color

- First aid kit, warning triangle and high-visibility vest
- Warning tone and light for unfastened front seat belts
- Central locking with remote control and interior operation
- Auxiliary heating: Electric auxiliary air heater

Extra equipment

- Rigid towbar (including trailer stabilization)
- Parking assistance (parking distance control, front and rear)
- Windows: Front side windows in heat-insulating glass (rear side windows and rear window tinted, 74% light-absorbing)
- Interior lighting: in the passenger compartment (LED reading lights - LED tailgate lighting)
- Air conditioning system "Air Care Climatronic" with 2-zone temperature control and air purification function
- Fuel fill quantity, higher initial fill (10 l)
- Multifunction display: Digital cockpit, multicolor, various information profiles selectable
- Navigation system "Discover Media" (Life, Move, Style) (25.4 cm (10 inch) color touchscreen - streaming & internet)
- Seats in the driver's cab: AGR ergoComfort seat, left (Life, Move, Style) (drawer under the right front seat - front seats height-adjustable, seat cushion tilt and depth adjustment for left seat - 4-way electrically adjustable lumbar support left and manually adjustable lumbar support right)
- Lane change assistant "Side Assist" including "Blind Spot Detection" and parking assistant
- Telephone: Mobile phone interface "Comfort" (with inductive charging function)
- Central locking with keyless start system "Keyless Start" without safe locking
- Adaptive Cruise Control (ACC) including speed limiter (DSG) (Multifunction camera - Leather multifunction steering wheel with shift paddles - Evasive steering assist and turn assist - "Front Assist" emergency braking assistant with pedestrian and cyclist detection - Adaptive Cruise Control (ACC), including speed limiter - with Follow to Stop)
- Child seat anchorage (I-Size) and Top Tether (for seats in the passenger compartment (except middle seat of the 2nd row) plus I-Size front passenger side)
- LED headlights with LED daytime running lights
- Multimedia systems: App-Connect (including App-Connect Wireless for Apple CarPlay)
- Package: Winter package (Seat heating for seats in the driver's cab, left and right, separately adjustable - Washer fluid level indicator with enlarged washer fluid reservoir - Heated windshield washer nozzles at the front)
- Seats: Deletion of the 3rd row of seats and deletion of seat preparation (3-seater bench in the 2nd row (foldable, rollable and removable), ISOFIX and Top Tether on outer seats in the 2nd row)
- 12-volt sockets in the instrument panel and in the cargo area
- Partition net: Luggage net in the cargo/passenger compartment

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work
3	Body	Underbody panelling - Broken / torn - Replace
4	Body	Body - Glued / labelled - De-glue / neutralise
5	Instrument panel	Instrument cluster - Electrical fault - Perform diagnosis
6	Engine	Engine (Kostenerweiterung möglich) - Electrical fault - Perform diagnosis
7	Braking system	Parking brake / hand brake (Kostenerweiterung möglich) - Electrical fault - Perform diagnosis
8	Sill - right side	Sill - Scratched - Repair
9	Rear bumper	Rear bumper - Scratched - Repair and paint
10	Vehicle glazing	Windscreen (Rissbildung) - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Trim / covers	Boot lining - Scratch(es) - No deduction
2	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction
3	Side panel - rear left side	Side panel - Scratch(es) - No deduction
4	Bonnet	Bonnet - Dent / paintcoat damage - No deduction
5	Door - rear right side	Door handle - outside - Scratch(es) - No deduction
6	Door - front right side	Door - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.

- Für den montierten Radsatz wurde kein Nachweis erbracht.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.





Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace




Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work




Damage 3: Body: Underbody panelling - Broken / torn - Replace



Damage 3: Body: Underbody panelling - Broken / torn - Replace



Damage 3: Body: Underbody panelling - Broken / torn - Replace



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Instrument panel: Instrument cluster - Electrical fault - Perform diagnosis



Damage 6: Engine: Engine (Kostenerweiterung möglich) - Electrical fault - Perform diagnosis



Damage 7: Braking system: Parking brake / hand brake (Kostenerweiterung möglich) - Electrical fault - Perform diagnosis



Damage 8: Sill - right side: Sill - Scratched - Repair



Damage 8: Sill - right side: Sill - Scratched - Repair



Damage 9: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 9: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 9: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 9: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 10: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



Damage 10: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace