# MACADAM
# Volkswagen ID.4 '21 BEV

## Vehicle information

| | | | |
|---|---|---|---|
| Make: | **Volkswagen** | License: | |
| Gearbox: | **Automatic** | Body color: | |
| Model: | **ID.4 '21 BEV** | VIN: | **WVGZZZE2ZNP008775** |
| Fuel type: | **Electric** | Power: | **150 kW** |
| Version: | **ID.4 77kWh Business** | First registration | **15/10/2021** |
| Mileage: | **83157 km** | N° of doors: | |

## Damage summary


| | |
|---|---|
| **Front** | 1 |
| **Right** | 2 |
| **Roof & others** | 1 |

## Commercial pictures














Noodoproepfunctie is beperkt.
Werkplaats opzoeken, alstublieft.
D / B
PARK
N
R
83157 km
76 %
344 km




WVGZZZE2ZNP008775
















Let op omgeving en kaar om te rennen!




Batterijcertificaat
Datum van diagnose: 19/10/2026
94,03%
Status van de gezondheid (SOH)*
Volkswagen ID4
VIN : WVGZZZE2ZNP008775
Kilometerstand : 83.157 km
*SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie
Raadpleeg het Moba-certificaat door deze QR-code te scannen
Meer weten over:
www.get-moba.com
CARA




## Options according to the inspector


| | | | | | |
|---|---|---|---|---|---|
| Central consol F | **Yes** | GPS | **Yes** | Headlights Xenon/LED/Laser | **Yes** |
| Hook | **Yes** | Radio multimedia | **Yes** | Rear view camera | **Yes** |
| Telephone equipment | **Yes** | | | | |

## Damages


**Bonnet**
Chemical polution
Repair and paint (complete)
Front





**Door FR**
Scratch(es)
Repair and paint (complete)
Right

**Door RR**
Scratch(es)
Repair and paint (complete)
Right

**Roof**
Chemical polution
Repair and paint (complete)
Roof & others

## Tyres

| |
|---|
| **Front Left** |
| Summer |
| 235/55/19/101/T |
| Hankook |
| 5.1 mm |
| **Front Right** |
| Summer |
| 235/55/19/101/T |
| Hankook |
| 5.2 mm |
| **Rear Left** |
| Summer |
| 235/55/19/101/T |
| Hankook |
| 4.2 mm |
| **Rear Right** |
| Summer |
| 235/55/19/101/T |
| Hankook |
| 4.4 mm |

## Checks

| | | | |
|---|---|---|---|
| CO2 Emission | **0** | Digital maintenance | **Yes** |
| GPS storage | **Yes** | Luggage cover | **Yes** |
| Number head rests | **5** | Number of charging cables (rapid charge) | **1** |
| Number of keys total | **2** | Reset to factory settings | **Yes, vehicle is reset to factory settings** |
| Service book | **N/A** | User's manual | **Yes** |

### Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.