Macadam Austria GmbH
Europaplatz 2/1/2
1150 Wien

Inspection location
Lagermax - AT - Straßwalchen
Lagermax Str. 1
5204 Straßwalchen

Inspection date: 18 Sept 2026
Protocol number: **47666591**

WBA51GN0905060511

Vehicle details

Operator		**Inspection condition**	sufficient
License number		**Mileage (Read)**	45,994 km
Manufacturer	BMW	**Next maintenance in**	15,000 km
Type / Model	X2 xDrive20d	**Main inspection (Report not on hand)**	08/2027
Vehicle Identification number	WBA51GN0905060511	**Power**	110 kW
Engine displacement	1,995 ccm	**Cylinder**	—
First registration	22 Aug 2024	**Upholstery/Colour**	Cloth / Black
Last maintenance	08/2026, 45,123 km	**Paintwork**	Grey
Fuel type	Diesel	**Gearbox**	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Door - rear right side	Door (1 S auf Kante) - dent(s) - Smooth repair work
2	Side panel - rear right side	Side panel (1 S Auf kante) - dent(s) - Smooth repair work
3	Door - front right side	Door (2 M eine auf Kante) - dent(s) - Smooth repair work
4	2nd wheel set	1 tyre - Damaged - Replace

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Tyre - front right side (Winter Profil unter 5,5mm) - No deduction
2	Door - front left side	Door - Dent / paintcoat damage - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
1	Bumper rear

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/65 R17	Pirelli	Winter tyres	5mm - 5mm	o.k.	
2	205/65 R17	Pirelli	Winter tyres	6mm - 6mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/55 R18	Bridgestone	Summer tyres	6mm - 6mm	o.k.	
2	225/55 R18	Bridgestone	Summer tyres	6mm - 6mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Standard equipment

Code	Description
-	2-year warranty
-	Airbags
-	Attention assistant
-	Automatic air conditioning
-	Automatic tailgate operation
-	BMW iDrive
-	BMW Live Cockpit Plus
-	BMW xDrive
-	Central locking system
-	Central locking with remote control
-	Condition Based Service
-	Cruise control with braking function
-	DAB tuner
-	Diesel particulate filter
-	Efficiency improvement and emission reduction
-	electric window regulator
-	Exterior features
-	i-Size child seat attachment for front passenger
-	Interior features
-	Interior trim strips, quartz silver, matt grained
-	Larger fuel tank, 18" alloy wheels, star spoke 865
-	M High Gloss Shadow Line
-	Outdoor lighting
-	Parking Assistant
-	Performance Control
-	Power socket
-	Power steering
-	Security systems
-	Solid color paint
-	speaker system
-	Speed Limiter
-	Standard steering wheel
-	Standard suspension
-	Steptronic transmission with dual clutch
-	Tire pressure monitoring
-	Traction control
-	Upholstery fabric 'Arktur'
-	Visual function
-	Warning triangle with first aid kit

Extra equipment

Code	Description
03KA	Acoustic comfort glazing
05AV	Active Guard
08TF	Active pedestrian protection
0552	Adaptive LED headlights
A060	AGM battery 60 Ah
0302	Alarm system
01EA	BMW LM wheel star spoke 865 STD
0478	Child seat attachment
01CB	CO2 scope
08R3	COC ADDITIONAL PACKAGES
0322	Comfort access
02TM	Control Gear type
0654	DAB tuner (DAB+ capable)
0320	Deletion of model designation
07EV	Equipment package
0230	EU-specific additional scopes
01DF	EU6 rde II emissions standard
0313	Exterior mirror folding function
0851	German language version
0494	Heated seats for driver and passenger
05AC	High beam assist
0760	High-gloss Shadow Line
0431	Interior mirror automatically dimming
04GN	Interior trim strips quartz silver matt
0430	Interior/exterior mirrors with automatic dimming
01AG	Larger fuel tank
06AF	Legal emergency number
0548	odometer
08KA	Oil change interval: 24 months/30,000 km
0879	Onboard literature in German
05DM	Parking assistance system
06PA	Personal eSIM
09QV	Preparation Driving Assistant Plus
01CE	recuperation system
08R9	Refrigerant R1234yf
02TF	Steptronic with dual-clutch transmission
06NX	Storage tray wireless charging
06AE	Teleservices
02VB	Tire pressure gauge
02VC	Tyre repair kit
0428	Warning triangle and first aid kit

Comments

Dieses Gutachten wurden in Verantwortung von Ing. Martin Lennes, allgemein beeideter und gerichtlich zertifizierter Sachverständiger, erstellt.

Die o.a. Serienausstattung des Fahrzeuges basiert auf Angaben der Firma Eurotax und Macadam Austria übernimmt daher für deren Inhalt keine Haftung.

Die o.a. Sonderausstattung des Fahrzeuges stammt aus dem BMW System Myair und Macadam Austria übernimmt daher für deren Inhalt keine Haftung.

Vehicle details

Manufacturer	BMW	**Inspection condition**	sufficient
Type / Model	X2 xDrive20d	**Mileage (Read)**	45,994 km
Vehicle Identification number	WBA51GN0905060511	**First registration**	22 Aug 2024

Details of the order:
In accordance with the contract, the evaluation of vehicle's condition was performed without the vehicle being disassembled.

This product is based on the Austrian standard ÖNORM V5080. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on their own expertise.

Vehicle identification:
The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.

Inspection conditions:
The inspection conditions were sufficient for the assessment of the vehicle.

General condition:
The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear




Figure 5: Interior




Figure 6: Interior




Figure 7: Interior




Figure 8: Interior




Figure 9: Interior




Figure 10: Interior




Figure 11: Interior




Figure 12: Interior



Figure 13: Interior




Figure 14: Interior




Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.

Pictures of damage



Damage Door - rear right side: Door - rear right side: Door (1 S auf Kante) - dent(s) - Smooth repair work




Damage Door - rear right side: Door - rear right side: Door (1 S auf Kante) - dent(s) - Smooth repair work



Damage Side panel - rear right side: Side panel - rear right side: Side panel (1 S Auf kante) - dent(s) - Smooth repair work




Damage Side panel - rear right side: Side panel - rear right side: Side panel (1 S Auf kante) - dent(s) - Smooth repair work



Damage Door - front right side: Door - front right side: Door (2 M eine auf Kante) - dent(s) - Smooth repair work



Damage Door - front right side: Door - front right side: Door (2 M eine auf Kante) - dent(s) - Smooth repair work



Damage Door - front right side: Door - front right side: Door (2 M eine auf Kante) - dent(s) - Smooth repair work



Damage Door - front right side: Door - front right side: Door (2 M eine auf Kante) - dent(s) - Smooth repair work



Damage 2nd wheel set: 2nd wheel set: 1 tyre - Damaged - Replace



Damage 2nd wheel set: 2nd wheel set: 1 tyre - Damaged - Replace