TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 47996022
Order No. / Reference: 27130903
Inspection date: 7 Oct 2026

Manufacturer: Mercedes-Benz	Model: A 250 e 8G-DCT Progressive Advanced
VIN: W1K3F8FBXPN316625	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz A 250 e 8G-DCT Progressive Advanced	
Vehicle Identification number	W1K3F8FBXPN316625
Mileage (Read)	52,524 km
First registration	19 Jul 2023
Number of holders	1
Next periodical technical inspection	07/2026
(Report not on hand)	
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,332 ccm / 4
Power	120 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Mountaingrau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black
Re-import	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	286 Tag(e)
Last service on / at	06/2026 at 51,868 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV695749
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	2222 / BKN 00003		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,170 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91W	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	205/55 R17 91W	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91H	Winter tyres on Light alloy	Hankook	5mm / 5mm
2)	205/55 R17 91H	Winter tyres on Light alloy	Hankook	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in center console with roller blind
- Adaptive Highbeam Assist
- Airbag: Automatic passenger airbag deactivation
- Airbag: Kneebag for driver
- Airbag: Windowbag for driver and front passenger
- Foldable armrest in the center console for driver and front passenger
- Outdoor temperature display
- Basic services
- Double cup holder at the front
- ECO start/stop function
- Electronic Stability Program (ESP)
- Chassis: Comfort chassis
- Electric windows (4-way)
- Luggage net on driver and passenger seatbacks
- Transmission: 8G-DCT automatic
- Heated rear window
- KEYLESS-GO start function
- THERMATIC automatic climate control (1-zone climate control, automatically controlled air distribution, recirculation function, tunnel function in conjunction with navigation system, fine dust filter). Automatic tunnel deactivation in conjunction with activated navigation. It detects tunnel entrances, interrupts the fresh air supply and closes the side windows or the panoramic sunroof. Personalization adjusts the heating, air conditioning and airflow for different driver profiles.)
- Charging cable for wallbox and public charging station, 5m, smooth 11kW (This charging cable, also called Mode 3 cable, allows you to charge the vehicle battery at the wallbox or at public charging stations with up to 11 kW (Type 2, 3-phase, 16 A).)
- Mercedes-Benz emergency call system
- Otto particulate filter
- Package: Seating comfort (height adjustment for passenger seat - seat cushion tilt adjustment for driver and passenger seats - seat cushion depth adjustment for improved seating comfort through a 60 mm wider thigh support area - specific seat design)
- Package: Mirror package (interior and exterior mirrors on the driver's side automatically dimming - exterior mirrors left and right electrically folding)
- Package: USB Package Plus (2 USB-C ports in the front storage compartment, fast charging and suitable for data transfer - 2 USB-C ports under the center armrest, fast charging and suitable for data transfer - 2 USB-C ports in the rear center console, fast charging)
- Radio: Extended MBUX functions
- Radio accessories: Central Media Display
- Remote and Charging Services Plus
- Windscreen wipers with rain sensor
- Crosswind Assist
- Seat belts A-Class
- Seats: 4-way lumbar support
- Seats: Comfort seats
- ABS - Anti-lock Braking System
- Adaptive brake light flashing
- Airbag: Driver and front passenger
- Airbag: Side airbag for driver and front passenger
- Traction control (ASR)
- ATTENTION ASSIST
- Heated exterior mirrors (left and right), electrically adjustable from inside
- Brake assist, active
- Third brake light
- Door sills with the lettering "Mercedes-Benz"
- Driving light assistant
- Vehicle key with chrome decorative frame
- Velour floor mats
- Speed Limit Assistant
- rear window wiper
- Interior headliner fabric crystal grey
- Mechanical child safety lock
- Communication module (LTE) for the use of Mercedes me connect services
- Rear headrests (3)
- Front headrests are height-adjustable
- Charging cable for household socket, 5m, smooth (This charging cable, also called Mode 2 cable, allows you to charge the vehicle battery at the household socket with up to 1.8 kW (230 V, 1-phase, 8A) and fits sockets of type E/F CEE 7/7)
- Charging system: Alternating current charging system (AC charging) 3.7 kW
- Steering wheel: Multifunction sports steering wheel in leather
- Steering: Direct steering
- Navigation: MBUX Navigation Premium
- Package: Light and Sight Package (Overhead control unit "4 light stones" (including glasses compartment), Interior light/reading light rear in mounting plate (rear/left/right), Touchpad lighting (front), Reading lights (front/left/right), Console ambient light, Make-up lights (front/left/right), Signal and ambient light, Exit signal light (front/left/right), Handle recess/pull handle lighting (front/rear/left/right), Footwell lighting (front/left/right), Cupholder/storage compartment lighting, Spontaneous storage compartment lighting)
- Upholstery: ARTICO leatherette/Bertrix fabric
- Radio accessories: Digital radio (DAB)
- Radio accessories: USB interface in the storage compartment & 2 USB interfaces in the rear center console
- Radio: MBUX multimedia system
- Tire pressure monitoring system
- Wheels: 43.2 cm (17") alloy wheels, 4-piece set in 5-twin-spoke design (aerodynamically optimized, painted black and polished with 205/55 R17 tires on 6.5J x 17 ET44 rims)
- Seats: Rear seat backrests foldable 40/20/40 split
- Seats: Heated seats for driver and front passenger

- Lane Keeping Assist, active
- Cruise control
- Touchpad
- High-visibility vest for drivers
- Heat-insulating glass, green all around
- Decorative elements in dark carbon look
- Power outlet: 12V connection
- TIREFIT with tire inflation compressor
- Pre-installation for digital key handover
- Electronic immobilizer
- Central locking

Extra equipment

- Airbag: Side airbags in the rear
- THERMOTRONIC automatic climate control with 2 zones (separate temperature selection for driver and front passenger - automatic control of temperature, air volume and air distribution - sensors keep the desired climate constant - continuous monitoring of the intake outside air for harmful gases with automatic recirculation - a fine dust activated carbon filter improves the air quality in the vehicle - dew point sensor prevents the windows from fogging up)
- MULTIBEAM LED (18 individually controllable high-performance LEDs per module, low beam/high beam in LED projection technology, Adaptive Highbeam Assist Plus, Active Cornering Light when high beam is activated, Country Road, City, Highway, Bad Weather and Extended Fog Light with road illumination optimized for the driving situation, Cornering Light with roundabout and intersection function in conjunction with hard drive navigation, Adaptive full-LED taillights with automatic adjustment of light intensity to the surroundings)
- Package: Parking package with 360° camera (12 ultrasonic sensors, Active Parking Assist, 360° camera, PARKTRONIC parking assist, Rear Cross Traffic Alert: can provide visual and audible warnings when reversing out of a parking space if rear cross traffic is detected and, if necessary, automatically initiate emergency braking; Drive Away Assist: can briefly limit the approach speed if an obstacle is detected less than approximately 1 meter away when changing gears while the vehicle is stationary)
- Sunroof: Electric panoramic sunroof
- Seats: Electrically adjustable driver's seat with memory function (The memory function saves your ideal position for the driver's seat, exterior mirrors, and head-up display. Up to three people can instantly find their preferred position at the touch of a button – making driver changes quick and easy. You can also easily readjust the seat electrically and continuously.)
- Black fabric headliner
- Paint finish: Metallic
- Charging system: AC charging system 11kW (More flexibility: With the powerful AC charging system, you can charge your plug-in hybrid quickly and easily with up to 11 kW (3-phase) or 7.4 kW (1-phase). In addition to a wallbox at home, you can also connect your vehicle to a variety of public charging stations. These usually supply alternating current – just like conventional sockets.)
- Package: Advanced Plus (Compact Sedan) (Ambient lighting - Fully digital instrument display - Wireless charging system for mobile devices in the front - Rear armrest - KEYLESS-GO - Fingerprint scanner)
- Package: Driving Assistance (Active Distance Assist DISTRONIC (Active Speed Limit Assist, Extended Automatic Restart on Motorways, Route-Based Speed Adaptation with Traffic Jam Radio) - Active Steering Assist (Active Emergency Stop Assist with SOS Radio, Emergency Lane Radio) - Active Brake Assist (Turning and Intersection Function, Traffic Jam Emergency Braking Function) - Evasive Steering Assist - Active Lane Keeping Assist - Active Blind Spot Assist (Exit Warning Function) - Traffic Sign Assist (Pedestrian Warning Function in the Area of Zebra Crossings) - PRE-SAFE PLUS)
- Upholstery: ARTICO leatherette/fabric
- Wheels: Complete summer wheel sets fitted at the factory
- Wheels: Winter complete wheels M+S 4-way 43.2 cm (17") (43.2 cm (17") light alloy wheels 5-twin-spoke design aerodynamically optimized, vanadium silver painted with 205/55 R17 on 6.5J x 17 ET44)
- Seats: Front right seat electrically adjustable with memory
- Phone accessories: Smartphone integration (consisting of Apple CarPlay and Android Auto)
- Partition net for luggage compartment separation and occupant protection
- Traffic Sign Assistant

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - Smart repair
2	Misc.	Main inspection - Due - Perform
3	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value

Wear and tear

No.	Component group	Description
1	Front bumper	Spoiler - Stone chips - No deduction
2	Front bumper	Front bumper - Stone chips - No deduction
3	Bonnet	Bonnet - Stone chips - No deduction
4	Interior	Interior - Scratch(es) - No deduction
5	Vehicle glazing	Windscreen - Stone chips - No deduction
6	Sill - left side	Sill - Scratch(es) - No deduction
7	2nd wheel set	Wheel cover set - complete (Radnabenkappen) - Missing - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 9 May 2026	1.947,73 €
2	Front, Provided by user / customer, from 5 Jun 2026	2.007,81 €

Repainting

No.	Repainting
1	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear right side	143 µm

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt




Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 3: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 3: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Repainting 1: Side panel - rear right side



Repainting 1: Side panel - rear right side