TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 47950934
Order No. / Reference: 27054432
Inspection date: 6 Oct 2026

Manufacturer: Opel	Model: Mokka-e Ultimate
VIN: VXKUKZKXZPW069528	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Mokka-e Ultimate	
Vehicle Identification number	VXKUKZKXZPW069528
Mileage (Read)	18,220 km
First registration	7 Aug 2023
Number of holders	1
Next periodical technical inspection	08/2028
(Report on hand)	
Fuel type	Electric
Power	57 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Arktis Weiß
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	17,000 km
Last service on / at	07/2025 at 10,301 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS866057
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1889 / ADD 00041		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,015 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R18 99V	Summer tyres on Light alloy	Goodyear	3mm / 3mm
2)	215/55 R18 99V	Summer tyres on Light alloy	Goodyear	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R17 96H	Winter tyres on Light alloy	Bridgestone	5mm / 5mm
2)	215/60 R17 96H	Winter tyres on Light alloy	Bridgestone	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 ignition keys, with remote control
- Storage compartments (storage compartment in the center console, front and rear - storage compartment in the front doors, suitable for 1.5-liter beverage bottles - storage compartment in the rear doors, suitable for 0.5-liter beverage bottles - cup holder in the center console - glove compartment)
- Driver and passenger side airbags
- Airbag: Head airbags, front and rear outer
- Active pedestrian warning tone (AVAS) (ambient noise up to a driving speed of 30 km/h)
- Exterior mirrors in black
- Exterior mirrors, electrically adjustable and heated, electrically folding
- Hill Start Assist
- Roof and A-pillar in carbon black
- Headliner, Black
- Decorative strips, silver
- Third brake light
- Electronic Stability Program Plus (ESP Plus)
- Chassis: Driving modes (with 3 adjustable driving modes: ECO, Normal and Sport)
- Pedestrian protection
- Transmission: Automatic electric drive with fixed gear ratio
- Heated rear window
- rear window wiper
- Child safety lock in the rear doors, manual
- Front headrests and 3 rear headrests, height adjustable
- Charging connection options (alternating current (AC), plug type 2, and direct current (DC), plug type CCS (Combined Charging System))
- Steering wheel: Leather steering wheel, flattened at the bottom
- Steering column, height and tilt adjustable
- Illuminated makeup mirror in sun visor, for driver and front passenger
- Multi-collision brake (In the event of a collision or unavoidable accident, the system is activated and brakes the vehicle to a standstill to avoid further collisions with other road users or obstacles.)
- Fatigue detection
- OpelConnect with telematics services (Connect One: - Emergency call/breakdown call - Vehicle status and information - Route and trip information; Connect Plus: - Live navigation (including real-time traffic information, fuel prices, POI search; only in conjunction with Multimedia Navi and Multimedia Navi Pro) - Remote control (activating the headlights and horn as well as locking and unlocking the vehicle remotely via the myOpel app))
- Storage: Pockets on the back of the front seats (driver and passenger)
- Active Drive Assist Plus (Automatic Speed Assist with Stop & Go function - Front Collision Warning with automatic emergency braking as well as pedestrian and cyclist detection - Active Lane Keeping Assist)
- Adaptive brake light
- Airbag: Front and side airbags
- Actively controlled air intakes (Active Aero Shutter)
- Aluminum sports pedals
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Battery charging kit: Mode 2 charging cable (1.8 kW) for household socket and battery charging status indicator
- Braking system: Regenerative
- Roof design line in chrome
- Roof spoiler, black
- Double boot floor
- Electronic brake force distribution (EBD)
- Emblem "e" on tailgate
- Electric windows front and rear (with one-touch function and anti-pinch protection)
- Cruise control with intelligent speed limiter (The intelligent speed limiter, in conjunction with traffic sign recognition, allows for rapid speed adjustment)
- Rear shelf
- Automatic climate control (with activated carbon filter, manual recirculation, automatic air distribution - footwell heating, rear - sun position sensor)
- LED headlights (LED ambient lighting in door storage compartments, front - LED turn signals, front and rear - LED taillights - LED daytime running lights - LED headlights - High beam assist)
- Reading lights, front
- Center armrest, front (incl. 2 USB charging ports)
- Mode 2 charging cable (Type 2, up to 1.8 kW), 6 m length, for household sockets)
- myOpel App (with Mokka-e specific functions: battery charge level indicator and range monitoring, remote control of the climate control and charging settings)
- Onboard charger (vehicle-integrated charging unit), 3-phase (11 kW)
- Park & Go (Park Pilot, front and rear parking aid with audiovisual warning - 180-degree panoramic reversing camera - blind spot warning and side protection - electrically folding exterior mirrors - ambient lighting - LED fog lights)

- Radio: Multimedia Radio Pro (with 10" touchscreen and fully digital 12" driver information display - Bluetooth audio streaming - Automatic music recognition - Hands-free system - Phonebook and call list display - Smartphone integration via Apple CarPlay and Android Auto - Display and operation of selected apps and functions via the 7" touchscreen or voice control, e.g., navigation, music, telephone - Text message reading and dictation - Siri - Digital radio reception DAB+ - Steering wheel controls - 4x20 watts, FM/AM - Front USB - 2 rear USB)
- Wheels: Tire repair kit (with tire sealant and 12-volt compressor (without jack))
- "Mokka" lettering on the rear in chrome
- Side impact protection
- Seat belts (three-point seat belts in all seats: - belt force limiter and belt tensioner, front and rear outer seats - warning tone and light for unfastened seat belts, front seats)
- Seats: Driver's seat manually adjustable in 6 ways (length, height and backrest angle)
- Seats: Rear seat backrest foldable in a 60:40 ratio
- Solar Protect heat-insulating glazing (heavily tinted, in the rear)
- 12-volt power outlet (in the center console, front)
- Traction control with engine and brake intervention TC Plus
- Underride protection look, front and rear, in silver
- Immobiliser
- heat pump
- Tinted heat-insulating glazing
- Central locking with remote control
- Upholstery: Alcantara/Premium Leather Look (Alcantara trim, black - seat contact surfaces and side bolsters, inside, in Alcantara - headrests, door panels and outer side bolsters in premium leather look - comfort driver's seat with massage function: 6-way manually adjustable (length, height, backrest angle), lumbar support, electro-pneumatically adjustable in height and length - comfort passenger seat, 6-way manually adjustable (length, height, backrest angle))
- Tire pressure warning
- Wheels: Light alloy (4) 5 spoke 7J x 18 in BiColor Black (with tires 215/55 R18)
- Keyless locking and starting system "Keyless Open & Start" (Keyless unlocking for driver's door and luggage compartment - engine start button)
- Speed-sensitive power steering
- Visibility equipment (front rain sensor - automatic dimming headlights with tunnel detection - interior rearview mirror, automatically dimming)
- Seats: Front passenger seat manually adjustable in 6 ways (length, height and backrest angle)
- Seats: Comfort seats, front
- Seats: Pre-installation for ISOFIX child seat mounting system, front passenger seat and rear outer seats
- Start/Stop System (Reinforced starter motor - High-performance battery - Switch to deactivate the start/stop function)
- Traffic sign recognition (recognition of speed limits and their cancellation, as well as display of the recognized sign in the driver information display (depending on visibility and weather conditions))

Extra equipment

- Anti-theft alarm system (deterrent signal - interior monitoring)
- Mode 3 charging cable
- Package: Winter (Seat heating, driver and front passenger, multi-stage switchable - Leather steering wheel, heated)
- Paint finish: Solid
- Radio: Multimedia Navi Pro (Mokka-e) (with 10" color touchscreen display and fully digital 12" driver information display - Navigation with integrated memory - Road map of Europe (including Russia and Turkey) - 3D map display - Dynamic route guidance via map and/or arrow display - Display of points of interest - Trip planning - GPS module - Display of charging stations. OpelConnect, including LIVE navigation services: - Map updates (via USB) - Voice control for audio, telephone and navigation - Radio, Bluetooth, DAB+, USB, hands-free calling)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wing mirror - left side	Cap - Scratch(es) - Smart repair
2	Side panel - rear left side	Side panel - dent(s) - Smooth repair work

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Der beiliegende Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.

- Keine Besichtigung des Unterbodens, Begutachtung Fahrwerk/Achsen/Aggregate nur bedingt möglich, Zusatzkosten können entstehen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Damage 1: Wing mirror - left side: Cap - Scratch(es) - Smart repair

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck



Damage 1: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 2: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 2: Side panel - rear left side: Side panel - dent(s) - Smooth repair work