DEKRA

DEKRA Automotive Solutions


# Appraisal Report

## Vehicle details

| | | | | | |
|---|---|---|---|---|---|
| VIN | ZARPAHPX0 R7D85554 | Registration date | 14/05/2024 | Exterior Color | Unknown |
| Brand | ALFA ROMEO | Licence Plate | UL-MM 1221 | Odometer | 58 563 km |
| Model | STELVIO 2.2 Diesel 16V 154kW Veloce AT8- | | | | |

## Inspection Details

| | | | | | |
|---|---|---|---|---|---|
| Arrival Date | 17/08/2026 | Inspection ID | 7123694 | Inspection date | 24/08/2026 |
| Assign Date | 17/08/2026 | Fleet owner | Leasys Privat Leasing | Inspection loc. | Leasys AKB Lüdersfeld |



## Generic equipment

## Removable element

| | |
|---|---|
| Spare wheel kit | ✓ |
| Load cover | ✓ |
| Radio user manual | ✓ |


## Technical Document

| | |
|---|---|
| User manual | ✓ |
| Warranty booklet | ✓ |
| Log books | ✓ |
| Spare key | ✓ |
| Key | ✓ |
| Service | ✓ |

## Tyres

Continental 225/45/20 Y Summer 5.0 mm

Continental 225/45/20 Y Summer 5.0 mm





Continental 255/45/20 Y Summer 5.0 mm

Continental 255/45/20 Y Summer 5.0 mm

## Exception / Damage

**1**



| | | | | | |
|---|---|---|---|---|---|
| Part | Bumper | Repair Time | 0.85 | Part Cost | - |
| Position | Front | Repair Cost | 119.00€ | Gross Cost | 374.00€ |
| Damages | Scratched | Paint Time | 1.70 | Depreciation % | 15.00% |
| Severity | - | Paint cost | 255.00€ | Depreciation | - 56.10 |
| Repair mode | Repair | Flat Rate | - | **Net Cost** | **317.90€** |

**2**

| | | | | | |
|---|---|---|---|---|---|
| Part | Bonnet | Repair Time | - | Part Cost | - |
| Position | Front | Repair Cost | - | Gross Cost | - |
| Damages | Scratched | Paint Time | - | Depreciation % | 15.00% |
| Severity | - | Paint cost | - | Depreciation | - |
| Repair mode | For info | Flat Rate | - | **Net Cost** | **-** |

**3**

| | | | | | |
|---|---|---|---|---|---|
| Part | Windscreen | Repair Time | - | Part Cost | - |
| Position | Front | Repair Cost | - | Gross Cost | - |
| Damages | Stone impact | Paint Time | - | Depreciation % | - |
| Severity | - | Paint cost | - | Depreciation | - |
| Repair mode | For info | Flat Rate | - | **Net Cost** | **-** |

**4**



| | | | | | |
|---|---|---|---|---|---|
| Part | Bumper | Repair Time | 0.60 | Part Cost | - |
| Position | Back | Repair Cost | 84.00€ | Gross Cost | 294.00€ |
| Damages | Scratched | Paint Time | 1.40 | Depreciation % | 15.00% |
| Severity | - | Paint cost | 210.00€ | Depreciation | - 44.10 |
| Repair mode | Repair | Flat Rate | - | **Net Cost** | **249.90€** |

**5**




| | | | | | |
|---|---|---|---|---|---|
| Part | Wing | Repair Time | - | Part Cost | - |
| Position | Back left | Repair Cost | - | Gross Cost | 45.00€ |
| Damages | Scratched | Paint Time | 0.30 | Depreciation % | - |
| Severity | - | Paint cost | 45.00€ | Depreciation | - |
| Repair mode | Smart Repair | Flat Rate | 45.00€ | **Net Cost** | **45.00€** |

**6**



| | | | | | |
|---|---|---|---|---|---|
| Part | Door | Repair Time | - | Part Cost | - |
| Position | Back left | Repair Cost | - | Gross Cost | 30.00€ |
| Damages | Scratched | Paint Time | 0.20 | Depreciation % | - |
| Severity | - | Paint cost | 30.00€ | Depreciation | - |
| Repair mode | Smart Repair | Flat Rate | 30.00€ | **Net Cost** | **30.00€** |

**7**




| | | | | | |
|---|---|---|---|---|---|
| Part | Door | Repair Time | - | Part Cost | - |
| Position | Front left | Repair Cost | - | Gross Cost | 30.00€ |
| Damages | Scratched | Paint Time | 0.20 | Depreciation % | - |
| Severity | - | Paint cost | 30.00€ | Depreciation | - |
| Repair mode | Smart Repair | Flat Rate | 30.00€ | **Net Cost** | **30.00€** |

**8**



| | | | | | |
|---|---|---|---|---|---|
| Part | Roof post A/B/C | Repair Time | 1.50 | Part Cost | - |
| Position | Back left | Repair Cost | 210.00€ | Gross Cost | 210.00€ |
| Damages | Dented | Paint Time | - | Depreciation % | - |
| Severity | - | Paint cost | - | Depreciation | - |
| Repair mode | Smart Repair | Flat Rate | 210.00€ | **Net Cost** | **210.00€** |

**9**

| | | | | | |
|---|---|---|---|---|---|
| Part | Paint preparation | Repair Time | - | Part Cost | - |
| Position | - | Repair Cost | - | Gross Cost | 255.00€ |
| Damages | - | Paint Time | 1.70 | Depreciation % | 15.00% |
| Severity | - | Paint cost | 255.00€ | Depreciation | - 38.25 |
| Repair mode | Paintworks | Flat Rate | - | **Net Cost** | **216.75€** |

DEKRA Automotive Solutions

## Summary Inspection

| | | | | | |
|---|---|---|---|---|---|
| Gross Price | 1,238.00€ | Depreciation | -138.45€ | Net Price | 1,099.55€ |

## Labor cost summary

| | Hourly Rate | Time | Gross Price | Depreciation % | Depreciation | Net Price |
|---|---|---|---|---|---|---|
| Bodywork | 140.00€ | 2.95 | 413.00€ | 7.37 % | -30.45€ | 382.55€ |
| Paintwork | 150.00€ | 3.80 | 570.00€ | 12.24 % | -69.75€ | 500.25€ |
| Paint preparation | 150.00€ | 1.70 | 255.00€ | 15.00 % | -38.25€ | 216.75€ |

## Miscellaneous

| | Gross Price | Depreciation % | Depreciation | Net Price |
|---|---|---|---|---|
| Small parts / disposal charge | 0.00€ | - | - | 0.00€ |
| Part Cost | 0.00€ | - | - | 0.00€ |
| Flat Rate | 0.00€ | - | - | 0.00€ |