TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach

Expertise

Protocol number: 48547933
Order No. / Reference: 27262894
Inspection date: 4 Nov 2026

Manufacturer: Skoda	Model: Superb Combi 2.0 TDI DSG 4x4 L&K
VIN: TMBLR0NZ0SC008997	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Superb Combi 2.0 TDI DSG 4x4 L&K	
Vehicle Identification number	TMBLR0NZ0SC008997
Mileage (Read)	123,673 km
First registration	16 Oct 2024
Number of holders	1
Next periodical technical inspection	10/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	142 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	Car station wagon
Colour / colour code	Ebony Black Metallic (Y9T)
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	23,300 km
Last service on / at	09/2026 at 116,967 km		
Key is / should be	3 / 3	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HG803140
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	short drive on the company premises	**Engine function test**	Performed
Manufacturer key number/ type code number	8004 / AYA 00016		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,320 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98V	Winter tyres on Light alloy	Pirelli	3mm / 3mm
2)	215/55 R17 98V	Winter tyres on Light alloy	Pirelli	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/45 R18 94W	Summer tyres on Light alloy	Goodyear	4mm / 4mm
2)	235/45 R18 94W	Summer tyres on Light alloy	Goodyear	3mm / 3mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	125/70 R18 99M	Summer tyres on Steel	Sonstige	3 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach

Equipment

Standard equipment

- Storage compartments in the front door panels with 1.5l bottle holders
- Airbag, driver and passenger
- Airbag: Side airbags, front center airbag and front and rear head airbags
- Trailer hitch preparation including trailer stabilization
- Anti-lock braking system (ABS)
- Attention and fatigue assistant
- Exterior mirrors and door handles in body color
- Cup holders in the front center console
- Hill start assist
- third brake light
- Four roof grab handles (rear with coat hooks, ticket holder on the windshield)
- Diesel particulate filter
- Digital rotary controls (Smart Dials)
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC)
- Luggage compartment lighting with 2 lamps
- Cruise control system including speed limiter (speed limiter)
- Rear window wiper including windshield washer system
- Interior mirror with automatic dimming function (Automatic interior mirror dimming with rain and light sensor)
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Climatronic air conditioning (3-zone) (separately adjustable for driver, front passenger and rear passengers)
- Paint finish: Solid
- LED footwell lighting front and rear
- electric auxiliary air heater
- Front center armrest, including storage compartment
- Engine drag torque control (MSR)
- Multi-collision brake
- Package: Chrome (Combi) (Window trim strips and radiator grille ribs in chrome - Radiator grille frame and front bumper trim strip in Unique Dark Chrome - Roof rails silver anodized)
- Package: Infotainment (Navigation system - 13" infotainment display - Display cleaner - Infotainment Online (3-year subscription))
- Package: Light & Sight (Matrix LED headlights with Light Assist and Welcome Effect - Dynamic High Beam Assist - Dynamic and automatic headlight range control - LED rear reflectors with dynamic turn signals, crystal design and Welcome Effect - Rear fog lights on both sides, reversing lights on both sides - Cornering and rough road lights)
- Package: Winter (Heated front seats and outer rear seats - Heated leather steering wheel with multifunction buttons and paddle shifters - Wireless heated windscreen)
- Phone box with charging function 15 W
- Proactive occupant protection with rear impact detection
- Storage pockets on the backs of the front seats including smartphone pockets
- Airbag, driver's knee airbag
- Ambient lighting (dashboard, front and rear trim strips, footwell with selectable color climate) in the interior as well as LED safety warning lights in the front and rear doors)
- Traction control (ASR)
- Electrically adjustable, heated and folding exterior mirrors with boarding spots (memory function - automatic dimming (driver's side))
- Hydraulic brake assist (HBA)
- Cargo elements in the trunk
- Grey headliner
- Roof rails, black
- Digital Cockpit Plus
- Ice scraper in the fuel filler flap
- Electronic transverse differential lock (XDS+)
- Electric windows front and rear, including anti-pinch protection and electric child safety lock
- Transmission: 7-speed dual-clutch transmission (DSG)
- Heated rear window
- Interior LED lights at the front with 2 reading lights, 2 reading lights at the rear
- Interior Design Selection Suite L&K Black (dashboard in black - headliner in grey - door trim in black with soft touch - seat covers in perforated black leather with Laurin & Klement logo, seat bolsters in black)
- Rear headrests (3), height adjustable
- Front headrests, height and length adjustable
- Stainless steel loading edge
- Remote release of the rear seat backrests in the trunk
- Center armrest with storage compartment and 12-volt socket
- Multifunctional camera (for driver assistance systems)
- eCall+ emergency call function
- Package: Drive Plus (Adaptive chassis DCC Plus - Driving profile selection - Progressive steering)
- Package: EU-NCAP (Bumpers with enhanced and predictive pedestrian protection measures - Traffic sign recognition - Emergency Steering and Turn Assist - Crossroad Assist - Front radar assist including City Emergency Braking and pedestrian and cyclist detection - Intelligent Speed Assist (ISA) - Lane Assist - Side Assist and Exit Warning)
- Package: Transport (Combi) (Luggage compartment net program (3 nets) - Luggage compartment cover with flexible storage pocket with electric roller blind release - Comfort opening with electric tailgate operation - KESSY - Anti-theft alarm system including safe system with interior monitoring and tilt sensor)
- Front and rear parking sensors with maneuvering brake function
- Radio accessories: 2 USB charging ports in the center console (and 2 on the back of the front center armrest (Type-C) 45 W)

- Radio accessories: Bluetooth hands-free system
- Radio accessories: CANTON sound system with 14 speakers (12 speakers, 1 center speaker, 1 subwoofer) - including steel spare wheel)
- Radio accessories: Wireless & Wired SmartLink (Apple CarPlay - Android Auto)
- Umbrella and broom compartments in the front doors
- Tire pressure monitoring
- Tire mobility kit (tire repair spray incl. compressor)
- Rear view camera
- Electromechanical power steering
- LED safety lights in the front and rear doors
- Seats: Heated front seats
- Seats: Ergo Comfort front seats (fully electrically adjustable - extended massage function - memory function - adjustable lumbar support - entry aid - extendable leg rest - seat ventilation)
- SKODA Infotainment Online (Online map updates for navigation - Online traffic situation - Online petrol station and parking space search)
- Sun visors with illuminated make-up mirror on driver and passenger side
- 12V power outlet in the luggage compartment
- Sunset (rear window and rear side windows tinted dark)
- Daytime running lights with cornering lights and coming home function
- Glazing: Acoustic glazing in the front side windows and Sunset (dark tinted rear window and rear side windows)
- Electronic immobilizer
- Radio accessories: Digital radio reception DAB+
- Radio accessories: USB charging port in the rearview mirror (15W)
- Umbrella
- Rain sensor and driving light assistant ((Easy Light Assist) (Tunnel light, Coming Home, Leaving Home))
- Wheels: 18" Belatrix alloy wheels, diamond-turned anthracite (8Jx18 tires 235/45 R18 94)
- Superb safety belts (Height-adjustable three-point front seat belts with belt tensioners - Three three-point rear seat belts - Belt fastening indicator for all seats)
- Seats: Rear seat backrest split 60:40, foldable with center armrest
- SKODA Care Connect (SOS emergency call function (Emergency Call incl. automatic activation in the event of an accident with airbag deployment), Mobility service (connection for rapid assistance in case of breakdown), Information service (connection to the hotline for all questions relating to vehicle functions), Free remote vehicle access for 3 years (Remote Access) with access to vehicle data and functions via smartphone, e.g. parking position, activating hazard warning lights, current fuel level)
- Textile floor mats
- Front door sill trims
- Lashing eyes in the luggage compartment
- Preparation for alcohol immobilizer
- Central locking accessories: 3rd vehicle key

Extra equipment

- Swiveling trailer hitch including trailer stabilization with trailer maneuvering assistant (ARA)
- Package: Driving Assistance Plus (Travel Assist Plus: - Adaptive Cruise Control ACC (control range up to 210 km/h, cruise control system omitted) - Adaptive Lane Keeping Assist (Lane Assist +) - Traffic Jam and Emergency Assist - Intelligent Park Assist, front and rear parking sensors - Trained Park Assist - 360° Surround View Cameras)
- Tire pressure monitoring system active
- Variable double floor including anchoring eyelet for loading floor, organizer
- Luggage net partition
- Paint finish: Metallic
- Package: Family (Combi) (Sunshade roller blind for rear side windows - Tablet holder - Sleeping package (sleeping headrest + blanket) - Rear side airbag - Waste bin)
- Package: Infotainment Plus (Navigation system - 13" infotainment display - Display cleaner - Head-up display - Infotainment Online (3-year subscription))
- Panoramic sunroof, electric
- Auxiliary heater with radio remote control

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	A short maneuvering and shunting exercise was carried out on the company premises.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Roof	Roof rail - left side - Soiled - Conditioning
2	Side panel - rear right side	Sill - Scratch(es) - Smart repair
3	Equipment	Vehicle key with remote control - Non-operational - Perform diagnosis
4	2nd wheel set	1 tyre (Drucklos) - Leaking - Replace
5	2nd wheel set	1 alloy rim (Materialabtrag) - Scratched - Replace
6	2nd wheel set	1 alloy rim (Materialabtrag) - Scratched - Replace

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Tyres - complete set (4 Winterreifen unter 4mm - kein Teil der Ausstattung) - Worn - No deduction
2	Door - front right side	Door handle - outside - Scratch(es) - No deduction
3	Rear bumper	Rear bumper (Ladekante) - Scratch(es) - No deduction
4	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Umbrella

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 19 Jun 2025	1.136,86 €
2	Front, Provided by user / customer, from 5 Mar 2026	6.108,11 €

Repainting

No.	Repainting
1	Bonnet, Professionally carried out
2	Side panel - rear left side
3	Door - front right side, Professionally carried out

Paint coat thickness measurement

Bonnet	211 µm	Side panel - rear left side	174 µm
Door - front right side	282 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.




Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.




Damage 1: Roof: Roof rail - left side - Soiled - Conditioning



Damage 1: Roof: Roof rail - left side - Soiled - Conditioning



Damage 2: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 2: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 3: Equipment: Vehicle key with remote control - Non-operational - Perform diagnosis



Damage 4: 2nd wheel set: 1 tyre (Drucklos) - Leaking - Replace



Damage 5: 2nd wheel set: 1 alloy rim (Materialabtrag) - Scratched - Replace



Damage 5: 2nd wheel set: 1 alloy rim (Materialabtrag) - Scratched - Replace



Damage 5: 2nd wheel set: 1 alloy rim (Materialabtrag) - Scratched - Replace



Damage 6: 2nd wheel set: 1 alloy rim (Materialabtrag) - Scratched - Replace




Damage 6: 2nd wheel set: 1 alloy rim (Materialabtrag) - Scratched - Replace



Damage 6: 2nd wheel set: 1 alloy rim (Materialabtrag) - Scratched - Replace




Wear and tear 3: Rear bumper: Rear bumper (Ladekante) - Scratch(es) - No deduction




Wear and tear 3: Rear bumper: Rear bumper (Ladekante) - Scratch(es) - No deduction



Wear and tear 3: Rear bumper: Rear bumper (Ladekante) - Scratch(es) - No deduction



Wear and tear 4: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 4: Vehicle glazing: Windscreen - Stone chips - No deduction



Missing part 1: Equipment: Umbrella - Missing - Replace



Missing part 1: Equipment: Umbrella - Missing - Replace



Repainting 1: Bonnet

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach



Repainting 1: Bonnet



Repainting 2: Side panel - rear left side



Repainting 2: Side panel - rear left side



Repainting 3: Door - front right side



Repainting 3: Door - front right side