Audi

2.0 TFSI 50 E S-TRONIC 4WD BE ATTRACTION

VIN: WAUZZZF25RN016864



Description

Registration number 2EMA349	**Registration date** 16/11/2023	**Odometer** 83388 km
Color Gris Chronos Métallisé	**Year** 2023	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
Engine displacement 1984	**Gearbox type** Automatic	**Engine type** Plug-in Hybrid
Number of gears 7	**Max power** 220 KW	

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

DEKRA

Vehicle Equipments

Standard

center armrest front	driver assistance system: parking aid side	airbag driver side/passenger side
airbag passenger side deactivatable	sidebag front	generator 110-180 A
immobilizer (electronic)	Audi Application Store and Smartphone Interface	Audi connect (web-based services)
Audi connect (Emergency and Assistance System)	Audi Drive Select	Audi Smartphone Interface
battery 68 Ah	transmission 7-speed - dual-clutch transmission S-tronic	rear lid open+close automatic (Hands-Free-Access system)
body: 4-door	standard suspension	comfort automatic air-conditioning 4-zone
auxiliary air-conditioning	steering column (steering wheel) mech. height/longitudinal adjustment	instrument cluster digital (virtual cockpit plus)
instrument cluster digital (virtual cockpit)	Electronic Stability Control (ESP)	jack
charging cable with type-2 connector (mode 3)	charging cable with three-pin plug	progressive steering
Disques de frein AR (330 mm x 22 mm)	rear seat backrest split/folding (40:20:40)	charging system alternating current (AC)
Longlife-Service	interior equipment decorative trim inserts aluminium matte brushed, dark	rear lights LED
turn signal lights LED in exterior mirror integrated	gasoline particulate filter (GPF)	refrigerant R 1234 YF
roof liner anthracite	windshield washer jets heated	hybrid
light alloy rims 8x18 (5-double-arm Design)	tire repair kit	vehicle speed limiter
Type of drive: all-wheel drive	engine 2,0 liter - 143 kW CDI catalyst	electric motor 105 kW (hybrid drive)
multi-media Interface MMI basic plus / MMI radio plus	multi-media Interface MMI Navigation Plus with MMI Touch	sound system DSP / Audi sound system
liftgate control automatic	Shine package	non-smoking package
windshield heat protection glazing	bumper Sports design, painted	Pneus 225/55 R18 ...W
charging socket (AC / DC)	headlight LED	scuff rails with aluminium insert
acoustic pedestrian protection (external sound)	model refinement	radio reception digital (DAB)
cruise control (cruise control)	fuel tank: 52 liter	exterior mirror aspherical, left
exterior mirror vehicle colour	rear seat system (3 seats)	standard seats front
Isofix mounts for child seat	head airbag system (Sideguard)	antilock braking system (ABS)
driver assistance system: brake assistant (Audi pre sense front)	driver assistance system: lane-departure warning	driver assistance system: traffic sign detection
driver assistance system: passenger protection system (Audi pre sense basic)	rail system in cargo space	start/stop system
tire puncture indicator	glazing rear darkened (privacy tinting) and door glasses front acoustic glass	heat protection glazing (sideways / rear)
daytime running lights LED	control elements black matte	

Optional

parking aid front and rear, acoustic and optical with selective display (APS Plus)	lumbar support front, electrically adjustable	roof rails anodised
reversing camera	front camera (multi-functional camera windshield)	comfort key with sensor controlled liftgate release incl. (open+close)
trailer coupling (pivoting ball head)	Disques de frein AV (375 mm x 36 mm)	Disques de frein AV (400 mm x 38 mm)
all-wheel drive coupling	low emissions according to emission standard Euro 6e	metallic paintwork
exterior mirror with automatic curb-view tilting, right	exterior mirror convex, right	exterior mirror electrically adjustable, heated + folding, with Memory
interior mirror with automatic dimming	seat covers/upholstery: leather / mono.pur 550 combination	seat heating front
seats front electrically adjustable (left with Memory)	Isofix mounts for child seat at passenger seat	pedestrian protection system
panoramic roof front electric, rear fixed	VarEq-méthode Véhicule sans UNECE CS (R155) et SU (R156) avec SFD2-SG	steering wheel (leather) with multiple function and shift function
ambient lighting	brake calipers red painted	

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Statement details

Inspection loc
PARC HÖDLMAYR TONGEREN

Statement date
12/10/2026

Inspection approval date
13/10/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Rim / Front Left Material : Aluminium alloy / Rim/Tyre diameter : 16 " / Surface : Painted	Scratched	Repair





002	Door / Front Left	Dent	Acceptable



003	Rim / Back Left Material : Aluminium alloy / Rim/Tyre diameter : 16 " / Surface : Painted	Scratched	Repair




004	Bumper / Back Painted : Yes	Scratched	Painting





005	Rear windscreen / Back Tinted window : Yes	Scratched	Acceptable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



006	Rim / Back Right Material : Aluminium alloy / Rim/Tyre diameter : 16 " / Surface : Painted	Scratched	Repair





007	Exterior door mirror shell / Front Right	Scratched	Acceptable



008	Wing / Front Right	Scratched	Acceptable



009	Bumper / Front Painted : Yes	Scratched	Painting






Loose Items

- Quick charging cable (Type 2, Mode 3)
- First aid kit
- Rear parcel shelf
- Spare Key
- Document holder
- Registration certificate owner
- Conformity certificate
- Towing hook
- Triangle
- User manual
- Registration certificate
- Safety vest

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Main set of tyres

Front Left	PIRELLI	225/55/16 Summer	2 mm
Front Right	PIRELLI	225/55/16 Summer	2 mm
Back Left	PIRELLI	225/55/16 Summer	5 mm
Back Right	PIRELLI	225/55/16 Summer	5 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures



Front left



Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right




Odometer



Navigation



Cable




Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Other



Other



Other



Rim / Front Left / Scratched



Rim / Front Left / Scratched



Door / Front Left / Dent



Rim / Back Left / Scratched



Rim / Back Left / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Rear windscreen / Back / Scratched



Rim / Back Right / Scratched



Rim / Back Right / Scratched


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Exterior door mirror shell / Front Right / Scratched



Wing / Front Right / Scratched



Bumper / Front / Scratched



Bumper / Front / Scratched



Bumper / Front / Scratched



Bumper / Front / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.