TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48109926
Order No. / Reference: 27080568
Inspection date: 14 Oct 2026

Manufacturer: Opel	Model: Combo Cargo 1.5 D Edition erhöhte Zuladung
VIN: W0VEFYHT2NJ557106	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Combo Cargo 1.5 D Edition erhöhte Zuladung	
Vehicle Identification number	W0VEFYHT2NJ557106
Mileage (Read)	94,691 km
First registration	10 Mar 2022
Number of holders	1
Next periodical technical inspection (Report on hand)	06/2028
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	75 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Jade Weiß uni
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Grey-Black
Re-import	no
readiness to drive	Roadworthy

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	39,540 km
Last service on / at	03/2026 at 49,102 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ637019
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	1844 / AIQ 00869		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,390 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96W	Summer tyres on Steel rim with wheel cover	Pirelli	5mm / 5mm
2)	205/60 R16 96W	Summer tyres on Steel rim with wheel cover	Pirelli	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Cover strip for sliding door track
- ABS including brake assist and adaptive brake light
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Exterior mirror housings in black
- Battery discharge protection
- Floor covering: Cargo area floor, painted
- Diesel particulate filter, maintenance-free
- Three-point seat belts in all seats
- Electronic Stability Program (ESP Plus)
- Electric front windows
- Speed controller
- Air conditioning, front, with particle and odor filter
- Paint finish: Solid color paint
- Steering column, adjustable for reach and height
- Upholstery: Cloth
- Wheels: Tire repair kit
- Side impact protection
- Speed-sensitive power steering
- Seats: Driver's seat adjustable in 6 ways: length, height and backrest angle
- Daytime running light
- Doors: Sheet metal insert, driver's side
- Doors: Sliding door, passenger side, sheet metal
- Immobiliser
- Central locking with remote control
- Storage compartments (edition)
- Driver's side airbag
- Automatic dipped headlights
- Exterior mirrors, electrically adjustable, heated and manually folding
- Hill Start Assist
- On-board computer
- Tachometer
- Third brake light
- Driver information display - LCD, black surround
- Speed limiter
- Transmission: 6-speed transmission
- Headrests (2), front, height adjustable
- Steering wheel remote control
- Rear parking pilot
- Radio BT
- Wheels: Steel wheels 6.5 J x 15
- Side protection strips
- Seats: Single passenger seat, fixed
- Start/Stop System
- 12-volt power outlet in the center console
- Traction control with engine and brake intervention (TC Plus)
- Lashing eyes (6) in the cargo area
- Heat-insulating glazing, tinted
- Central locking: Ignition keys (2), one of which is foldable

Extra equipment

- Driver and passenger side airbags
- Rear wing doors, asymmetrically split, glazed, 180° opening angle (rear window wiper - rear window heater)
- Radio: Multimedia radio with 8" color touchscreen display (automatic music recognition (title, album, artist, cover) for audio devices with USB connection, Bluetooth audio streaming, hands-free calling via Bluetooth interface, display of phonebook and call lists, up to 10 mobile phones can be paired, display of pictures/films/videos via USB interface, smartphone integration via Apple CarPlay and Android Auto, USB interface, dual tuner, graphic equalizer, 4 speakers, cruise control, steering wheel remote control)
- Electric windows, front, with one-touch function and anti-pinch protection (as well as comfort closing function via remote control of the central locking system - electrically adjustable, heated and folding exterior mirrors)
- Seats: Double passenger seat (Electric parking brake - storage compartment on the backrest of the middle seat of the double passenger seat)
- FlexCargo partition wall with window (with pass-through function below the passenger double seat including protective bag for the load - interior rearview mirror, manually dimmable)
- Doors: Sliding door, passenger side with fixed window

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Floor mats (VL) - Holes - Replace
2	Body	Body (Ausbleichungen d. Beklebung: aufbereiten, Mehrkosten möglich) - Glued / labelled - Smart repair
3	Mudguard - left side	Mudguard - left side - Scratch(es) - Paint
4	Side panel - rear right side	Side panel (Vergilbung) - Paint defect - Paint

Missing parts

Description
Equipment - Tirefit complete

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 4 Apr 2024	3.391,46 €
2	Rear, Provided by user / customer, from 25 May 2023	6.344,89 €
3	Side right, Professionally repaired, Invoice of repair done Non-existent	

Repainting

No.	Repainting
1	Boot lid / rear door, Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Boot lid / rear door	179 µm	Side panel - rear right side	244 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Professionally repaired previous damages were found at the vehicle.

Comments

- Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - front



Figure 7: Interior - rear



Figure 8: Interior - rear



Figure 9: Instrument cluster



Figure 10: Instrument panel




Figure 11: Instrument panel

Figure 12: Interior 360° view (Online Link)



Figure 13: Cargo area



Figure 14: VIN



Figure 15: Mounted tyres



Figure 16: Mounted tyres



Figure 17: Documents




Figure 18: Documents




Figure 19: Documents




Figure 20: Documents




Figure 21: Documents




Figure 22: Navigation



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Damage 1: Trim / covers: Floor mats (VL) - Holes - Replace



Damage 2: Body: Body (Ausbleichungen d. Beklebung: aufbereiten, Mehrkosten möglich) - Glued / labelled - Smart repair



Damage 2: Body: Body (Ausbleichungen d. Beklebung: aufbereiten, Mehrkosten möglich) - Glued / labelled - Smart repair



Damage 3: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint



Damage 3: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint



Damage 4: Side panel - rear right side: Side panel (Vergilbung) - Paint defect - Paint



Damage 4: Side panel - rear right side: Side panel (Vergilbung) - Paint defect - Paint



Damage 4: Side panel - rear right side: Side panel (Vergilbung) - Paint defect - Paint



Repainting 1: Boot lid / rear door, Side panel - rear right side



Repainting 1: Boot lid / rear door, Side panel - rear right side