TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48520583
Order No. / Reference: 27234466
Inspection date: 3 Nov 2026

Manufacturer: Audi	Model: A3 35 TDI Sportback S tronic advanced
VIN: WAUZZZGY5RA013697	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A3 35 TDI Sportback S tronic advanced	
Vehicle Identification number	WAUZZZGY5RA013697
Mileage (Read)	86,152 km
First registration	22 Aug 2023
Number of holders	1
Next periodical technical inspection	08/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Mythosschwarz Metallic (Y9T)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	13,800 km
Last service on / at	08/2026 at 81,098 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV349078
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BZQ 02068		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,965 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R17 91Y	Summer tyres on Light alloy	Bridgestone	4mm / 4mm
2)	225/45 R17 91Y	Summer tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/50 R17 93H	Winter tyres on Light alloy	Pirelli	4mm / 4mm
2)	205/50 R17 93H	Winter tyres on Light alloy	Pirelli	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Traction control ASR
- Audi pre sense front
- Electrically adjustable and heated exterior mirrors
- third brake light
- Roof edge spoiler
- Digital instrument cluster - fully digital instrument cluster in 10.25 inches
- Electromechanical parking brake
- Electronic Stability Control (ESC)
- Electric windows front and rear
- front and rear floor mats
- Speed limiter
- rear window wiper
- Electrically operated child safety lock
- Manual air conditioning
- Rear headrests (3)
- Steering wheel: Leather steering wheel in 3-spoke design with multifunction and paddle shifters
- Wheel: Alloy wheels - 17 inch - multi-spoke
- Tire pressure monitoring system
- Headlight
- 3-point automatic seat belts
- Seats: Standard front seats
- Lane Departure Warning
- 12-volt power outlet in the rear
- Daytime running light
- Electronic immobilizer
- Airbag: Front side airbags with head airbag system and front interaction airbag
- Audi connect emergency call & service m.connect remote & control
- Exterior mirror housings in body color
- Headliner in steel grey fabric
- Additive-free diesel particulate filter (DPF)
- Tachometer
- Electric auxiliary air heater
- Electronic Differential Lock (EDS)
- Chassis: Standard chassis
- Remote key (without Safe-Lock)
- Removable luggage compartment cover
- Transmission: S tronic 7-speed
- Interior lighting
- i-Size child seat attachment and top tether for the outer rear seats
- Front headrests
- Light and rain sensor
- Non-smoking version
- Radio: MMI Radio plus
- Tire repair kit
- Electromechanical power steering
- Seat covers in fabric
- Seats: Rear seat backrest foldable
- Start-stop system
- 12V socket
- Glazing: Green tinted thermal insulation glazing

Extra equipment

- Adaptive Cruise Control (S tronic) (Using a radar sensor, it detects vehicles ahead within the system's limits and maintains a largely constant speed and distance within the control range. The speed range is between 0 and 210 km/h. The control range is 30 to 210 km/h. In stop-and-go traffic, vehicles can brake to a standstill and, under certain conditions, automatically accelerate again. The distance can be adjusted in 5 steps via Audi drive select or the ACC menu.)
- Towbar (removable and lockable; ball rod and head made of forged steel, the 13-pin socket can be swivelled invisibly behind the bumper apron, the removed towbar fits in the spare wheel well; including trailer stabilization via the electronic stability control (ESC))
- Decorative inlay aluminium spectrum dark (for inlays in dashboard; accent surfaces in instrument panel and center console in satin-effect lacquer platinum grey)
- Anti-theft alarm system (monitoring of doors, front and trunk lids. The Safelock, linked to the door locks, prevents the doors from being opened from the inside once the vehicle has been locked with the key. The anti-theft alarm system includes: - switchable ultrasonic interior monitoring - warning via tilt sensor in case of theft - battery-powered horn to prevent tampering)
- High-beam assist (within the system's limitations, it automatically detects oncoming headlights, taillights of other road users, and light sources in built-up areas. Depending on the traffic situation, the high beams are automatically switched on or off. The system thus improves the driver's visibility and increases comfort.)
- ISOFIX child seat attachment at the front, Top Tether and i-Size for the outer rear seats (holding device for the practical attachment of i-Size and ISOFIX child seats on the front passenger seat and on the outer seats of the rear bench seat.)
- Paint finish: Metallic
- Steering wheel: Leather steering wheel in a 3-spoke design with multifunction plus and shift paddles (The steering wheel's height and reach are manually adjustable. For convenient operation of the extensive standard and optional infotainment features, the steering wheel is equipped with twelve multifunction buttons. Shift paddles allow manual gear changes.)
- Ambient Lighting Package Plus (Glove box lighting (incandescent bulb), LED trunk lighting (right side), front/rear roof module including reading lights (LED), illuminated vanity mirrors (LED), entry lights on the underside of front doors (LED), front footwell lighting (LED), entry lights on the underside of rear doors (white), dashboard contour lighting (multicolor), ambient door lighting (front/rear, multicolor), door contour lighting (front/rear, multicolor), center console storage compartment (multicolor))
- Airbags: Front and rear side airbags with head airbag system and front interaction airbag (The so-called interaction airbag deploys between the front seats, providing protection for the driver and front passenger occupants in the event of a side impact within the system's limits. In a side collision, this largely mitigates the impact between the two front occupants and the front passenger seat when driving alone, thus reducing the risk of injury.)
- Aluminum look in the interior (frame of the control button strip of the center console, the door trim strips front and rear, the elements on the mirror adjustment switch, the window regulator switch and the control buttons of the parking brake in aluminum look)
- Audi drive select (allows the desired vehicle characteristics to be set in various available modes via a separate control element in the switch panel of the center console and via the MMI operating system. This includes adjustments to the steering assistance, engine characteristics or shift points (in vehicles with S tronic), driving dynamics control, and other standard systems. If ordered, optional equipment is also adapted to the selected mode.)
- Deletion of model designation and performance/technology lettering
- Hold assist
- Interior mirror, automatically dimming, frameless
- Camera-based traffic sign recognition (Supports the driver by displaying traffic signs detected within the system's limits, such as speed limits, no-overtaking zones, and temporary speed restrictions, which are within the detection range of the front camera. The traffic sign recognition is displayed automatically in the digital instrument cluster or in the optional Audi virtual cockpit.)
- 2-zone automatic climate control (electronically regulates air temperature, volume and distribution - separate temperature distribution for driver and front passenger side - with sun position-dependent control - automatic recirculation control - dust and odor separating allergen filter - air vents in the rear center console - separate defroster button for faster defrosting of the front and side windows)
- Front center armrest (adjustable in tilt, movable in length)
- Storage and luggage compartment package (lockable glove compartment - storage compartment on driver's side - storage net on the back of the front seatbacks - comfort cupholder - 12-volt socket in the trunk - luggage compartment net - second luggage compartment light on the left in LED (only for A3 Sportback))
- Business package (USB ports with charging function in the rear - Audi connect Navigation & Infotainment plus - Audi phone box - Audi virtual cockpit plus - Smartphone interface (Android Auto and Apple CarPlay) - MMI Navigation plus with MMI touch - Cruise control)
- Wheel: Alloy wheels - 17 inch - 5-parallel spokes (8.0 J × 17, tires 225/45 R 17)
- Wheel: Winter wheels with 4 light alloy wheels, 5 parallel spokes (6.5 J x 17, winter tires 205/50 R17)
- KA2 reversing camera

- Parking assistant with parking aid plus (Using ultrasonic sensors, the system searches for suitable parallel or perpendicular parking spaces. For perpendicular spaces, the system calculates the parking path (forwards and backwards); for parallel spaces, it calculates the entry and exit paths. The driver must accelerate, shift gears, and brake, as well as monitor the parking process. The system handles the steering. Within the system's limits, the surround view displays warnings of obstacles around the vehicle, depending on the driving path. Multi-stage parking maneuvers are supported.)
- Seats: Front seats electrically adjustable (with electric adjustment of seat height, seat longitudinal position, seat and backrest tilt)
- Front seat heating (heats seat and backrest center section (standard seats in fabric), otherwise seat and backrest center section as well as seat side bolsters - individually adjustable in 3 stages for driver and front passenger via direct selection button on the climate control unit)
- Glazing: Sun protection glazing, tinted (rear window, rear door and side windows tinted)
- Seats: Pneumatically adjustable lumbar support with massage function (The lumbar support provides support in the lumbar region through targeted inflation and deflation of three lordosis bladders and is adjustable via lumbar support buttons on the seat. The massage function, with three different programs (wave, stretch, kneading) and three intensity levels, can be switched on and off via the lumbar support buttons with integrated direct massage buttons. Programs and intensity levels can be adjusted via the MMI. Massage duration approximately 10 minutes.)
- Phone: Audi Phone Box
- Phone: LTE support for Audi phone box
- Telephone: Smartphone interface in conjunction with MMI Navigation plus with MMI touch

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Boot lid - Glued / labelled - Remove
2	Front bumper	Front bumper - Scratch(es) - Smart repair
3	Vehicle glazing	Windscreen (Rißbildung) - Broken / torn - repair according to calculation

Wear and tear

No.	Component group	Description
1	2nd wheel set	2nd wheel set (4,2 mm Restprofil) - No deduction
2	Interior	Interior - Scratch(es) - No deduction
3	Rear bumper	Rear bumper - Scratch(es) - No deduction
4	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig
und eingeschränkt möglich.
- Mehrkosten möglich



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents



Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Damage 1: Boot lid / rear door: Boot lid - Glued / labelled - Remove



Damage 1: Boot lid / rear door: Boot lid - Glued / labelled - Remove




Damage 2: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 2: Front bumper: Front bumper - Scratch(es) - Smart repair

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt



Damage 3: Vehicle glazing: Windscreen (Rißbildung) - Broken / torn - repair according to calculation



Damage 3: Vehicle glazing: Windscreen (Rißbildung) - Broken / torn - repair according to calculation