TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 48585508
Order No. / Reference: 27226011
Inspection date: 5 Nov 2026

Manufacturer: Opel	Model: Mokka 1.5 Diesel Business Elegance
VIN: VXKUDYHSKMW054087	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Mokka 1.5 Diesel Business Elegance	
Vehicle Identification number	VXKUDYHSKMW054087
Mileage (Read)	96,403 km
First registration	28 Oct 2021
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	81 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Multipurpose vehicle
Colour / colour code	Diamant Schwarz Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Grey-Dark grey

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	29,600 km
Last service on / at	06/2026 at 96,070 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA242293
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1889 / ADC 00012		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,750 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R17 96H	Summer tyres on Light alloy	Michelin	5mm / 5mm
2)	215/60 R17 96H	Summer tyres on Light alloy	Michelin	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R17 96H	Winter tyres (Without wheel rim)	Goodyear	6mm / 6mm
2)	215/60 R17 96H	Winter tyres (Without wheel rim)	unterschiedliche Hersteller	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 ignition keys, both with remote control and foldable
- Adaptive brake light
- Airbag: Front and side airbags
- Actively controlled air intakes (Active Aero Shutter)
- Electrically adjustable and heated exterior mirrors
- Exterior mirrors in black
- Roof design line in chrome
- Roof spoiler, black
- Diesel particulate filter
- Tachometer
- Electronic brake force distribution (EBD)
- Electric windows front and rear
- Pedestrian protection
- Cruise control with intelligent speed limiter
- Rear shelf
- automatic climate control
- Rear headrests (3), height adjustable
- LED headlights
- Steering column, height and tilt adjustable
- Reading lights, front
- Center armrest, front
- Fatigue detection
- Parkpilot, rear parking aid, with acoustic warning signal when reversing.
- Radio: Multimedia Navigation
- Wheels: Light alloy (4) 5 double spokes 6.5 J x 17 in BiColor Black (with tires 215/60 R 17)
- Keyless locking and starting system "Keyless Open & Start"
- Seat belts
- Seats: Passenger seat 6-way manually adjustable
- Seats: Comfort seats, front
- Seats: Pre-installation for ISOFIX child seat mounting system, rear outer
- 12-volt power outlet
- Ambient lighting
- Traffic sign recognition
- Central locking with remote control
- Storage compartments
- Driver and passenger side airbags
- Airbag: Head airbags, front and rear outer
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Hill Start Assist
- Headliner, Grey
- Decorative strips, silver
- Double boot floor
- Third brake light
- Electronic Stability Program Plus (ESP Plus)
- Front collision warning with automatic city emergency braking and pedestrian detection
- Transmission: 6-speed manual
- Child safety lock in the rear doors, manual
- Headrests (2)
- LED fog lights
- Steering wheel: Leather steering wheel, flattened at the bottom
- Makeup mirror in sun visor, driver and front passenger
- Multi-collision brake
- Opel Connect with telematics services
- Upholstery: Fabric/Premium leather look
- Quickheat rapid heating system
- Radio accessories: Digital radio reception DAB+
- Wheels: Tire repair kit (with tire sealant and 12-volt compressor (without jack))
- Side impact protection
- Speed-sensitive power steering
- Visibility equipment
- Seats: Driver's seat 6-way manually adjustable
- Seats: Rear seat backrest foldable in a 60:40 ratio
- Lane Keeping Assist
- Start/Stop System
- Traction control with engine and brake intervention TC Plus
- Underride protection look, front and rear, in silver
- Tinted heat-insulating glazing

Extra equipment

- Active Drive Assist Plus (manual transmission) in conjunction with Multimedia Navi (Automatic Speed Assist - Front Collision Warning with automatic emergency braking as well as pedestrian and cyclist detection - OpelConnect with telematics services: Emergency call/ breakdown call, vehicle status and information, route and journey information)
- Paint finish: Metallic special color
- Park & Go (Park Pilot, front and rear parking aid with audiovisual warning - 180-degree panoramic reversing camera - blind spot warning and side protection - electrically folding exterior mirrors - ambient lighting)
- Seats: Heated seats, multi-stage, driver and front passenger
- Solar Protect heat-insulating glazing (heavily tinted, in the rear)
- IntelliLux LED Matrix Light (Adaptive LED matrix headlights with individual light distribution and the following functions: - City light - Highway light - Country road light - Static cornering light - Turning light - Parking light - High beam assistant: traffic-dependent dimming taking into account preceding and oncoming road users - Automatic headlight range control)
- Steering wheel: Heated leather steering wheel
- Radio: Multimedia Navi Pro (with 10" color touchscreen display and fully digital 12" driver information display - navigation system with integrated memory - European road map (including Russia and Turkey) - 3D map display - dynamic route guidance via map and/or arrow display - display of points of interest - trip planning - GPS module OpelConnect, including LIVE navigation services: - map updates (via USB) - voice control for audio, telephone and navigation. - radio, Bluetooth, DAB+, USB, hands-free calling.)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Due - Replace
2	Engine	Engine (Ölspuren erkennbar) - Soiled - Clean
3	Side panel - rear left side	Side panel - Scratch(es) - Smart repair
4	Door - front right side	Door - Scratch(es) - Smart repair
5	Rear bumper	Cover - bumper - rear - Scratch(es) - Smart repair
6	Braking system	Brake discs and pads - rear - Corrosion - Replace
7	Braking system	Brake discs and brake pads - front (Korrosion und) - Worn - Replace
8	Body	Body (Hagelschaden) - dent(s) - Repair
9	Bonnet	Bonnet - Scratch(es) - Repair and paint
10	Vehicle glazing	Windscreen - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Door - rear left side	Door - dent(s) - No deduction
2	Rear bumper	Rear bumper - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Der beiliegende Winterreifen sind kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Navigation




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.





Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 1: Equipment: Tirefit filler - Due - Replace



Damage 2: Engine: Engine (Ölspuren erkennbar) - Soiled - Clean



Damage 2: Engine: Engine (Ölspuren erkennbar) - Soiled - Clean




Damage 3: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 4: Door - front right side: Door - Scratch(es) - Smart repair



Damage 4: Door - front right side: Door - Scratch(es) - Smart repair



Damage 5: Rear bumper: Cover - bumper - rear - Scratch(es) - Smart repair




Damage 5: Rear bumper: Cover - bumper - rear - Scratch(es) - Smart repair



Damage 6: Braking system: Brake discs and pads - rear - Corrosion - Replace




Damage 6: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 6: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 6: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 6: Braking system: Brake discs and pads - rear - Corrosion - Replace




Damage 6: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 7: Braking system: Brake discs and brake pads - front (Korrosion und) - Worn - Replace



Damage 7: Braking system: Brake discs and brake pads - front (Korrosion und) - Worn - Replace



Damage 7: Braking system: Brake discs and brake pads - front (Korrosion und) - Worn - Replace



Damage 7: Braking system: Brake discs and brake pads - front (Korrosion und) - Worn - Replace



Damage 7: Braking system: Brake discs and brake pads - front (Korrosion und) - Worn - Replace




Damage 7: Braking system: Brake discs and brake pads - front (Korrosion und) - Worn - Replace




Damage 7: Braking system: Brake discs and brake pads - front (Korrosion und) - Worn - Replace




Damage 8: Body: Body (Hagelschaden) - dent(s) - Repair



Damage 8: Body: Body (Hagelschaden) - dent(s) - Repair



Damage 8: Body: Body (Hagelschaden) - dent(s) - Repair




Damage 8: Body: Body (Hagelschaden) - dent(s) - Repair




Damage 8: Body: Body (Hagelschaden) - dent(s) - Repair



Damage 8: Body: Body (Hagelschaden) - dent(s) - Repair



Damage 8: Body: Body (Hagelschaden) - dent(s) - Repair




Damage 9: Bonnet: Bonnet - Scratch(es) - Repair and paint



Damage 9: Bonnet: Bonnet - Scratch(es) - Repair and paint




Damage 9: Bonnet: Bonnet - Scratch(es) - Repair and paint



Damage 9: Bonnet: Bonnet - Scratch(es) - Repair and paint




Damage 9: Bonnet: Bonnet - Scratch(es) - Repair and paint




Damage 10: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 10: Vehicle glazing: Windscreen - Stone chips - Replace



Wear and tear 1: Door - rear left side: Door - dent(s) - No deduction



Wear and tear 1: Door - rear left side: Door - dent(s) - No deduction



Wear and tear 2: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 2: Rear bumper: Rear bumper - Scratch(es) - No deduction