TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48443647
Order No. / Reference: 27218668
Inspection date: 28 Oct 2026

Manufacturer: Ford	Model: Kuga 2.5 Duratec PHEV VIGNALE
VIN: WF0FXXWPMHPC24409	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Kuga 2.5 Duratec PHEV VIGNALE	
Vehicle Identification number	WF0FXXWPMHPC24409
Mileage (Read)	135,744 km
First registration	6 Mar 2023
Number of holders	1
Next periodical technical inspection	03/2028
(Report on hand)	
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	2,488 ccm / 4
Power	112 kW
Gearbox / Number of gears	Automatic / 1
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Magnetic Grey Metallic
Doors / Seats	5 / 5
Upholstery type	Artificial leather
Colour of upholstery	Anthracite-Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	84 %
Last service on / at	10/2026 at 132,304 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP512509
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BTM 00020		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,320 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/60 R18 104V	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	225/60 R18 104V	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/60 R18 104V	Winter tyres on Light alloy	Continental	6mm / 6mm
2)	225/60 R18 104V	Winter tyres on Light alloy	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 01/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Acoustic Vehicle Alerting System (AVAS)
- Anti-lock braking system
- Passenger airbag deactivation
- Tires: 7.5 J x 18 light alloy wheels (4) in 5x4 spoke design Luster Nickel premium paint finish (with tires 225/60 R 18)
- Fabric headliner
- Roof spoiler
- Tachometer
- Electronic Safety and Stability Program (ESP)
- Lane keeping assist including lane keeping assist
- Electric parking brake with auto hold function
- Ford Easy Fuel
- Ford Power Start Function & Ford Key Free System
- Geofencing - Display of emission zones with Euro 6 and higher in the SYNC navigation device
- Cruise control
- Illuminated glove compartment
- Electric tailgate, sensor-controlled (opens via foot movement)
- Interior mirror, automatically dimming
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- Charging cable for household socket
- Steering wheel: Steering wheel, 3-spoke design, in Sensico synthetic leather
- Rear center armrest with two cup holders
- Front center console with integrated armrest
- Navigation system: Ford navigation system including Ford SYNC 3 (AppLink, Android Auto, Apple CarPlay - 8" touchscreen (20.3 cm screen diagonal) - DAB/DAB+ radio reception (Digital Audio Broadcasting) - 6 speakers - Steering wheel controls - Bluetooth hands-free system and audio streaming - USB port - Voice control for audio and telephone - Acoustic and visual route guidance - Dynamic navigation with enhanced traffic information system - Lane guidance - Road map for Europe)
- Post-Collision Assist
- Pre-Collision Assist
- Tire Pressure Monitoring System (TPMS)
- Rear view camera
- Windscreen wipers with rain sensor
- Headlights with delayed shut-off
- Power steering
- Seats: Passenger seat, 8-way manually adjustable
- Seats: Rear bench seat, sliding, with split-folding backrest
- Seats: Front sports seats with integrated headrests
- Static LED headlights (high beam assist - LED fog lights)
- Carpet floor mats front and rear
- Immobiliser
- Ambient lighting at the front
- Electrically adjustable, heated and folding exterior mirrors (VIGNALE)
- Tires: Tire repair kit (maximum speed 80 km/h when used)
- third brake light
- Roof rails, silver-colored
- 12.3-inch digital instrument panel
- Front door sill trims, Vignale design
- Driving mode switch selective
- Electric front and rear windows with all-around closing function
- Ford EcoCoach
- FordPass Connect
- Luggage compartment cover, roller blind, removable
- Luggage compartment lighting
- Transmission: continuously variable automatic transmission (CVT)
- Heated rear window
- rear window wiper
- Intelligent Protection System (IPS)
- Air conditioning with automatic temperature control
- Front and rear headrests (5) height adjustable
- LED taillights
- Steering column, adjustable in height and reach
- Illuminated makeup mirrors in the driver's and passenger's sun visors
- MyKey key system
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Package: Winter II (Heated windscreen - Heated leather steering wheel - Heated outer rear seats)
- Front and rear parking pilot system
- Upholstery: Premium Sensico upholstery in leather look with leather seat center panels (including driver's seat 10-way electrically adjustable with memory function and electrically adjustable lumbar support - seat back and side bolsters as well as interior applications in leather look)
- Radio accessories: B&O Sound System (560 Watt premium sound system with 10 speakers, including subwoofer - based on the renowned sound and design expertise of Bang & Olufsen)
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Seats: Map pockets on the driver's and front passenger's seat backrests
- Seats: Front seats, individually and variably heated
- Front and rear bumpers in Vignale design
- Variable radiator air intake
- Central locking with remote control and remote luggage compartment release

Extra equipment

- Swiveling towbar (incl. ESP trailer stabilization)
- Paint finish: Special metallic paint finish
- Package: Driver Assistance Package (Automatic Transmission) (Intelligent Adaptive Cruise Control with Traffic Sign Recognition System - Traffic Jam Assist with Stop&Go Function and Lane Keeping Assist - Wrong-Way Driver Warning System - Evasive Steering Assist - Driver Drowsiness Detection - Pre-Collision Assist including Forward Collision Warning System with Cross Traffic Alert - Blind Spot Assist with Emergency Braking Function and Trailer Detection - Active Park Assist with Parking Assist and Semi-Autonomous Vehicle Steering - Front Camera with Split View - Door Edge Protectors - Intelligent Speed Limiter with Speed Limit Display)
- Inductive charging station for mobile devices (The inductive charging station allows you to charge your compatible smartphone while driving without the hassle of connecting it to a cable. The charging station is located in the vehicle's center console and is only activated when it comes into contact with a compatible device. If you place a wallet or other items on the charging station, it remains inactive.)
- Package: Technology (Adaptive LED headlights with glare-free high beam assist and dynamic cornering lights, automatic headlight range control and LED fog lights - Head-up display)
- Panoramic sliding sunroof, electric, including roof console with glasses storage compartment

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Vehicle key with remote control (Batterie) - Empty - Replace
2	Wing mirror - right side	Cap - Scratch(es) - Smart repair
3	Roof	Roof (Vorderteil) - Dent / paintcoat damage - Repair and paint
4	Door - front left side	Door - dent(s) - Repair and paint
5	Headlight	Headlight - right side (Tief) - Scratch(es) - Replace

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Stone chips - No deduction
2	Trim / covers	Door trim - front left side - Deformed - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - charging cable (230V)

Accident damages

No.	Accident
1	Side right

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents




Figure 19: Documents



Figure 20: Additional tyres




Figure 21: Navigation



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Damage 1: Equipment: Vehicle key with remote control (Batterie) - Empty - Replace



Damage 2: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 2: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 3: Roof: Roof (Vorderteil) - Dent / paintcoat damage - Repair and paint



Damage 3: Roof: Roof (Vorderteil) - Dent / paintcoat damage - Repair and paint



Damage 3: Roof: Roof (Vorderteil) - Dent / paintcoat damage - Repair and paint



Damage 4: Door - front left side: Door - dent(s) - Repair and paint



Damage 4: Door - front left side: Door - dent(s) - Repair and paint



Damage 4: Door - front left side: Door - dent(s) - Repair and paint



Damage 4: Door - front left side: Door - dent(s) - Repair and paint



Damage 4: Door - front left side: Door - dent(s) - Repair and paint



Damage 4: Door - front left side: Door - dent(s) - Repair and paint




Damage 5: Headlight: Headlight - right side (Tief) - Scratch(es) - Replace




Damage 5: Headlight: Headlight - right side (Tief) - Scratch(es) - Replace




Damage 5: Headlight: Headlight - right side (Tief) - Scratch(es) - Replace



Damage 5: Headlight: Headlight - right side (Tief) - Scratch(es) - Replace



Wear and tear 2: Trim / covers: Door trim - front left side - Deformed - No deduction



Wear and tear 2: Trim / covers: Door trim - front left side - Deformed - No deduction



Accident 1: Side right




Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right




Accident 1: Side right



Accident 1: Side right



Accident 1: Side right




Accident 1: Side right



Accident 1: Side right




Accident 1: Side right




Accident 1: Side right



Accident 1: Side right




Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right




Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum



Accident 1: Side right