TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48513455
Order No. / Reference: 27236580
Inspection date: 4 Nov 2026

Manufacturer: Ford	Model: Transit Custom 320 L2H2 LKW VA Trend
VIN: WF0YXXTTGYLD86903	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit Custom 320 L2H2 LKW VA Trend	
Vehicle Identification number	WF0YXXTTGYLD86903
Mileage (Read)	155,790 km
First registration	14 Jan 2021
Number of holders	1
Next periodical technical inspection	04/2027
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	96 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frost-Weiß
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	Available / incomplete	**Next maintenance in**	7,000 km
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FV083997
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BMU 05703		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,200 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 109T	Summer tyres on Steel rim with wheel cover	Goodyear	6mm / 6mm
2)	215/65 R16 109T	Summer tyres on Steel rim with wheel cover	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	215/65 R16 109T	Summer tyres on Steel	Goodyear	7 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- Headliner in driver's cab
- Tachometer
- Third brake light
- Front electric windows
- Ford Easy Fuel
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Transmission: 6-speed transmission
- Interior lighting with delay circuit
- Paint finish: Solid color paint
- Cargo area floor: Vinyl floor covering, sealed, "Easy Clean"
- Emergency brake assist including emergency brake light
- Particulate filter: diesel particulate filter
- Wheels/Tires: Spare wheel, steel wheel
- Headlights: Halogen projector headlights
- Sliding door: Sliding door, right
- Mud flaps front and rear
- Low side paneling
- Seat belts
- Power outlet: 12-volt connection
- Lashing eyes 8
- Heat-insulating glazing, lightly tinted
- Auxiliary heater, electric
- Driver's side airbag
- On-board computer
- roof, high
- Double-leaf rear door with 180° opening angle (without window)
- Electronic Stability Program (ESP) with Traction Control System (TCS)
- FordPass Connect
- Generator, 240 A
- Cruise control including leather steering wheel
- Lockable glove compartment with lid
- Front air conditioning
- Cargo area lighting with activatable switch-off delay
- Steering column, adjustable in height and reach
- Package: Style-Color Package
- Wheel trims
- Wheels: Steel wheels 6.5 J x 16 with 215/65 R 16 R tires
- Sliding door entry light automatically illuminates when the door is opened
- Side protection strips
- Power steering
- Start-stop system
- Front bumper in body color
- Immobiliser
- Central locking with remote control
- Second key with remote control

Extra equipment

- Package: Service Line Light (shelving system on the left side of the vehicle - screen-printed wooden floor in the cargo area (the standard lashing eyes are omitted))
- Reversing camera with front and rear parking pilot system with fog lights (with image transmission of the rear driving path in the multifunction display [additionally with coupling aid in conjunction with trailer hitch (extra charge)] with high-mounted LED exterior light downlight)
- Seats: Seat package 17A - Partition (load-through flap), without window (Custom Truck Trend (driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - double passenger seat with storage compartment under individually foldable seat cushions - height-adjustable headrests - integrated tray in the double passenger seat (foldable) - heated driver's seat - heated passenger seat (outer seat) - inner armrest for driver - manual lumbar support (driver's seat) - passenger and side airbags and front head/shoulder airbags - TREND seat cover: fabric)
- LED lights in the cargo area
- Package: Smoker (cigarette lighter and ashtray)
- Radio: Audio System 24: Ford audio system including Ford SYNC 3 with AppLink, DAB/DAB+, navigation system. (Radio (FM/AM) 8" touchscreen multifunction display (20.32 cm), 4 speakers, FordPass Connect Wi-Fi hotspot, integrated control panel and audio remote control on the steering wheel, Ford SYNC 3 with touchscreen (hands-free system with voice control, SMS readout/sending function, Bluetooth, Emergency Assistance...), AppLink (advanced voice control, privacy mode, Android Auto and Apple CarPlay support, capacitive touchscreen technology,...), dynamic navigation, lane guidance, road map for Western Europe)
- Towing device (fixed, 13-pin socket - incl. trailer stability control (TSC))

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Braking system	Brake fluid - No evidence - No deduction
3	Documents	Service book - Incomplete - No deduction
4	Wheel / tyres	Wheel cover - front right side - Scratch(es) - Replace
5	Trim / covers	Boot lid - interior trim (Links) - Broken / torn - Replace
6	Trim / covers	Boot lid - interior trim (Rechts) - Broken / torn - Replace
7	Sill - right side	Sill - Scratch(es) - Smart repair
8	Seat - front	Seat cover - left side - Broken / torn - Replace
9	Front bumper	Front bumper - Scratch(es) - Paint
10	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - Repair and paint
11	Boot lid / rear door	Rear door - left side - Scratch(es) - Paint
12	Sliding door, right	Sliding door - Dent / paintcoat damage - Repair and paint
13	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Side panel - rear left side	Side panel - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster




Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents



Figure 19: Navigation




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.





Figure 37: Misc.



Figure 38: Misc.



Damage 4: Wheel / tyres: Wheel cover - front right side - Scratch(es) - Replace



Damage 4: Wheel / tyres: Wheel cover - front right side - Scratch(es) - Replace



Damage 5: Trim / covers: Boot lid - interior trim (Links) - Broken / torn - Replace



Damage 6: Trim / covers: Boot lid - interior trim (Rechts) - Broken / torn - Replace



Damage 7: Sill - right side: Sill - Scratch(es) - Smart repair



Damage 7: Sill - right side: Sill - Scratch(es) - Smart repair



Damage 8: Seat - front: Seat cover - left side - Broken / torn - Replace



Damage 9: Front bumper: Front bumper - Scratch(es) - Paint



Damage 9: Front bumper: Front bumper - Scratch(es) - Paint



Damage 9: Front bumper: Front bumper - Scratch(es) - Paint



Damage 9: Front bumper: Front bumper - Scratch(es) - Paint



Damage 10: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 10: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 10: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 10: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 10: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 10: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 11: Boot lid / rear door: Rear door - left side - Scratch(es) - Paint



Damage 11: Boot lid / rear door: Rear door - left side - Scratch(es) - Paint



Damage 11: Boot lid / rear door: Rear door - left side - Scratch(es) - Paint



Damage 11: Boot lid / rear door: Rear door - left side - Scratch(es) - Paint



Damage 11: Boot lid / rear door: Rear door - left side - Scratch(es) - Paint



Damage 11: Boot lid / rear door: Rear door - left side - Scratch(es) - Paint



Damage 12: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 12: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 12: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 12: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Wear and tear 2: Side panel - rear left side: Side panel - dent(s) - No deduction



Wear and tear 2: Side panel - rear left side: Side panel - dent(s) - No deduction