TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48127745
Order No. / Reference: 27025027
Inspection date: 14 Oct 2026

Manufacturer: Volvo	Model: XC60 B5 D AWD Geartronic RDesign
VIN: YV1UZK2VCN1940609	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volvo XC60 B5 D AWD Geartronic RDesign	
Vehicle Identification number	YV1UZK2VCN1940609
Mileage (Read)	119,000 km
First registration	27 Oct 2021
Number of holders	1
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	1,969 ccm / 4
Power	173 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Silver Dawn Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Grey

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	62 Tag(e)
Last service on / at	04/2026 at 106,336 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GC682430
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	9101 / BPP 00023		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,520 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 105V	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	235/55 R19 105V	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R18 107H	Winter tyres on Light alloy	Dunlop	5mm / 5mm
2)	235/60 R18 107H	Winter tyres on Light alloy	Dunlop	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 12-volt socket at the front
- Airbag, driver's knee airbag
- All-wheel drive (AWD) (via electronically controlled multi-plate clutch (5th generation) with Instant Traction)
- Android infotainment system (9" touchscreen (22.9 cm diagonal) - Bluetooth hands-free system incl. audio streaming - Digital vehicle owner's manual - Digital radio reception (DAB+) - 2 USB-C ports (compatible with Apple iPod/iPhone/iPad))
- Anthracite headliner
- Automatic tailgate (electric)
- Cargo area roller blind
- Central locking with two remote controls and integrated emergency keys (automatic locking of doors while driving (can be deactivated) - comfort opening/closing of side windows and, if applicable, sunroof via remote control - panic function integrated into the remote control)
- Charging box under the cargo floor
- Child safety lock (rear doors)
- Digital instrumentation 2nd generation (Full graphic 12.3" driver display (31.2 cm diagonal) with two variable round instruments and information display (e.g. for navigation map view))
- Electrically adjustable and heated exterior mirrors, left and right
- Electronic differential lock
- Emergency brake lights (brake lights flash rapidly during heavy deceleration; hazard warning lights are automatically activated at speeds below 10 km/h)
- Fog light
- Headrests (5) front and rear
- Heated rear window
- Hill Start Assist (HSA)
- IDIS - Intelligent Driver Information System (delays incoming calls or vehicle information in potentially dangerous situations)
- Immobiliser
- ISOFIX mounting for the outer rear seats
- Keyless Drive (electronic access system) with sensor-controlled tailgate, illuminated door handles and puddle lights
- Lashing eyes in the luggage compartment (foldable)
- LED headlights "Thor's Hammer" with high beam assist and integrated LED daytime running lights
- LED turn signals integrated into the exterior mirrors
- Luggage net
- Phone: Inductive smartphone charging system (Wirelessly charges smartphones that support the QI standard on a charging pad)
- Preparation for Trailer Stability Assist (TSA)
- Radio accessories: Digital radio reception (DAB+)
- Rain sensor
- Rear center armrest (foldable) (with cup holders)
- Rear headrests foldable (electrically)
- Rear parking assist with automatic braking intervention (rear)
- Roof edge spoiler
- Roof rails in high-gloss black (integrated)
- ABS - Anti-lock Braking System (with EBV)
- Airbag, side airbags for driver and front passenger and head/shoulder airbags (iC) for all occupants
- Aluminum door sill plates with Volvo lettering at the front
- Aluminum insert, metal mesh
- Ambient lighting (Extended interior lighting with: - Ambient lighting front and rear - Exit lights front and rear - Work light on the tailgate - Illuminated door pockets and door openers front and rear - Rear footwell lighting - Rear reading lights)
- Automatic climate control with separate temperature control for driver and front passenger (and additional air vents for the 2nd row of seats (integrated in the B-pillar))
- CleanZone air quality system with activated carbon filter (automatic recirculation and pre-ventilation of the interior when the vehicle is unlocked)
- Cruise control system (and variable speed limiter)
- Diesel particulate filter
- Drive Mode (driving mode settings for engine, transmission, steering, brakes and suspension: Comfort, Off Road)
- Driver and passenger side airbags with two-stage deployment system
- Electric parking brake
- Electric windows front and rear (with auto-down and auto-up function)
- Electrically folding exterior mirrors
- Electronic Stability Control (ESC)
- First aid kit and warning triangle
- Fog sensor for automatic activation of the defroster function
- Front center armrest with integrated storage compartment and cup holders
- Glazing: Colored glazing
- Google Services with navigation (navigation via Google Maps, Google Assistant, Google Play Store and unlimited data (includes data for map updates, app downloads and streaming services) for the first 4 years)
- Hill Descent Control (HDC)
- Illuminated makeup mirror for driver and front passenger
- Interior and exterior mirrors automatically dimming
- Interior lighting (headliner, front reading lights, front ambient lighting, front footwell, storage compartment behind center console, glove compartment and luggage compartment)
- Keyless Start (electronic engine start system)
- On-board computer (with vehicle control functions)
- Outdoor temperature display
- Package: Winter Package (front seat heating - steering wheel heating)
- Passenger side airbag can be deactivated
- Power outlet (12-volt connection in the luggage compartment)
- Radio accessories: Two USB-C ports on the back of the center console

- Safety Assistance (Automatic Emergency Braking System - Connected Safety - Driver Alert - Attention Warning - Distance Warning (only in conjunction with Head-up Display) - Variable Speed Limiter - Cruise Control - Lane Keeping Aid (LKA) - Active Lane Keeping Assist - Oncoming Lane Mitigation - Ready to Drive Notification - Road Edge Detection - Road Sign Information (RSI) - Traffic Sign Recognition (only in conjunction with Navigation))
- Seats: Adjustable (electric) leg rest for driver and front passenger seats
- Seats: Driver's seat electrically adjustable (with memory function for driver's seat and exterior mirror settings (stored in the remote control))
- Sport front and rear apron
- Sport pedals
- Start/Stop technology
- Steering wheel: Sports steering wheel
- third brake light
- Tire pressure monitoring system (with tire-specific pressure loss warning)
- Transmission: 8-speed Geartronic automatic transmission
- Upholstery: Part-leather/mesh-textile sports seats (including rear center armrest)
- Wheels: 19" 5-twin-spoke sport design alloy wheels, diamond cut/ high-gloss black (tires 235/55 R19 with rims 7.5 x 19")
- Wheels: Tire sealant (Incl. 12-volt compressor, maximum speed 80 km/h)
- WHIPS whiplash protection system (including immersion protection on all seats and energy-absorbing front seat cushions)
- Window surround in high-gloss black
- Radio: Audio system High Performance Sound (330 watts of power - 10 speakers)
- Rear seats in a 40/60 split or completely foldable with pass-through function
- Run-off Road Protection (preventive protection system in case of unintentional leaving the road or impending rollovers including pre-activation of the seat belt tensioners, deactivation of the battery (plug-in hybrid only) and door unlocking)
- Safety braking system with disc brakes all around (internally ventilated) (automatic brake system pre-tensioning, brake assist and automatic hold function)
- Seat belts (active seat belts with belt tensioners, pre-activation of the belt tensioners only in conjunction with IntelliSafe Surround - belt height adjustment front - warning tone/indication when seat belts are not fastened (for all seats))
- Seats: Driver and front passenger seats height adjustable (electrically) (including manual tilt adjustment)
- Seats: Lumbar support (4-way electrically adjustable) for driver and front passenger seats
- Speed-sensitive power steering
- Sport exterior mirrors in high-gloss black
- Sport front grille with horizontal struts and surround in high-gloss black
- Stainless steel loading sill protector in the luggage compartment
- Steering wheel adjustable for height and reach
- Steering wheel: Multifunction buttons on the steering wheel
- Textile floor mats: Sport textile floor mats front and rear
- Volvo On Call (alerting the Volvo On Call service center at the touch of a button, as well as additional convenience services via the smartphone app, such as locking and unlocking the vehicle, direct start of pre-conditioning of the interior and retrieval of the high-voltage battery charge status)

Extra equipment

- Towbar (semi-electric)
- Luggage compartment tray mat (accessory)
- Package: Driver Assistance Package
- Package: Parking Assistance Package (front and rear parking aid - reversing camera)
- Panoramic glass sliding sunroof with lifting function (electric) (with integrated, continuously adjustable sunshade)
- Parking camera with 360° surround view (including front, side and rear parking aid with automatic braking intervention (rear))
- Windscreen, heater
- Paint finish: Metallic paint
- Package: Lighting Package (LED fog lights (integrated into the front spoiler) - headlight cleaning system - full LED headlights "Thor's Hammer" Active High Beam with extended high beam, dynamic cornering lights, intelligent high beam assist with adaptive headlight range control and integrated LED daytime running lights)
- Stainless steel bumper protection strip (accessory)
- Winter complete wheels 18 inch (ACCESSORIES)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Equipment	Tirefit filler - Expired - Replace
3	Sill - right side	Sill - Scratch(es) - Smart repair
4	Boot lid / rear door	Boot lid - Scratch(es) - Smart repair
5	Front bumper	Air-inlet grille - Scratch(es) - Smart repair
6	Wheel / tyres	Alloy rim - rear left side - Scratched - Replace

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Stone chips - No deduction
2	Door - front left side	Door edge - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Interior - Luggage net

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Additional tyres




Figure 18: Navigation




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Damage 2: Equipment: Tirefit filler - Expired - Replace




Damage 3: Sill - right side: Sill - Scratch(es) - Smart repair



Damage 3: Sill - right side: Sill - Scratch(es) - Smart repair



Damage 4: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair



Damage 4: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair



Damage 5: Front bumper: Air-inlet grille - Scratch(es) - Smart repair



Damage 5: Front bumper: Air-inlet grille - Scratch(es) - Smart repair



Damage 6: Wheel / tyres: Alloy rim - rear left side - Scratched - Replace



Damage 6: Wheel / tyres: Alloy rim - rear left side - Scratched - Replace