AUDI A3 SPORTBACK

Vehicle information

Make:	**AUDI**	License:	**2CFC366**
Gearbox:		Body color:	
Model:	**A3 SPORTBACK**	VIN:	**WAUZZZGY5NA098115**
Fuel type:		Power:	**110 kW**
Version:	**2.0 35 TDI 110KW S TRONIC S LINE BUS. ED**	First registration	**30/06/2022**
Mileage:	**158952 km**	N° of doors:	


Damage summary





Front	2
Interior	3
Left	5
Rear	2
Right	3
Roof & others	3


Commercial pictures
























VIN equipment according to manufacturer information

Airbag	Central consol	Central locking	Distance control
Electric adjustable mirrors	Fog lights	GPS	Integrated child seat
Power steering	Rain sensor	Rims alloy	Steering wheel leather
Steering wheel multifunctional	Telephone	Windows electric functioning	

Options according to the inspector

GPS	**Yes**

Damages

Bodywork
Damaged
Acceptable
Roof & others













Bonnet
Stone chip(s)
Acceptable
Front



Bumper F
Scratch(es)
Paint
Front







Bumper moulding R
Scratch(es)
Replace
Rear





Door FL
Repaired
Acceptable
Left



Door FR
Repaired
Acceptable
Right



Door RL
Repaired
Acceptable
Left



Door RR
Dent(s)
Acceptable
Right





Interior
Damaged
Acceptable
Interior



Interior
Stain
Cleaning
Interior
















Roof
Dent(s)
Acceptable
Roof & others

Roof
Hail damage
Paintless dent repair (hail)
Roof & others



Sill trim L
Scratch(es)
Replace
Left





Sunblind
Broken
Replace
Interior




Tyre repair kit
Missing
Replace
Rear



Wing FL
Repaired
Acceptable
Left



Wing FR
Repaired
Acceptable
Right



Wing RL
Repaired
Check
Left



Tyres

Front Left
Summer
Aluminium
225/45/17/94/Y
Goodyear
4.0 mm
Front Right
Summer
Aluminium
225/45/17/94/Y
Goodyear
4.0 mm
Rear Left
Summer
Aluminium
225/45/17/94/Y
Goodyear
5.0 mm
Rear Right
Summer
Aluminium
225/45/17/94/Y
Goodyear
5.0 mm

Checks

Category	**Passenger Car**	Certificate of Conformity	**Yes**
Compressor	**Yes**	Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**0**	Number of keys total	**2**
Registration Certificate Car (BE)	**Yes**	Registration Certificate Home (BE)	**Yes**
Repair kit	**No**	Reset to factory settings	**No, not possible**
Type of Maintenance book	**Digital maintenance**		

VIN detail - *If the description in the language of your choice is not available, the French description is shown*

ABS (antiblocage des freins)	Accoudoir central avant	AdBlue
Air conditionné	Airbag conducteur	Airbag passager
Airbags de tête	Airbags genoux	Airbags latéraux aux sièges avant
Allumage automatique des phares suite obscurité	Antivol électronique transpondeur Audi	APS (Acoustic Parking System) arrière
Audi Connect Navigation & Infotainment (3 ans)	Audi Music Interface	Audi pre sense front
Audi Smartphone Interface (si MMI Nav. Plus)	Boîte à gants éclairée	Ceintures avant réglables en hauteur
Ciel de toit en tissu	Climatisation électronique 2 zones	Contours de fenêtres noirs
Contrôle de l'application ceinture de sécurité AR	Contrôle de la pression des pneus	Cruise Control (ready for adaptive cruise control)
Désactivation manuelle de l'airbag passager	Détecteur de pluie	Dossier de banquette arr. rabattable en 2 parties
DPF (Diesel Particle Filter)	Eclairage DEL pour le coffre	EDS
Encarts décoratifs Micrometallic platina	ESC (Contrôle électronique de la stabilité)	Feux de jour DEL
Fonction start/stop	Frein à main électromécanique active par bouton	Garantie 3 ans/120.000 km
Indicateur d'occupation de siège	JAV 5 branches design 8Jx17''+225/45 R17 91Y	Kit crevaison et compresseur 12v
Lane Departure Warning	Limiteur de vitesse	MMI Radio Plus DAB+ AM/FM 6HP VC
Moulures de seuil avec insert en aluminium à l'avant et à l'arrière+éclairées+logo S à l'avant	Outillage de bord	Pack Business
Pack Business (convention A/B/C/D/E/F/H/P)	Pack Business (si Sans APS AR)	Pack Business (si Sans APS AR) (convention)
Pare-brise en verre athermique teinté vert	Phares avant à technologie DEL	Plafonnier central AR à extinction temporisée
Plafonnier central AV à extinction temporisée	Pommeau de changement de vitesse en cuir	Pré-installation GSM Bluetooth
Préparation pour MMI Navigation Touch	Prises 12V AV/AR	Rétroviseurs électriques
Rétroviseurs extérieurs à dégivrage électrique	Rétroviseurs extérieurs couleur carrosserie	Sécurité enfant aux places arrière
Servotronic	Siège conducteur réglable en hauteur	Siège passager réglable en hauteur
Spoiler arrière	Suspension sport (abaissé 15 mm)	Système de navigation MMI Plus
Tapis de coffre	Tapis de sol complémentaires AV/AR	Tissu Index
Trousse de secours avec triangle de présignalisation	Verrouillage central 'Keyless-Go' sans safelock	Vitres électriques arrière
Vitres électriques avant	Vitres teintées	Volant multif.3 branches cuir+palettes (si Busin.)
Volant multifonction cuir 3 branches cuir+palettes	Volant multifonctions	Volant sport gainé de cuir

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.