TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48407468
Order No. / Reference: 27211095
Inspection date: 28 Oct 2026

Manufacturer: Volkswagen	Model: Transporter T6.1 Kurz
VIN: WV1ZZZ7H8PX027113	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Transporter T6.1 Kurz	
Vehicle Identification number	WV1ZZZ7H8PX027113
Mileage (Read)	58,099 km
First registration	24 Mar 2023
Number of holders	1
Next periodical technical inspection	04/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	66 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Reflexsilber Metallic
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Grey

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	11,500 km
Last service on / at	06/2026 at 49,313 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS348950
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CKI 20661		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,800 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 105T	Summer tyres on Steel rim with wheel cover	Hankook	6mm / 6mm
2)	205/65 R16 105T	Summer tyres on Steel rim with wheel cover	Hankook	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage and stowage boxes
- Electrically adjustable and heated exterior mirrors
- Hill Start Assist
- third brake light
- Electronic Stability Program
- Chassis: Suspension and damping, standard
- Fresh air system with multi-stage fresh air blower
- Tailgate without window
- Child safety lock, electrically operated
- Fuel tank with a 70-liter tank capacity
- Multi-collision brake
- Particulate filter: Soot particle filter for diesel engines
- "Composition Audio" radio with TFT display (monochrome)
- Radio accessories: 2 speakers (wideband)
- Wheels/Tires: Steel wheels 6.5 J x 16 in 20-hole design
- Wheels/Tire Accessories: Wheel covers for 16" wheels
- Sliding door in the passenger/cargo compartment: sliding door on the right
- electromechanical power steering
- Start-stop system
- Telephone: Mobile phone interface
- Lashing eyes for securing cargo
- Green thermal insulation glazing
- Registration as a truck
- Airbag for driver and front passenger
- Exterior mirrors, left and right convex
- Floor coverings: Rubber floor covering in the driver's cab
- Tachometer
- Chassis: 16" chassis with 16" brake system
- Electric windows, front
- Transmission: 5-speed transmission
- Heating and ventilation system in the driver's cab
- Headrests (2)
- Headlight range control
- Non-smoking version
- Upholstery: Seat covers in fabric, "Double Grid" design
- Radio: Digital radio reception (DAB+)
- Wheels/Tires: 205/65 R 16 C 107/105 T, optimized for low rolling resistance
- Wheels: Tire Mobility Set
- Keys for locking system: 2 remote control flip keys
- Crosswind assist
- Seat belts: Three-point automatic seat belts
- Daytime running light
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking with remote control and interior operation

Extra equipment

- Rigid towbar (including trailer stabilization)
- Rear wing doors without windows (Rear wing doors without window cutouts - Rear wing door locking mechanism with internal unlocking function - Without rear window - Without interior safety mirror)
- Package: Cargo area package (partition wall, high - double passenger seat on the right, with under-loading function - without child safety locks in the passenger compartment - universal wooden floor in the cargo area with loading edge protection, rear - reinforced lashing eyes for securing cargo (ISO 27956) - step lighting in the passenger/cargo area)
- "Bulli" lettering on the fender, no lettering on the rear
- Battery/Generator Capacities: Higher Battery and Generator Standard
- Air conditioning with manual control in the driver's cab
- Paint finish: Metallic
- Multifunction display "Plus" with fatigue detection (Multifunction display "Plus" with black and white display)
- ParkPilot in the front and rear areas
- Radio "Ready 2 Discover" including "Streaming & Internet" (voice control - 2 USB interfaces (Type C) in the dashboard - Radio "Ready 2 Discover" with 20.3 cm (8 inch) color touchscreen including "Streaming & Internet" - navigation function/preparation - 4 speakers: 2 tweeters, 2 woofers - Wired & Wireless App-Connect)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Sliding door, right	Sliding door - dent(s) - Smooth repair work
2	Door - front right side	Door - dent(s) - Smooth repair work
3	Side panel - rear left side	Side panel - dent(s) - Smooth repair work

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Wheel cover - front right side - Scratched - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side - left, Side right, Provided by user / customer, from 20 Jun 2023	5.773,93 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: VIN



Figure 13: Mounted tyres




Figure 14: Documents



Figure 15: Navigation



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.




Figure 32: Misc.



Damage 1: Sliding door, right: Sliding door - dent(s) - Smooth repair work



Damage 1: Sliding door, right: Sliding door - dent(s) - Smooth repair work




Damage 1: Sliding door, right: Sliding door - dent(s) - Smooth repair work



Damage 2: Door - front right side: Door - dent(s) - Smooth repair work



Damage 2: Door - front right side: Door - dent(s) - Smooth repair work



Damage 2: Door - front right side: Door - dent(s) - Smooth repair work




Damage 2: Door - front right side: Door - dent(s) - Smooth repair work




Damage 3: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 3: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 3: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Wear and tear 1: Wheel / tyres: Wheel cover - front right side - Scratched - No deduction



Wear and tear 1: Wheel / tyres: Wheel cover - front right side - Scratched - No deduction



Wear and tear 1: Wheel / tyres: Wheel cover - front right side - Scratched - No deduction