APPRAISAL REPORT



VEHICLE IDENTIFICATION

Make:	VOLKSWAGEN
Model / version:	TOURAN
Wine:	WVGZZZ1TZNW017637
Plate:	2CJB383
Mileage:	131632
First registration:	05/08/2022
Color:	reflex silver

ADDITIONAL INFORMATION




Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book	
Number of keys:	2
Original key:	✓

PICTURES












































WINE INFORMATION

8 speakers	Bluetooth	Sequential transmission
7 reports	Automatic headlights	Fog lights
Headlight washers	Chrome window surround	Material: alloy
Reference letter (J)	Front diameter 16	Rear diameter 16
Front width 6.5	Rear width 6.5	Front diameter 16
Rear diameter 16	Front height 60	Rear height 60
Forward speed index V	Rear speed index V	Front width 205
Rear width 205	Rear air conditioning	3-zone automatic climate control
Air conditioning refrigerant 1234YF	Front center armrest	Rear center armrest
Chrome interior finish	On-board computer	Essence
1498 cm3	1.50 liters	110 kW
150 hp	140 Amp Alternator	Metallic varnished

Automatic day/night left rearview mirror	Automatic day/night right-side rearview mirror	Electrically folding mirrors
Automatic day/night interior rearview mirror	Heated front left seat	Heated front seats
Height-adjustable front left seat	Siège avant gauche à réglage électrique	Siège avant gauche à réglage lombaire
Siège avant droit rabattable	Sièges avant massants	Garnitures tissu et Alcantara
Volant cuir	Volant chauffant	Volant multifonction
Aide au stationnement avant	Aide au stationnement arrière	Caméra arrière de recul
Régulateur et limiteur de vitesse	Régulateur automatique de la distance	Equipement Stop & Start
Ouverture du coffre électriquement	Pare-brise chauffant	Lunette arrière teintée foncée
Vitres portes arrière teintées foncées	Vitres de custode teintées foncées	détecteur de pluie essuie-vitre
Fixotoit chromé	Protection piéton	Freinage d'urgence assistée autonome (urbain)
Avertisseur de collision avant	depuis 07.22	éclairage périphérique Ambiente
Infotainment-System (MIB3)	console pavillon avec vide-poches	radio avec récepteur digital
tablette rabattable dans les dossiers des sièges av	plancher de chargement modulable	filet de séparation
réservoir à charbon actif (EVAP)	ceintures de sécurité ar avec prétensionneurs	barre stabilisatrice 25,4 mm
enjoliveurs inf du pare-chocs av chromés	poignées de porte livrées avec couche de fond	norme anti-pollution Euro 6 AP

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	3 mm		205/60R16 96V	Summer		?
Front right	3 mm		205/60R16 96V	Summer		?
Rear left	3 mm		205/60R16 96V	Summer		?
Rear right	3 mm		205/60R16 96V	Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Interior	Dirty
2	Boot cover	Grooved
3	Bumper F	Grooved
5	Cap	Scratches
6	Windscreen - Destickeren	Not original part
7	Outside rear-view mirror housing L	Scratches
8	Bumper R	Grooved
9	Tailgate / Boot	Teeth)
10	Alloy rim RR	Grooved
11	Roof - Daklijst R	Teeth)
12	Inner door sill RR	Teeth and scratches

Total: 11

ACCEPTABLE / NOT TO BE INVOICED

#	Rental	Damage type	Renta®	Repaired	Already invoiced
4	Bodywork	Teeth and scratches	✓	✗	✗

Total: 1

DAMAGE DETAILS

1 - Interior - Dirty










2 - Boot cover - Grooved





3 - Bumper F - Grooved







5 - Beanie - Velcro(s)




6 - Windscreen - Ontstickeren - Not original part






7 - Outside rear-view mirror housing L - Scratch(es)






8 - Bumper R - Grooved





9 - Tailgate / Boot - Tooth(s)



10 - Alloy rim RR - Grooved





11 - Roof - Daklijst R - Dent(s)




12 - Inner door sill RR - Dent(s) and scratch(es)







4 - Bodywork - Dent(s) and scratch(es) - Renta®














SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

16/10/2026 08:42

