Macadam Austria GmbH
Europaplatz 2/1/2
1150 Wien

Inspection location
Lagermax - AT - Straßwalchen
Lagermax Str. 1
5204 Straßwalchen

Inspection date: 25 Sept 2026
Protocol number: **47774743**

WBA31BL060WX00987

Vehicle details

Operator		**Inspection condition**	sufficient
License number		**Mileage (Read)**	227,277 km
Manufacturer	BMW	**Next maintenance in**	6,000 km
Type / Model	520d	**Main inspection**	11/2026
Vehicle Identification number	WBA31BL060WX00987	**Power**	140 kW
Engine displacement	1,995 ccm	**Cylinder**	—
First registration	6 Nov 2020	**Upholstery**	Leather
Last maintenance	05/2026, 207,709 km	**Paintwork**	Blue
Fuel type	Diesel	**Gearbox**	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Front bumper	Front bumper (Ziehrleiste) - Broken / torn - Replace
2	Wheel / tyres	Alloy rim - front right side - Scratched - Smooth repair work
3	Wheel / tyres	Tyre - right (Winter unter 5,5mm) - Does not meet the leasing specifications - Replace
4	Front bumper	Front bumper - Scratch(es) - repair/paint (S3)
5	Roof	Roof - Scratch(es) - repair/paint (S3)
6	Bonnet	Bonnet - Scratch(es) - repair/paint (S3)

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratched - No deduction

Missing parts

Missing part

Detected repainting

No.	Location

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	245/45 R18	Pirelli	Winter tyres	6mm - 6mm	Not o.k.	
2	275/40 R18	Pirelli	Winter tyres	4mm - 4mm	Not o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Standard equipment

Code	Description
-	12V power outlet
-	2-year warranty
-	Air Breather
-	Airbag for driver and front passenger
-	Aluminum door sill trims with fine brushed finish and BMW lettering, front and rear
-	Anti-lock braking system (ABS) 3rd brake light in LED technology
-	Attention assistant
-	Automatic climate control with 2-zone regulation
-	BMW Live Cockpit Plus
-	Brake assist
-	Brake energy recuperation
-	Brake pad wear indicator
-	Bumper system
-	Center armrest in the rear
-	Center lock switch
-	Central locking system including 2 remote controls
-	Chromium circumference kidney
-	Condition Based Service
-	Crash sensor
-	Cruise control with braking function
-	DAB tuner
-	Diesel particulate filter
-	Double wishbone front axle
-	Double-tone fanfare
-	Double-walled/dual-flow
-	Driving experience switch
-	Dynamic brake lights
-	Dynamic Stability Control (DSC)
-	electric window regulator
-	Electromechanical parking brake with automatic hold function
-	Electronic immobilizer (EWS)
-	Enhanced telephony with extended smartphone connectivity
-	Extended exterior mirror package
-	Exterior components painted in body color (door handles)
-	Exterior mirrors, exterior mirror housings in body color, electrically adjustable and heated, aspherical, 17" alloy wheels V-spoke 618
-	Favorite keys
-	Front and rear armrests in the center console with storage compartment
-	Front grille with one-piece chrome kidney surround and black kidney bars
-	Grab handles integrated into the roof lining at the rear with coat hooks

Code	Description
-	Hands-free device with USB interface
-	Head airbags for the 1st and 2nd rows of seats
-	Headlight range control
-	Headrests for all seats
-	Heat/sun protection glazing
-	Heated windshield washer nozzles
-	Home lights
-	Integrated operating instructions
-	Interior mirror automatically dimming
-	Interior trim strips in dark matte oxide silver with pearlescent chrome accent strip
-	Internally ventilated front and rear brake discs
-	ISOFIX child seat attachment
-	Keyless engine start
-	Knee airbag
-	Lashing eyes
-	LED headlights
-	LED taillights
-	Light-on warning, 5 seats
-	Lockable glove box
-	Micro/activated carbon filter
-	Misfueling protection for diesel vehicles
-	Model lettering
-	Multi-link rear axle
-	Non-smoking package
-	Oil level and quality sensor
-	On-board computer
-	Park Distance Control (PDC)
-	Partially electric seat adjustment for driver and front passenger
-	Passive pedestrian protection
-	Personal Profile
-	Rain sensor and automatic headlight control
-	Rear center console iDrive controller
-	Rear doors with mechanical child safety lock
-	Roof trim and bumper)
-	Safety battery terminal
-	Seat backrest with folding pocket
-	Servotronic
-	Side airbag for driver and front passenger
-	Side impact protection
-	Speed Limiter
-	Sport leather steering wheel
-	Standard seat for driver and passenger

Code	Description
-	Start/Stop button
-	Steering column adjustment
-	Stereo speaker system
-	Sun visor with slip pocket and make-up mirror
-	Three-point seat belts
-	Tire Pressure Monitoring System (RPA)
-	tire repair kit
-	Tool set
-	Two cup holders each in the front and rear.
-	USB port
-	Velour floor mats
-	visible trapezoidal exhaust tailpipe
-	Warning triangle with first aid kit
-	Welcome light
-	Window frame and window shaft cover (M550i/d)

Extra equipment

Code	Description
05AV	Active Guard
08TF	Active pedestrian protection
0230	Additional scope EU-specific
A090	AGM battery 90 Ah
0302	Alarm system
04UR	Ambient interior lighting
0775	Anthracite headliner
0534	Automatic air conditioning
02TE	Automatic transmission with paddle shifters
0536	Auxiliary heating
03DS	BMW Display Key
05AZ	BMW Laserlight
01WX	BMW light alloy wheel double spoke 662M FG
06U3	BMW Live Cockpit Professional
01CB	CO2 scope
0322	Comfort access
06AK	Connected Drive Services
06C4	Connected Package Professional
0654	DAB tuner (DAB+ capable)
05AS	Driving Assistant
08EK	Dummy-SALAPA
0459	Electric seat adjustment with memory
04T8	Extended mirror package
0851	German language version
0494	Heated seats for driver and passenger
05AC	High beam assist
0760	High-gloss Shadow Line
06AC	Intelligent emergency call
04ML	Interior trim strips in piano black
0488	Lumbar support for driver and front passenger
0715	M Aerodynamics Package
0710	M leather steering wheel
0337	M Sport Package
0704	M Sport suspension
0548	odometer
08KB	Oil change interval: 24 months/25,000 km
0879	Onboard literature in German
05DM	Parking assistance system
06NW	Phone calls with wireless charging
01CE	recuperation system
08R9	Refrigerant R1234yf
0481	Sports seat

Code	Description
06AE	Teleservices
0465	through-loading system
0420	tinted glazing
02VB	Tire pressure gauge
02VC	Tyre repair kit
0423	Velour floor mats
0428	Warning triangle and first aid kit
02PA	Wheel bolt lock
06WD	Wi-Fi hotspot

Retrofitted equipment

Code	Description
DEBP	PCU48 GEN1 RSU
FRFK	RKF HO Flash

Comments

Dieses Gutachten wurden in Verantwortung von Ing. Martin Lennes, allgemein beeideter und gerichtlich zertifizierter Sachverständiger, erstellt.

Die o.a. Serienausstattung des Fahrzeuges basiert auf Angaben der Firma Eurotax und Macadam Austria übernimmt daher für deren Inhalt keine Haftung.

Die o.a. Sonderausstattung des Fahrzeuges stammt aus dem BMW System Myair und Macadam Austria übernimmt daher für deren Inhalt keine Haftung.

Vehicle details

Manufacturer	BMW	**Inspection condition**	sufficient
Type / Model	520d	**Mileage (Read)**	227,277 km
Vehicle Identification number	WBA31BL060WX00987	**First registration**	6 Nov 2020

Details of the order:
In accordance with the contract, the evaluation of vehicle's condition was performed without the vehicle being disassembled.

This product is based on the Austrian standard ÖNORM V5080. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on their own expertise.

Vehicle identification:
The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.

Inspection conditions:
The inspection conditions were sufficient for the assessment of the vehicle.

General condition:
The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear




Figure 5: Interior



Figure 6: Interior




Figure 7: Interior




Figure 8: Interior



Figure 9: Interior




Figure 10: Interior



Figure 11: Interior



Figure 12: Interior



Figure 13: Interior



Figure 14: Interior




Figure 15: Interior




Figure 16: Misc.




Figure 17: Misc.




Figure 18: Misc.




Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.

Pictures of damage



Damage Front bumper: Front bumper: Front bumper (Ziehrleiste) - Broken / torn - Replace




Damage Front bumper: Front bumper: Front bumper (Ziehrleiste) - Broken / torn - Replace



Damage Wheel / tyres: Wheel / tyres: Alloy rim - front right side - Scratched - Smooth repair work




Damage Wheel / tyres: Wheel / tyres: Alloy rim - front right side - Scratched - Smooth repair work



Damage Wheel / tyres: Wheel / tyres: Tyre - right

(Winter unter 5,5mm) - Does not meet the leasing specifications - Replace



Damage Wheel / tyres: Wheel / tyres: Tyre - right

(Winter unter 5,5mm) - Does not meet the leasing specifications - Replace



Damage Front bumper: Front bumper: Front bumper - Scratch(es) - repair/paint (S3)




Damage Front bumper: Front bumper: Front bumper - Scratch(es) - repair/paint (S3)



Damage Roof: Roof: Roof - Scratch(es) - repair/ paint (S3)




Damage Roof: Roof: Roof - Scratch(es) - repair/ paint (S3)



Damage Roof: Roof: Roof - Scratch(es) - repair/paint (S3)



Damage Bonnet: Bonnet: Bonnet - Scratch(es) - repair/paint (S3)



Damage Bonnet: Bonnet: Bonnet - Scratch(es) - repair/paint (S3)