Audi

VIN: WAUZZZF39N1036030



Description

Registration number 2BDL155	**First registration date** 12/10/2021	**Odometer** 212320 km
Color Bleu Navarre Métallisé	**Model year** 2020	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
Engine displacement 1968	**Gearbox type** Automatic	**Engine type** Combustion
Number of gears 7	**Drivetrain** Front Wheel Drive (FWD)	**Max power** 110 KW

Vehicle Equipments

Alloy wheel rims	Climate control	Towing
Rear sensors	Front sensors	SATNAV
Cruise control		

Statement details

Inspection loc PARC HÖDLMAYR TONGEREN	**Statement date** 21/10/2026	**Inspection approval date** 22/10/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Rear parcel shelf / -	Missing	Replace

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.





002	Personal Data / -	Non Compliant	Carry out




003	Door / Front Left	Scratched	Acceptable





004	Door / Back Left	Scratched	Acceptable

005	Wing / Back Left [1]	Scratched	Acceptable




006	Rear windscreen / - [2] Tinted window : Yes	Scratched	Polishing






007	Bumper / Back [3] Painted : Yes	Scratched	Acceptable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




008	Tailgate / Boot door / -	Scratched	Painting

009	Make badge / -	None	Replace



010	Wing extension moulding / Front Right Painted : Yes	Scratched	Acceptable




011	Roof / - [4]	Scratched	Acceptable



[1] Polissage

[2] Sur réserve pour échanger

[3] Polissage

[4] Polissage

Loose Items

- [x] Conformity certificate
- [x] Registration certificate
- [x] Registration certificate owner
- [x] Remote key
- [x] Compressor tyre repair kit
- [x] Hook /Hicth ball
- [x] Spare Key
- [x] User manual
- [ ] Rear parcel shelf

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Main set of tyres

Front Left	GOODYEAR	235/55/18 Winter	6 mm
Front Right	GOODYEAR	235/55/18 Winter	6 mm
Back Left	GOODYEAR	235/55/18 Winter	6 mm
Back Right	GOODYEAR	235/55/18 Winter	6 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment



Front right



Odometer


Navigation


Spare Tyre



Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




Other



Other



Other



Other



Rear parcel shelf / - / Missing




Personal Data / - / Non Compliant



Personal Data / - / Non Compliant



Door / Front Left / Scratched



Door / Back Left / Scratched



Door / Back Left / Scratched




Wing / Back Left / Scratched




Wing / Back Left / Scratched



Rear windscreen / - / Scratched



Rear windscreen / - / Scratched



Rear windscreen / - / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




Bumper / Back / Scratched



Bumper / Back / Scratched



Tailgate / Boot door / - / Scratched



Tailgate / Boot door / - / Scratched



Make badge / - / None



Wing extension moulding / Front Right / Scratched



Wing extension moulding / Front Right / Scratched



Roof / - / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.