TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48146794
Order No. / Reference: 26979252
Inspection date: 15 Oct 2026

Manufacturer: Volkswagen	Model: Golf Variant 2.0 TDI SCR DSG R-Line
VIN: WVWZZZCD3RW847072	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Golf Variant 2.0 TDI SCR DSG R-Line	
Vehicle Identification number	WVWZZZCD3RW847072
Mileage (Read)	180,326 km
First registration	13 May 2024
Number of holders	1
Next periodical technical inspection	05/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Delfingrau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Grey

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	4,200 km
Last service on / at	06/2026 at 154,432 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HA955848
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CNN 02109		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,060 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R18 92Y	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	225/40 R18 92Y	Summer tyres on Light alloy	Bridgestone	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Hankook	6mm / 6mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Hankook	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	125/70 R18 99M	Summer tyres on Steel	Sonstige	4 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- 30-color ambient lighting
- App-Connect
- Exterior mirror housings and door handles in body color
- third brake light
- Car2X
- Decorative inlays "Carbon Grey"
- Digital Cockpit Pro, multicolor
- Electronic differential lock XDS
- Electronic stability program and electromechanical brake booster
- Driving profile selection
- Electric windows, front and rear
- Pedestrian protection measures expanded
- luggage compartment cover
- Transmission: 7-speed DSG
- Rear window wiper with intermittent function
- Rear headrests (3)
- LED reading lights at the front (2) and 2 at the rear
- LED headlights
- Dynamic headlight range control
- Fatigue detection
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Brushed stainless steel pedals
- Radio "Composition"
- Rear bench seat undivided, backrest asymmetrically split and foldable with center armrest
- Seat belts: Three-point automatic seat belts for the outer rear seats
- Seat covers in "R-Line" fabric
- Seats: Lumbar support in the front
- Lane keeping assistant “Lane Assist”
- 12-volt power outlet in the luggage compartment
- Telephone interface with inductive charging function
- Ambient lighting with logo projection
- Green thermal insulation glazing, sides and rear
- Airbags: Front and rear head airbags, front side airbags, center airbag
- Electrically adjustable and heated exterior mirrors with memory function and passenger-side mirror lowering function.
- black roof rails
- Diesel particulate filter and SCR catalyst
- Parking assistance
- Electronic parking brake including auto-hold function
- Automatic headlight control, with LED daytime running lights
- Chassis: Sport chassis
- Windscreen made of laminated safety glass, heat and sound insulating
- Speed limiter
- Rear window heated
- ISOFIX mounting points
- Front headrests
- LED taillights
- Steering wheel: Multifunction sports steering wheel in leather, with touch controls and paddle shifters
- Non-smoking version
- Emergency call service
- Package: Seat Comfort Package
- Progressive steering
- Tire pressure monitoring system (passive)
- Keyless start system without safe locking
- Seat belts: Three-point automatic seat belt for the middle rear seat
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
- Seats: Top sports seats in the front
- Start-stop system
- Bumpers in body color
- Textile floor mats front and rear
- Electronic immobilizer
- Central locking without safe locking, with remote control and 2 remote folding keys

Extra equipment

- Easy Open & Close - tailgate with sensor-controlled opening and closing, with remote unlocking
- Paint finish: Metallic
- Navigation system "Discover Media" incl. "Streaming & Internet" (6+1 speakers - App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto - Multifunction camera - Navigation system "Discover Media" incl. "Streaming & Internet" - Radio - Traffic sign recognition)
- Package: Design package "Black Style" (Exterior mirror housings in black - Roof rails in black - Illuminated strip between headlights and door handle recesses - With individual installation)
- Package: Technology package including center airbag (anti-theft alarm system with interior monitoring, backup horn and tow-away protection - "Park Assist" parking assistant including parking aid - keyless locking and starting system "Keyless Access", with safe locking - front and rear head and side airbags, center airbag)
- Package: Winter (DSG) (R-Line) (Multifunction sports steering wheel in leather, heated, with touch controls and shift paddles - Automatically heated front windscreen washer nozzles - Heated front seats)
- Wheels: Alloy wheels (4) "Bergamo" 7.5 J x 18 in black with sporty driving dynamics (tires 225/40 R 18 - with individual installation - wheel locks with extended theft protection)
- Wheels: Spare wheel, weight and space saving (on-board tools and jack - instead of Tire Mobility Set)
- Rear side windows and rear window tinted
- Air conditioning "Air Care Climatronic" (with active combination filter, rear controls and 3-zone temperature control)
- Package: Business Premium incl. navigation system (R-Line DSG) (6+1 speakers, App-Connect incl. App-Connect Wireless for Apple CarPlay, Android Auto, automatic distance control, adaptive cruise control (ACC) stop/go, speed limiter, emergency brake, pedestrian detection, travel assist, lane assist, emergency assist, multifunction sports steering wheel with LED and heated steering wheel, paddle shifters, multifunction camera, Discover Media navigation incl. streaming & internet (MP3, touchscreen, USB), cargo net, radio, heated windshield washer system, voice control, telephone interface, comfort with inductive charging, textile floor mats, traffic sign recognition, heated front seats)
- Package: Top Package (2 LED reading lights front, 2 rear, Dynamic High Beam Control, Dynamic Light Assist, Automatically dimming interior mirror, IQ.LIGHT - LED matrix headlights with LED daytime running lights, cornering lights and dynamic turn signals, Air Care Climatronic air conditioning with 3-zone temperature control, allergen filter and rear controls, LED taillights with dynamic turn signals, Dynamic headlight range control with dynamic cornering lights, Multifunction camera, Panoramic tilt/slide sunroof, Rain sensor, Bad weather lights and cornering lights)
- Rear View reversing camera

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Tyre - rear right side - Broken / torn - Replace
2	Front bumper	Spoiler (Rechts) - Scratch(es) - Replace
3	Wheel / tyres	Alloy rim - rear right side - Scratched - Replace
4	Front bumper	Front bumper (Sandstrahlefekt) - Stone chips - Paint
5	Door - front right side	Door - Scratch(es) - Paint
6	Door - rear right side	Door - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	2nd wheel set	Wheel cover set - complete - Missing - No deduction
4	Rear bumper	Rear bumper - Abrasion - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 30 Dec 2025	1.217,33 €
2	Rear, Provided by user / customer, from 22 Dec 2024	5.533,76 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.

Der beiliegende Radsatz gehört nicht zur Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres




Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 1: Wheel / tyres: Tyre - rear right side - Broken / torn - Replace



Damage 1: Wheel / tyres: Tyre - rear right side - Broken / torn - Replace



Damage 2: Front bumper: Spoiler (Rechts) - Scratch(es) - Replace



Damage 2: Front bumper: Spoiler (Rechts) - Scratch(es) - Replace




Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 4: Front bumper: Front bumper (Sandstrahlefekt) - Stone chips - Paint



Damage 4: Front bumper: Front bumper (Sandstrahlefekt) - Stone chips - Paint



Damage 4: Front bumper: Front bumper (Sandstrahlefekt) - Stone chips - Paint



Damage 4: Front bumper: Front bumper (Sandstrahlefekt) - Stone chips - Paint



Damage 4: Front bumper: Front bumper (Sandstrahlefekt) - Stone chips - Paint



Damage 5: Door - front right side: Door - Scratch(es) - Paint



Damage 5: Door - front right side: Door - Scratch(es) - Paint



Damage 6: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 6: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 6: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Wear and tear 3: 2nd wheel set: Wheel cover set - complete - Missing - No deduction